GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6/DFS/MS/2017/EH/W2/641

Dated: 04/05/17

FIRE SAFETY CERTIFICATE

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

Issued on os os at New Delhi by

(Atul Garg) Chief Fire Officer Ph-011-23414250

Copy to:-

- 1. The Dy. Health Officer, North MCD, Civil Line Zone, Sec-5, Rohini, Delhi-110054.
- The Manager, Bikanervala Foods Private Ltd, Shop no 121, 1st Floor, Unity Metro Mall Rohini West Metro Station, Rohini, Delhi -110085.

INSPECTION REPORT

Basement, Ground plus 05 upper floors

1. Name & address of the building: Eating House (M/s Bikanerwala), Shop no 121, FF, Unity

One Mall, MLCP Rohini West Metro Station Delhi.

2. Type of Occupancy : Assembly (Restaurant located at First Floor)

3. Type of Case :New Case

4. Details of previous NOC : Nil

5. Fire Safety directives letter No : NBC Part-4
6. Date of inspection : 25/04/2017
7. Name of the Inspecting Officers : ADO/RN

8. Name and designation of officers

from the building side : Sh Puspender

9. Year of Construction :2014

10. Applicant's letter No. :Nil dated 31.03.2017

	O. Applicant's letter No. Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	1101100	narks /NMR	
	Access to building				
	Road width	09m	10m	MR	
	Gate width	06m	6m	MR	
	Width of internal road	NA	NA	NA	
	Number, Width, Type & Arrangement of	f Exits			
	a. Number of staircases		Service Control of the Control of th		
	Upper Floors	04 common with mall	04 common with mall & 01 Interconnected to Ground to 1 st Floor shop	MR	
	Basements	NA	NA	NA	
	b. Width of staircases		+ #*		
	Upper Floors	1.50m each	1.50m each	MF	
	Basements	NA	NA	NA	
	c. Protection of exits				
	Fire check door	Required	Provided	M	
	Pressurization	NA	NA	N/	
	d. No. of continuous staircases to terrace	01	01	M	
	e. Width of Corridor	NA	NA	NA	
	f. Door Size	02 Exits	2m & 1.50m	M	
3	Compartmentation.				
	Fire check door	Required	Provided	M	
	Sealing of electrical shafts	Required	Provided	M	
	Fire Rating of shaft door	Required	Provided	M	



	Water Curtain	NA	NA		
	Fire Dampers	NA			
4	Smoke Management System.		NA		
	Basements	20 -/-			
	 Upper floors 	30 a/c per hour	Provided		
5	Fire Extinguishers	12 a/c per hour	Natural Ventilated		
	Total numbers	06nos	08nos	1	
	• Types	ABC/Co2	ABC-06 /Co2-02		
6	IS marking	Yes	Yes	N	
6	First-Aid Hose Reels. (Common v	with Mall)	1 es	N	
	 Total numbers on each 	04	0.4		
	floor		04	M	
	 Length of hose reel hose 	30 m	30m		
	Nozzle diameter	5mm		M	
			5mm	M	
	Automatic fire detection and alarming system. (Common with mall)				
	 Type of detectors 	Smoke/ Heat	provided		
	 Location of Main Panel 	GF	Provided	MF	
	 Location of Repeater Panel 	NA	NA	MR	
	 Alternate source of power 	Required		NA	
	 Hooters' Location 	Common area's	Provided	MR	
N	IOEFA		Provided	MR	
P	ublic Address System.	Required	Provided	MR	
		Required	Provided	MR	
-	utomatic Sprinkler System.				
	• Basement	Required	Provided	10	
	 Upper Floor 	Required	Provided	MR MR	
	 Sprinkler above false ceiling 	NA	NA	NA	
Int	ternal Hydrants				
	Size of riser/down-comer	100			
		100mm	100 mm	MR	
	Number of hydrants per floorHose Box	4	4	MR	
	d Hydrants. (with mall)	7	4	MR	
Var				1	

-	Total number of hydrants	06	06	N		
	Hose Box	06	06	N		
13	Pumping Arrangements. (Comm	on with Mall)				
	Ground Level					
	Discharge of main Pump	2850 lpm	2850 lpm			
	Head of Main pump	70m	70m	M		
	Number of main pumps	02	02	M		
	Jockey Pump out put	180 lpm	180lpm	M		
	Jockey pump head	70m	70m	M		
	Standby Pump out put	2850 lpm	2850 lpm	M		
	Standby Pump Head	70m		M		
	Auto Starting/ Manual	Required	70m	M		
	stopping	required	Provided	M		
	Pump House Access	Required	Provided) (1		
	 Terrace level 		Trovided	M		
	Discharge of pump	9001pm	0001			
	Head of the pump	40m	9001pm 40m	M		
	Power Supply	Required		M		
	Auto Starting of pump	Required	provided	MF		
(Required	provided	MF		
+	Captive Water Storage for fire fighting. common with mall					
	Underground tank capacity	1 lack ltrs	1 lack ltrs	MR		
	Draw-off connection	Required	provided	MR		
	Fire service inlet	Required	provided	MR		
	Access to tank	Required	provided			
	Overhead Tank capacity	10,000 ltrs	_	MR		
-		10,000 1113	10,000 ltrs	MR		
E	xit Signage.	Required	provided	MR		
Pı	Provision of Lifts. (Common with Mall)					
•	Pressurization of Lift Shaft	Required	Provided	1.00		
•	Pressurization of Lift lobby	Required		MR		
	Communication In lift Car		Provided	MR		
	Fireman's Grounding	Required	Provided	MR		
	Switch	Required	Provided	MR		
		Required	-			
•	Lift Signage	Required	Provided	MR		
Sta	ndby power supply	Required	Provided	MD		
		_	110 / 100	MR		

18	Refuge Area.				
	> Total Area	NA	NA	NA	
	> Location	NA	NA	NA	
19	Fire Control Room (Common with mall)				
	Detector System Panel	Required	Provided	MR	
	Flow Switch Panel	Required	Provided	MR	
	PA System Panel	Required	Provided	MR	
	Batter backup	Required	Provided	MR	
	Building Floor Plans	Required	Provided	MR	
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA	

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection. Further, the said eating haouse is located at first floor of the building comprised of Basement, ground anf 05 upper floors. The building has already been cleared by this department vide FSC letter of even no 2188 dated 16.12.2015 for a period of 03 year from the date of its issuance.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name: - Rajesh Kumar Designation:- ADO/RN

DycFb (WZ) on leave CFO (WZ) MISIT

As opposed, f.t. letter is

Not RN for your signature 0/ 1/1