GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE NEW DELHI- 110001

NO. F6/DFS/MS/GH/2017/SZ/ 6 0 5

Dated: 28 / 4 /17

FIRE SAFETY CERTIFICATE

Ramphal Chowk, Sector-7, Dwarka, New Delhi-110077 comprised of basement, ground floor (Reception + Commercial use- Bank), 1st floor (Hall), 2nd floor (8 guest rooms), 3rd floor (4 guest rooms + owner's residence) owned/occupied by M/s MSK Residency Guest House was granted NOC by this department vide letter No. F6/MS/DFS/GH/2014/SZ/229 dated 13.2.2014. The said Guest House building was re-inspected by the officer concerned of this department on 18.4.2017 in presence of Sh. Dheeraj Sharma (Proprietor) and found that the Premises have deemed complied with the fire prevention and Fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the building is fit for occupancy class A-1 "Lodging or rooming" (Total -12 Guest Rooms (8 Guest Rooms at 2nd floor, 4 Guest Rooms at 3rd floor) + 1 Hall at 1st floor without basement) with effect from... 26.1.4.1.7. for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.

Issued on28. (.4./լ.)...... at New Delhi by

(Vipin Kental) Chief Fire Officer

Copy to:-

- The Addl. Commissioner of Police (Lic.), 1st Floor Police Station Defence Colony, New Delhi
- The Proprietor, M/s MSK Residency Guest House, C-912, Ramphal Chowk, Sector-7, Dwarka, New Delhi-110075

Jan (15/17)

		INSPECTI	ON REF	ORI		
1	Name & address of the building	M/s MSK Residency Guest House Located at C-912, Ramphal Chowk, Sector-7, Dwarka, New Delhi-110077				
2	Type of Occupancy	Lodging or rooming "A-1"				
3	Type of case	Renewal (Building Comprised of B+G+3 upper Floors)				
4	Details of previous NOC	F6/MS/DFS/GH/2014/229 dated 13.02.2014				
5	Fire safety directives letter No	As per letter	dated 13	.2.2014		
6	Date of inspection	18.4.2017				
7	Name of the inspecting Officers :	ADO Satpal Bhardwaj				
8	Name and designation of officers from the building side	Sh. Dheeraj Sharma (Proprietor)				
9	Year of construction	2007 F	Rooms Details (ground floor- Reception + Commercial use- Bank), 1st floors- (Hall), 2nd floors (8 guest rooms) and 3rd floors (4 guest rooms + owner's residence) Total - 12 guest rooms			
10	Applicant's letter No.	Nil dated 22	.3.2017			
S. NO.	Minimum Standards on fire prevention and fire safety U/R 33	Requiren per Letter 1.4.20	r dated	Prov	rided at site	Remarks MR / NMR
1	Access to building					
	1) Road width	6 Mtrs.		20 Mtrs	N-1	MR
	2) Gate width	N/A		Direct Acce	ssible From Road	N/A
	3) Width of internal road	N/A		N/A		N/A
2 Number, width Type & arrangement of exits			-			
	a. Number of staircases				4	
	1. Upper floors	One		One		MR
	2. basements	Two		Two		MR
	b. Width of staircase					
	1. Upper floors	1 Mtr.		1.12 Mtr.		MR
	2. basements	1 Mtr.		2.4 & 1.10 Mtrs.		MR
	c. Protection of exits					Sales William
	1. Fire check door			Provided N/A		MR.
	Pressurization No. of continuous staircase to	N/A One				N/A MR
	terrace	Offe		One		IVIIC
	e. Width of corridor	N/A		N/A		N/A
	f. Door size	1 Mtr.		1 Mtr.		MR
3	Compartmentation.	74				
	1. Fire check door	Required		Provided		MR
	Sealing of electrical shafts Fire Pating of shaft door.	Required		Provided		MR
	Fire Rating of shaft door water curtain	N/A N/A		N/A N/A		N/A N/A
	5. Fire dampers			N/A		N/A
4	Smoke Management system.			•		
	basement	30 a/c per hour 12 a/c per hour		Exhaust Fans Provided		MR
	upper floors			Natural Ventilation		MR
5	Fire Extinguishers					
	total numbers	10 Nos.				MR
			The special section is	ARC CO2		MR

6	First-Aid Hose Reels.			
	total numbers on each floor	One	One	MR
	Length of Hose reel hose	30 Mtr	30 Mtr	MR
	Nozzle Diameter	5 MM	5 MM	MR
7	Automatic fire detection and alarming	system		
	Type of detectors	N/A	N/A	N/A
	location of Main Panel	N/A	N/A	N/A
-	location of Repeater panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System.	N/A	N/A	N/A
10	Automatic Sprinkler System.			
	basement	Required	Provided	MR
	upper floors	N/A	N/A	N/A
	sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants			
*	Size of riser/down-corner	N/A	100 mm	MR
	Number of Hydrants per floor	N/A	One	MR
	hose Box	N/A	One	MR
12	Yard Hydrants.			Marine Salar
	total number of hydrants	N/A	N/A	N/A
	hose box	N/A	N/A	N/A
13	Pumping arrangements			
	1. Ground level			
* *	a. Discharge of main Pump	N/A	N/A	N/A
	b.Head of main pump	N/A	N/A	N/A
HIV THE	c.Number of main pumps	N/A	N/A	N/A
	d.jockey pump out put	N/A	N/A	N/A
4 8 1	e.jockey pump head	N/A	N/A	N/A
7.5	f. Standby Pump output	N/A	N/A	N/A
	g.Stanby Pump head	N/A	N/A	N/A
	h.Auto Starting/Manual stopping	N/A	N/A	N/A
	pump house access	N/A	N/A	N/A
	2.Terrace level			Barrier V
	a. Discharge of pump	450 LPM	450 & 180 LPM Provided	MR
	b. head of the pump	35 Mtrs.	35 Mtrs.	MR
	c. Power supply	Required	Provided	MR
15 5 4	d. Auto starting of pump	Required	Provided	MR
			No. of the second second	
14	Captive water storage for fire fighting		The state of the s	laura.
TENTE F	Underground tank capacity	N/A	N/A	N/A
	a. Draw-off connection	N/A	N/A	N/A
	b. fire service inlet	N/A	N/A	N/A
1-5	c.Access to tank	N/A	N/A	N/A
	Over head tank Capacity	5000 Ltrs	5000 Ltrs	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of lifts.		lau/a	INVA
131	a. Pressurization of lift shaft	N/A	N/A	N/A
	b. pressurization of lift lobby	N/A	N/A	N/A
	c. communication in lift car	Required	Provided	MR
	d. Fireman's grounding switch	Required	Provided	MR .
	e. Lift signage	N/A	N/A	N/A
17	Standby power supply	Required	Provided	MR
18	Refuge Area.		Not Required	
	total area			
	location	1		FACT.
		The same of the sa		

7	19	Fire	control room						
			tector system Panel	N/A	N/A	N/A			
			w switch Panel	N/A	N/A	N/A			
	0		system Panel	N/A	N/A	N/A			
	26		tter backup	N/A	N/A	N/A			
			ilding floor plans	N/A	N/A	N/A			
	20 Special Fire Protection systems for protection of special risks, if any:								
	Marin Ind								
		otection systems provided in the building were checked and found functional at the time of inspection.							
	Keeping in	view	deemed compliance of the minimum standards on fire prevention and fire safety requirements under the						
	rules. Fire	Safet	v Certificate issued vide letter no. F6/	MS/DFS/GH/2014/SZ/	229 dated 13.2.2014 is recor	nmended for			
	renewal ur	nder F	ule 37 of the Delhi Fire Service Act 2						
			Accordingly DFA is put up for approval and signature please.						
Signature of the Inspecting Officer									
			Signature of the hispecting officer						
				Name	Satpal Bhard	Satpal Bhardwaj			
			Designati	A.D.O. (Dwa	A.D.O. (Dwarka)				
			The second second second						
		1							
	DU	SW							
	-								
	, /		- holy 113						
61	67/D6CSW)								
1	2 - 10/1/7								
χ.	20 01 1	1							
			DCF (CZ)						
			32)						
	1-00		Nan						
718	JCh 82		Kan						
18	JCh 82	281	Karl						

CPO(2) M. \$cell lk 24/4.

Cho152/ Miscell le 29/4

ET lette is put up for signatur plush.