GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/School/2017/ 645

Dated: 04 05 17

FIRE SAFETY CERTIFICATE

Certified that the Flora Public School located at 10/1, Ram Mohalla, Gali No.-1, Johripur, Delhi-110094, comprised of ground plus one upper floor only owned/occupied by Flora Public School have complied with the fire prevention and fire safety requirements in accordance with the circular No-F-16/Estate/CC/Fire Safety/2011/3298 to 3398 dated-01/03/11 issued by the Director of Education and verified by the officer concerned of this department on 25/04/2017 in the presence of Mrs. Laxmi, Principal of the school and found that the school building is fit for occupancy class B' Educational Building' with effect from oh. oh. of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, subject to conditions printed overleaf.

(Vipin Kental) Chief Fire Officer

To.

The Manager, Flora Public School 10/1, Ram Mohalla, Gali No.-1, Johripur, Delhi-110094

Copy:-

The Dy. Director of Education, B-Block, Yamuna Vihar, North-East, Delhi-110053

CONDITIONS:

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

1. Name & address of the building : Flora Public School,

10/1, Ram Mohalla, Gali No.-1,

Johripur, Delhi-110094

2. Building is comprised of

: Ground plus first floor only

3. Type of Occupancy

: Educational

4. Type of Case

: New

: Nil

5. Details of Previous NOC letter

1 40 44

6. Fire Safety direction letter No

: F16/Estate/CC/FireSafety/2011/3298to3398 dt-01/03/11

7. Date of Inspection

: 25/04/17

8. Name of the Inspecting officers

: ADO Vijay Bahadur

9. Name and designation of Officer

from the building side

: Mrs. Laxmi (Principal)

10. Year of Construction

: 2008

11. Applicant's letter No

: Letter No.-Nil, Dated-27/03/17

Sr.	Minimum Standards on Fire	Circular	Provided at Site	Remarks			
No.	Prevention and Fire Safety U/R33	Requirement		MR/NMR			
01	Access to Building						
	Road width	06 mtr.	06 mtr.	MR			
	Gate width	N/A	NA	N/A			
	Width of internal road	N/A	N/A	N/A			
02	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases		<u> </u>				
The state of the s	Upper floor	01 no.	02 no.	MR			
	Basement	N/A	NA	N/A			
A designation of the second of	b. Width of Staircases						
	Upper floor	1.50 mtr.	1.32 mtr & 0.75 mtr	MR			
- Andrews	• Basement	N/A	N/A	N/A			
	c. Protection of Exits		en e	de la companya de la			
	Fire check door	N/A	N/A	N/A			
	 Pressurization 	N/A	N/A	N/A			
	d. No. of Continuous Staircases to Terrace	N/A	N/A	N/A			
	e. Width of Corridor	1.50 mtr.	1.82 mtr.	MR			
	f. Door Size	01 mtr.	01 mtr.	MR			
03	3 Compartmentation.						
	Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	N/A	N/A			
	 Fire rating of shaft door 	N/A	N/A -	N/A			
	Water curtain	N/A	N/A	N/A			
	• Fire dampers	N/A	», N/A	N/A			
04	Smoke Management System.						
	Basement	N/A	N/A	N/A			
	Upper floor	N/A	N/A	N/A			
05.	Fire Extinguishers						
	Total numbers	04 nos.	04 nos.	MR			
	• types	ABC/CO ₂	Provided	MR			
	 IS marking 	ISI marked	Provided	MR			

			and the state of t	
06	First-Aid-Hose Reels.			
	Total numbers on each floor	N/A	N/A	N/A
	Length of hose reel hose	N/A	N/A	N/A
	Nozzle diameter	N/A	N/A	N/A
07	Automatic Fire Detection and Alarming Sys			
		N/A	N/A	N/A
	Type of detectors	N/A	N/A	N/A
	Location of main panel	N/A	N/A	N/A
and the second	 Location of repeater panel Alternate source of power 		N/A	N/A
an a	Alternate source of power Hooter's location	N/A N/A	N/A	N/A
00		N/A	N/A	N/A
08	MOEFA			
09	Public Address System.	N/A	N/A	N/A
10	Automatic Sprinkler System.			T v
	Basement	N/A	N/A	N/A
	• upper floor	N/A	N/A	N/A
	sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants			Distance comments of the
	size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12	Yard Hydrants.			
	Total number of hydrants	N/A	N/A.	N/A
7 77	Hose box	N/A	N/A	N/A
13	Pumping Arrangements.			
	➤ Ground Level		у	
		5.17A	N1/A	N/A
	Discharge of main pump	N/A	N/A N/A	N/A
	Head of main pump	N/A N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey pump out put	N/A	N/A	N/A
	Jockey pump head Standby pump out but	N/A	N/A	N/A
	Standby pump out putStandby pump head	N/A	N/A	N/A
	Auto starting/manual stopping	N/A	N/A	N/A
	Pump house access	N/A	N/A	N/A
	> Terrace Level			
	Discharge of pump	N/A	N/A	N/A
	Head of the pump	N/A	N/A	N/A
	Power supply	N/A	N/A	N/A
	Auto starting of pump.	N/A	N/A	N/A
14	Captive Water Storage for Fire Fighting.		A CONTRACTOR OF THE PARTY OF TH	A Marine and American and Ameri
-	Underground tank capacity	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead tank capacity	N/A	N/A	N/A
15	Exit Signage.	N/A	N/A	N/A

16	Provision of Lifts.					
	Pressurization of lift shaft	N/A	N/A	N/A		
	Pressurization of lift lobby	N/A	N/A	N/A		
	Communication in lift car	N/A	N/A	N/A		
	Firemen's grounding switch	N/A	N/A	N/A		
	Lift signage	N/A	N/A	N/A		
17	Standby power supply	N/A	N/A \	N/A		
18	Refuge Area.					
	Total area .	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector system panel	N/A	N/A	N/A		
	Flow switch panel	N/A	N/A	N/A		
	PA system panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building floor plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of Special Risks, if Any:	N/A	N/A	N/A		

The shortcomings communicated earlier vide letter No. F-6/DFS/MS/School/2016/1527 dated 14/06/16 have been rectified now. The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the circular no. F16/Estate/CC/Fire Safety/2011/3298to3398 dated 01/03/11 issued by Director of Education, it is recommended to issue Fire Safety Certificate.

Signature of the Inspecting Officer

:- V. B. Yadav

Designation :- A.D.O (T.Pur)

M:SCELL VEJS

As approved FT FSC 1/2 but up for segnative please.

cfo(NDZ) miscell 14/5