GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2017/ 692

Dated: 15/5/17

FIRE SAFETY CERTIFICATE

Issued ______ at New Delhi by.

(VIPEN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- 1. The Manager, M/s. Walnut Castle Guest House, 18/10, Pusa Lane, Karol Bagh, New Delhi-110005.
- 2. The Joint C.P.(Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

Following Fire Safety Directives must be adhered to: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building

: M/s Walnut Castle guest house, 18/10, Pusa Lane, Karol

Bagh, New Delhi- 110005.

2. Type of Occupancy

: Lodging House

3. Type of Case

: Renewal

4. Details of previous NOC

: F6/DFS/MS/GH/2013/SZ/935 dated 20.09.2013

5. Fire Safety directives letter No

: Nil

6. Date of inspection

: 28.04.2017

7. Name of the Inspecting Officers

: M.K. Chattopadhyay, DO(South West)

8. Name and designation of officers

from the building side

: Mr. Madan Singh, manager

9. Year of Construction

: 2009-10

10. Applicant's letter No.

: nil dated 17.03.2017

The said guest house is comprised of basement (hall), stilt (parking), ground floor (reception + 03 guest room), first floor (06 guest room), second floor (06 guest rooms) and third floor (06 guest rooms)

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Existing fire safety requirements as per letter dated 20.09.2013	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	06 mts	Provided (09 mts)	MR		
	Gate width	05 mts	Directly accessible	MR		
	Width of internal road	N/A	N/A	N/A		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases	-		_		
	• Upper Floors	01	01	MR being old case		
	Basements	01	01	MR being old case		
	b. Width of staircases	-	-			
	• Upper Floors	1.25 mts	Provided	MR		
	Basements	1.25 mts	Provided	MR		
	c. Protection of exits	_	-	-		
	Fire check door	N/A	· N/A	N/A		
	• Pressurization	N/A	N/A	N/A		
	e. No. of continuous staircases to terrace	01	01	MR		
	g. Width of Corridor	1.25 mts	1.40 mts	MR		
	h. Door Size	Old case	0.87 mts	MR being old case		
	Compartmentation.					
	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain Fire Dampers	N/A	N/A	N/A		

4	Smoke Management System.					
	Basements	12 a/c per hour	Exhaust fan	MR		
* W.	Upper floors	12 a/c per hour	Natural Ventilation	MR		
5	Fire Extinguishers					
	Total numbers	02 at each floor	Provided	MR		
	• Types	CO ₂ , ABC	Provided	MR		
	IS marking	ISI marked	Provided	MR		
6	First-Aid Hose Reels.					
	 Total numbers on each floor 	01	Provided	MR		
	 Length of hose reel hose 	30 m	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
7	Automatic fire detection and alarming system.					
	Type of detectors	N/A	N/A	N/A		
	 Location of Main Panel 	N/A	N/A	N/A		
	 Location of Repeater Panel 	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
8	MOEFA	Required	Provided	N/A N/A Dvided MR Dvided MR		
9	Public Address System.	Required	Provided	MR		
10	Automatic Sprinkler System.					
	Basement	Required	Provided	MR		
	Upper Floor	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants					
	Size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12	Yard Hydrants.	12 a/c per hour Exhaust fan provided MR Natural Ventilation MR				
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements.	100				
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	➤ Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Ct 11 D	27/4	27/4	NI/A		

	> Stand	by Pump Head	N/A	N/A	N/A			
	 Auto Starting/ Manual stopping Pump House Access Terrace level 		N/A	N/A	N/A			
			N/A	N/A	N/A			
		narge of pump	450 LPM each	588 LPM, 450 LPM	MR			
		of the pump	30 mts rach	Provided	MR			
		or Supply Starting of pump	Required	Provided	MR			
	Auto	or pump						
14	Captive Water Storage for fire fighting.							
	Undergro	und tank capacity	N/A	N/A	N/A			
	Draw-off connectionFire service inlet		N/A	N/A	N/A			
			N/A	N/A	N/A			
		> Access to tank		N/A	N/A			
	Overhead	Tank capacity	10000 lts	10,000 lts	MR			
15	Exit Signage.		Required	Provided	MR			
16	Provision of Lifts.							
	Pressuriza	ation of Lift Shaft	N/A	N/A	N/A			
	Pressuriza	ation of Lift lobby	N/A	N/A	N/A			
	• Commun	ication In lift Car		Provided	MR			
	• Fireman's	s Grounding Switch	Required	Provided	MR			
	Lift Signa	age	Required	Provided	MR			
17	Standby power	supply	Required	Provided (125 KVA)	MR			
18	Refuge Area.							
	> Total Are	a	N/A	N/A	N/A			
	> Location		N/A	N/A	N/A			
19	Fire Control Ro	om		•				
	• Detecto	r System Panel	N/A	N/A	N/A			
	• Flow Sv	vitch Panel	N/A	N/A	N/A			
	• PA Syst	em Panel	Required	Provided	MR			
	Batter b	ackup	N/A	N/A	N/A			
	Building	g Floor Plans	N/A	N/A	N/A			
20	Special Fire Prot	ection Systems for cial Risks, if any:	Required	Two ABC type fire extinguisher found provided near elect. panel	MR			

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/GH/2013/SZ/935 dated 20.09.2013, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended. DFA is put up for approval & signature please. Signature of the Inspecting Officer Name M.K.CHATTOPADHYAY Div. Officer (South West) miscell F. T. letter is