## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2017/SZ

1842

Dated: 09/06/17

## FIRE SAFETY CERTIFICATE

Certified that the **Garima Public School**, Near Holi Chowk, Village Ghumanhera, New Delhi-110073 comprised of ground plus one upper floor in a three storied building, owned/occupied by Garima Public School was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2014/SZ/869 dated 16.7.2014. The school building was re- inspected by the officer concerned of this department on 25.05.2017 in the presence of Sh. Shrawan Kumar (TGT) and found that the Garima Public School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises (Ground plus one upper floor) is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on. o 9 / o 6 / 17 at New Delhi.

(VIPIN KENTAL) CHIEF FIRE OFFICER

## Copy to:-

- The Manager, Garima Public School, Near Holi Chowk, Village Ghumanhera New Delhi-110073
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

Garima Public School, Near Holi Chowk, Village Ghumanhera, New Name & address of the building Delhi-110073 Educational Type of Occupancy 2. Renewal 3. Type of Case F.6/DFS/MS/School/2014/SZ/869 dated 16.7.2014 4. Details of Previous NOC Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 5. Fire Safety directives letter No 25.05.2017 6. Date of inspection A.D.O. Sandeep Duggal 7. Name of Inspecting Officer 8. Name and designation of officers From the building side Sh. Sunil Kumar (Manager) 2004-2005 9. Year of Construction GPS/2017-18/05 dated 28.04.2017 10. Applicant's letter No. Remarks Requirement Provided at Minimum Standards on fire prevention and S. No. MR/NMR as per FSC dt. site fire safety U/R 33 16.7.2014 Access to building 1. MR, being old case Accessible 4.5 mtrs Road width 4.5 mtrs M/R Directly accessible Gate width from road N/A N/A Width of internal road N/A Number, Width, Type & Arrangement of Exits 2. a. Number of staircases MR 02 no.'s Upper Floors 01 no. N/A Basements N/A N/A b. Width of staircases Upper Floor MR 150 cms/additional 150 & 135 Basements staircase of 75 cms cms if less than 150 cms N/A N/A N/A c. Protection of exits Fire check door N/A N/A N/A Pressurization N/A N/A N/A d. No. of continuous staircases to N/A N/A One terrace MR 150 cms 155 cms Width of Corridor MR, being old case & f. Door Size 90 cms 100 cms students are less than (double door) 45 in each class Compartmentation 3. N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A **Smoke Management System** 4. N/A N/A N/A. Basements Natural Ventilation MR Required Upper floors provided Fire Extinguishers 5. Provided MR 07 No's Total numbers ABC/CO<sub>2</sub> type Provided MR Types ISI marked MR IS marking ISI marked First-Aid Hose Reels 6. N/A N/A N/A Total numbers on each floor N/A N/A N/A Length of hose reel hose N/A NT/A N/A

INSPECTION REPORT

7.	Automatic fire detection and alarming system	27/4	DI/A	N/A
	Type of detectors	N/A	N/A	
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel  Alternate source of power.	N/A	N/A	N/A
	<ul><li>Alternate source of power</li><li>Hooters' Location</li></ul>	N/A	N/A	N/A
		N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System			
	Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
171	<ul> <li>Sprinkler above false ceiling</li> </ul>	N/A	N/A	N/A
11.	Internal Hydrants	27/4	NT/A	N/A
	Size of riser/down-comer	N/A	N/A N/A	N/A N/A
	Number of hydrants per floor	N/A N/A	N/A N/A	N/A
	Hose Box	IN/A	IN/A	IVA
12.	Yard Hydrants	N/A	N/A	N/A
	Total number of hydrants	N/A N/A	N/A N/A	N/A
	Hose Box	IN/A	IVA	14/21
13.	Pumping Arrangements			
	Ground Level     Discharge of main Pump	N/A	N/A	N/A
	<ul><li>Discharge of main Pump</li><li>Head of Main pump</li></ul>			N/A
	Number of main pumps	N/A	N/A	
	> Jockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	- N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
- W	> Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	Pump House Access			
	Terrace level	N/A	N/A	N/A
	Discharge of pump	N/A N/A	N/A	N/A
	<ul><li>Head of the pump</li><li>Power Supply</li></ul>	N/A N/A	N/A	N/A
	> Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting			27/4
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
L	> Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
15.	Exit Signage.	N/A	N/A	N/A
16.	Provision of Lifts.			(No Lift)
	The state of the s	N/A	N/A	N/A
	CT'C111	N/A	N/A	N/A
	Pressurization of Lift lobby     Communication In lift Car	N/A N/A	N/A N/A	N/A
	Fireman's Grounding Switch			N/A
	Lift Signage	N/A	N/A	
	Zitt ölgilage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.			
	> Total Area	N/A	N/A	N/A

9.	Fire Control Room	N/A	N/A·	N/A
	Detector System Panel     Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2014/SZ/869 dated 16.7.2014 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer Name: - Sandeep Duggal Designation: - Asstt. Divisional Officer

1/00000)

Divisional Officer (South West)

CFO FM m scell FT to,

1/6.

FT. letter is put up for signature please sandage

CFO CSP M SCELL W 7/6/17.