GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/2017/ MD2/751

Dated :- 25/-5/17

FIRE SAFETY CERTIFICATE

Certified that the Pahwa International Guest House located at 10402/3, Gali No. 13, Furniture Block, Multani Dhanda, Pahar Ganj, New Delhi comprised of Ground + 03 Upper floors, Ground floor (02 guest rooms + Reception + Office), 1st floor (04 guest rooms), 2nd floor to 3rd floor (05 guest rooms at each floor) and terrace floor (01 store rooms + open terrace), total 16 guest rooms was granted FSC by this department vide letter No.F6/DFS/MS/GH/2014/NDZ/639 dated 27/05/14. The premises was re-inspected by the officer concerned of this department on 11/05/17 in the presence of Mr. Kishore Pahwa and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 as above 16 guest rooms only with effect from --25-15-17-for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued -----at New Delhi by.

(Vipin Kental) Chief Fire Officer Delhi Fire Service

Copy to:-

- de me 1. The Joint Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi ref. letter no. 609/Joint C.P./ Lic.(H) dated 06/03/17.
- 2. The Manager, Pahwa International Guest House at 10402/3, Gali No. 13, Furniture Block, Multani Dhanda, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

Pahwa International Guest House located at 1. Name & address of the building

10402/3, Gali No. 13, Furniture Block, Multani Dhanda, Pahar Ganj, New Delhi

Residential, Sub Division-A-1 2. Type of occupancy:-

Gr. + 03 Upper floors (total 16 Guest rooms) Ground floor (02 guest rooms + Reception + Office), 1st floor (04 guest rooms), 2nd floor to 3rd floor (05 guest rooms at each floor) and terrace floor (01 store

rooms + open terrace).

Mr. Kishore Pahwa

3. Type of case:-

4. Details of previous FSC:-

Renewal No. F6/DFS/MS/GH/2014/NDZ/639 dated

27/05/14.

5. Fire safety directives No.-

6. Date of inspection:-

N/A 11/05/17

7. Name of the inspecting officer:-

8. Name & designation of officer

Sh. Manoj Kumar Sharma (ADO/CC)

From the building side:-

9. Year of construction:-

2011

10. Applicant's letter No:-

609/Joint C.P./ Lic.(H) dated 06/03/17.

				Old Case		
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR		
1.	Access to Building					
	1) Road width	N/A	09 mtr.	N/A		
	2) Gate width	N/A	N/A	N/A		
	3) Width of internal road	N/A	N/A	N/A		
2.	Number, Width Type & Arr	angement of E	Exits			
	A. Number of staircases					
	1. Upper floors	01 Nos.	01 Nos.	MR		
	2. Basements	N/A	N/A	N/A		
	B. Width of staircase					
	1. Upper floors	0.80 mtr.	1.20 mtr.	MR		
	2. Basements	N/A	N/A	N/A		
	C. Protection of exits					
	1. Fire check door	N/A	N/A	N/A		
	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous	01	01	MR		
	staircase to terrace					
	E. Width of corridor	01 mtr.	01 mtr.	01 mtr.		
3 1	F. Door size	01 mtr.	01 mtr.	01 mtr.		
3.	Compartmentation					
	1) Fire check door	N/A	N/A	N/A		
	2) Sealing of electrical shafts	N/A	N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System					
	1) Basements	30 ACPH	N/A	N/A		
	2) Upper floors	12 ACPH	Natural	MR		

5.	Fire Extinguishers							
	1) Total numbers	12	2 Nos.	12 Nos.	MR			
			BC & CO2	ABC & CO2	MR			
	3) ISI marking	Re	equired	Provided	MR			
6.	First-Aid Hose Reel							
				01	MR			
	2) Length of hose reel hose		mtr.	30 mtr.	MR			
	3) Nozzle diameter		mm	05 mm	MR			
7.	Automatic Fire Detection & Alarming System							
- /			/A	N/A	N/A			
			/A	N/A	N/A			
			/A	N/A	N/A			
	4) Alternate source of power		/A	N/A	N/A			
	5) Hooter's Location		/A	N/A	N/A			
8.	MOEFA	R	equired	Provided	MR			
9.	Public Address System		/A	N/A	N/A			
10.	Automatic Sprinkler Syste							
2000			/A	N/A	N/A			
	2) Upper floors		/A	N/A	N/A			
	3) Sprinkler above false		/A	N/A	N/A			
	ceiling							
11.	Internal Hydrants							
	1) Size of riser/down-comer 1		00 mm	100 mm	MR			
				01	MR			
	floor							
	3) Hose box		1	01	MR			
12.	Yard Hydrants							
	1) Total number of hydrants		/A	N/A	N/A			
	2) Hose box	N	/A	N/A	N/A			
13.	Pumping Arrangement	11.1	8 1					
	1) Ground level		N/A	N/A	N/A			
	a) Discharge of main		N/A	N/A	N/A			
	pump							
	b) Head of main pum	p	N/A	N/A	N/A			
	c) Number of main p	ump	N/A	N/A	N/A			
	d) Jockey pump out p	out	N/A	N/A	N/A			
	e) Jockey pump head		N/A N/A	N/A	N/A			
		f) Stand by pump output		N/A	N/A			
	g) Stand by pump he			N/A	N/A			
	,			N/A	N/A			
	stopping							
	2) Terrace level							
	a) Discharge of pump		450 LPM	450 LPM	MR			
	b) Head of pump		30 mtr.	30 mtr. 🦠	MR			
	c) Power supply		Required	Provided	MR			
			Required	Provided	MR			

14.	Captive Water Storage for I	Fire Fighting		
17.	1) Under ground tank capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A N/A	N/A N/A
	b) Fire service inlet	N/A	N/A	N/A N/A
	c) Access to tank	Required	Provided	MR
*	d) Over head tank capacity	10,000 ltr.	10,000 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syste Risk, if any: ABC & CO ²	m for Protect	ion of special	MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2014/NDZ/639 dated 27/05/2014 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

24/1/12/5

Signature of the Inspecting Officer

Name: - M.K. Sharma Designation: - ADO (CC)

Dycho(NDE)

Th 16/3

F760.

miscell 1