GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2017/SZ

1839

Dated: 09/06/17

FIRE SAFETY CERTIFICATE

Certified that the **S.D.M.C Primary School (C0-ed)**, Dariya Pur Khurd, New Delhi-110073 comprised of ground plus one upper floor, having total 09 rooms (Including Class Rooms, Office, Hall, Comp. Room & Store etc.) owned/occupied by S.D.M.C was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2013/850 dated 28.02.2013. The school building was re- inspected by the officer concerned of this department on 25.05.2017 in the presence of Sh. Shishu Pal Singh (In-charge) and found that the S.D.M.C Primary School (C0-ed) have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

- The Principal,
 S.D.M.C Primary School (C0-ed),
 Dariya Pur Khurd, New Delhi-110073
- Director of Education,
 S.D.M.C, Civic Centre,
 Minto Road, New Delhi-110001.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

Comprised of ground plus one upper floor. INSPECTION REPORT Name & address of the building : S.D.M.C Primary School (C0-ed), Dariya Pur Khurd, New Delhi-110073 2. Type of Occupancy Educational Renewal Type of Case 3. F.6/DFS/MS/School/2013/850 dated 28.02.2013 4. Details of Previous NOC Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 5. Fire Safety directives letter No 25.05.2017 Date of inspection Name of Inspecting Officer A.D.O. Sandeep Duggal 7. 8. Name and designation of officers Sh. Shishu Pal Singh (In-charge) From the building side 9. Year of Construction 2007 Nil dated 02.03.2017 10. Applicant's letter No. Provided at Remarks Requirement Minimum Standards on fire prevention and S. No. MR/NMR as per FSC dt. site fire safety U/R 33 28.02.2013 Access to building 1. Accessible 06 mtrs 09 mtrs MR Road width 4.5 mtrs Directly accessible M/R Gate width from road N/A N/A Width of internal road N/A Number, Width, Type & Arrangement of Exits 2. a. Number of staircases Upper Floors 01 no. 01 no. MR Basements N/A N/A N/A b. Width of staircases Upper Floor 150 cms MR 150 cms Basements N/A N/A N/A c. Protection of exits N/A N/A N/A Fire check door N/A N/A N/A Pressurization N/A N/A. N/A d. No. of continuous staircases to MR 220 cms 150 cms terrace MR e. Width of Corridor 100 cms 118 cms (double door) f. Door Size Compartmentation 3. N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System 4. N/A N/A N/A Basements Natural Ventilation MR Required Upper floors provided Fire Extinguishers 5. MR Provided 05 No's Total numbers ABC/CO₂ type Provided MR Types ISI marked IS marking MR ISI marked **First-Aid Hose Reels** 6. N/A N/A N/A Total numbers on each floor NI/A N/A

NIA

	Electric de la constitución de l			
.7.	Automatic fire detection and alarming system	garage -		
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
· .	Location of Repeater Panel Alternate source of power	N/A	N/A	N/A
	Alternate source of powerHooters' Location	N/A	N/A	N/A
		N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	Basement	N/A	N/A	N/A
- , -,	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	Size of riser/down-comer	N/A	N/A	N/A
	 Number of hydrants per floor 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants		77/3	27/1
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	Ground Level		27/1	27/4
	Discharge of main PumpHead of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A.	N/A
	> Pump House Access	1772		
	Terrace level	N/A	N/A	N/A
	Discharge of pumpHead of the pump	N/A N/A	N/A N/A	N/A
	> Power Supply	N/A N/A	N/A N/A	N/A
	> Auto Starting of pump	N/A	N/A	N/A
		1074	17/11	1,171
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
15.	Exit Signage.	N/A	N/A	N/A
16.	Provision of Lifts.			(No Lift)
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch			
	• Lift Signage	N/A	N/A	N/A
		N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.			10. 10
*				

19.	Fire (Control Room			N/A
	•	Detector System Panel	N/A	N/A	
		Flow Switch Panel	N/A	N/A	N/A
		PA System Panel	N/A	N/A	N/A
	•	Battery backup	N/A	N/A	N/A
	. •	Building Floor Plans	N/A	N/A	N/A
					* -
20.		al Fire Protection System for Protection of al Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2013/850 dated 28.02.2013 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer Name - Sandeep Duggal

Designation: - Asstt. Divisional Officer

Divisional Officer (South West)

F.T. letter is protup for segnature please.

Scande Sande M. SCOU M. SCOUNTE/1?