## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001 Fax No. 011-23412593, Ph. 011-23412225

No. F6/DFS/MS/EH/2017/SZ/9 (o

Dated: 23.06.17

## FIRE SAFETY CERTIFICATE

Certified that the M/s Pizza Express restaurant located at T-303 B, Third floor, Ambience Mall, Vasant Kunj, running at third floor of the building, comprised of three tier basement, ground + three upper floors was granted FSC by this department vide letter No. F.6/DFS/MS/EH/2014/SZ/942 dated 30.07.2014. The premises was re-inspected by the officer concerned of this department on 10/06/2017 in the presence of Mr. Sumit (Manager) of the eating house and observed that the said premises have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class-D "Assembly Building" (Eating House) as above with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 23.06.17 at New Delhi by

(Vipin Kental) Chief Fire Officer

Copy to: -

1. M/S Pizza Express restaurant (A Unit of Gourmet Investments Pvt Ltd), T-303B, Third floor, Ambience Mall, Vasant Kunj, New Delhi-110070

2. The Joint C.P. (Lic.), First Floor, PS Defence Colony, New Delhi-110049

## Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- 2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
- 4. The basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
- 6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

| 9     |  | INSPECTIO  | N DEPO   | DT   |                             |                   |
|-------|--|--|--|--|-----------------------------|-------------------|
| 1     | Ma                                       |  |  |  | acc Pactourant T-303        | R Third           |
| 1     | Na                                       | me & Address of the Building   | M/s Pizza Express Restaurant, T-303 B, Third                 |  |                             |                   |
|       |  |  | floor, Ambience Mall, Vasant Kunj, ND-70                     |  |                             |                   |
|       |  |  | (A Unit of Gourmet Investment Pvt. Ltd.)                     |  |                             |                   |
| 2     | -  | pe of Occupancy  |  |  | ng "Group-D" Restaurar      |                   |
| 3     |  | ilding Comprised of  | Three tier Basement, Ground + 03 upper floors                |  |                             |                   |
| 4     |  | pe of Case   | Renewal  |  |                             |                   |
| 5     | -  | tails of Previous NOC  |  | MS/EH  | /2014/SZ/942 Dated 30-      | 07-2014           |
| 6     | Fir                                      | e Safety Directives Letter No  | Nil  |  |                             |                   |
| 7     |  | te of Inspection   | 10-06-2017   |  |                             |                   |
| 8     | Na                                       | me of the Inspecting Officers  | ADO R.N. Singh   |  |                             | 198               |
| 9     |  | me & Designation of Officers   | Mr. Sumit (Manager)  |  |                             |                   |
|       |  | m the building side  |  |  |                             |                   |
| 10    | Ye                                       | ar of construction   | 2006-07 Restt running at 3 <sup>rd</sup> floor in Ambience M |  | nbience Mal                 |                   |
|       | -  | Control of the Contro | building.  |  |                             | - 0017            |
| . 11  |  | plicant letter No.   |  |  | DD no. 6825 Dated 22-05     |                   |
| S. No | Minimum standards on Fire Prevention and |  | Old N  |  | Provided at Site            | Remarks<br>MR/NMR |
|       |  | e Safety U/R 33  | requirer   | nents  | Mall/SZ/2017/33 dated (     |                   |
| 1     | Ac                                       | cess to Building.  |  |  | As above                    | MR                |
| -     | - 1                                      | Road width   | Restau   |  | As above<br>As above        | N/A               |
|       |  | Gate width   | within   | Mall   |                             |                   |
|       |  | Width of internal road   |  |  | As above                    | N/A               |
| 2     | Nu                                       | mber, width, type & arrangement of exits.  |  | 1/   |                             |                   |
|       | a.                                       | Number of Staircase  | -  |  | Maintained by Ambier        |                   |
|       |  | Upper floors   | 2 No's   |  | As above                    | MR                |
|       | 340                                      | Basement floor   | N/A  |  | As above                    | N/A               |
|       | b.                                       | Width of Staircase   | Prov   | ided &   | Maintained by Ambier        |                   |
|       |  | Upper floors   | Requi  | red  | As above                    | MR                |
| ,     | -  | Basement floor   | N/A  |  | As above                    | N/A               |
|       | c.                                       | Protection of exits  | Provided &   |  | Maintained by Ambience Mall |                   |
|       | 7  | Fire check door  | Required   |  | As above                    | MR                |
|       |  | Pressurization   | N/A  | A  | As above                    | N/A               |
|       | d.                                       | No. of continuous staircase to terrace   | Requi  | red  | As above                    | MR                |
|       | e.                                       | Width of corridor  | N/A  |  | N/A                         | N/A               |
|       | f.                                       | Door size  | 2.0 n  |  | 2.0 mtr & 1.22 mtr          | MR                |
| 3     |  | mpartmentation.  |  |  | Maintained by Ambier        |                   |
|       | -  | Fire check door.   | N/A  |  | As above                    | N/A               |
|       |  | <ul> <li>Sealing of electrical shafts.</li> </ul>  | N/A  |  | As above                    | N/A               |
|       |  | • Fire rating of shaft door.   | N/A  |  | N/A                         | N/A               |
|       |  | Water curtain  | N/A  |  | N/A                         | N/A               |
|       |  |  | N/A  | the state of the s | N/A                         | N/A               |
| 4     | 0.                                       | • Fire dampers.  |  |  | Maintained by Ambier        |                   |
| 4.    | on                                       | oke Management system.   | N/A  |  | As above                    | N/A               |
| 2 2   |  | Basement   | Requi  |  | Exhaust fans provided       | MR                |
|       | -  | • Upper floors   | Requi  | ireu   | Exhaust fans provided       | IVIIC             |
| 5.    | Fin                                      | re Extinguishers.  |  |  | 07 Na?a                     | MR                |
| 3.    | ļ  | Total numbers  | ICI  | ulrad  | 07 No's                     | -                 |
| 5.    |  | • Types  | ISI ma   | rked   | ABC-04, W.Co2-03            | MR<br>MR          |
| 5.    |  |  |  |  |                             | 1 1 /1 12         |
| 3.    |  | ISI Marking  |  |  | Provided                    | 1                 |
| 6.    | Fin                                      | ISI Marking     st Aid Hose Reels.   |  |  | Maintained by Ambier        | nce Mall          |
|       | Fin                                      | ISI Marking  | Prov<br>Hose-  |  |                             | 1                 |
|       | Fin                                      | ISI Marking     st Aid Hose Reels.   |  |  | Maintained by Ambier        | nce Mall          |

M/s Pizza Express Restt, T-303 B, Third floor, Ambience Mall, Vasant Kunj, New Delhi

| 7   | Automatic fire detection & alarming system.                        |                                      | Maintained by Ambience |        |
|---|--|--------------------------------------|------------------------|--------|
|   | Type of detectors  | Required                             | Smoke & Heat           | MR     |
|   | Location of Main Panel   | Required                             | As above               | MR     |
|   | Location of Repeater Panel   | N/A                                  | N/A                    | N/A    |
|   | Alternate source of power  | Required                             | As above               | MR     |
|   | Hooter's location  | Required                             | . As above             | MR     |
| 8.  | MOEFA  | Required                             | As above               | MR     |
| 9.  | Public Address System  | N/A                                  | As above               | N/A    |
| 10.                                       | Automatic Sprinkler System   | Provided &                           | Maintained by Ambience | e Mall |
| - 3                                       | Basement   | Required                             | As above               | MR     |
|   | Upper floors   | Required                             | Provided in Restt.     | MR     |
|   | Sprinkler above false ceiling                                      | N/A                                  | N/A                    | N/A    |
| 11.                                       | Internal Hydrants.   | Provided &                           | Maintained by Ambieno  | e Mall |
| 7   | Size of Riser/Down-comer   | Required                             | As above               | MR     |
|   | Number of Hydrant per floor  | Required                             | As above               | MR     |
|   | Hose box.  | Required                             | As above               | MR     |
| 12.                                       | Yard Hydrants.   | Provided & Maintained by Ambience Ma |                        |        |
| I. dat 6                                  | Total number of hydrants.  | N/A                                  | As above               | N/A    |
|   | Hose box.  | N/A                                  | As above               | N/A    |
| 13.                                       | Pumping arrangements.  |                                      |                        |        |
| 10.                                       | Ground Level   | Provided &                           | Maintained by Ambiene  | e Mall |
|   |  | 4500 LPM                             | As above               | MR     |
|   |  | 70 mtr                               | As above               | MR     |
|   | <ul><li>Head of main pump.</li><li>Number of main pumps.</li></ul> | Two                                  | As above               | MR     |
|   | > Jockey Pump output.  | 450 LPM                              | As above               | MR     |
|   | > Jockey Pump head.  | 70 mtr                               | As above               | MR     |
| - San | > Standby Pump output.   | 4500 LPM                             | As above               | MR     |
|   | > Standby Pump head.   | 70 mtr                               | As above               | MR     |
|   | > Auto Starting / Manual Stopping.                                 | Required                             | As above               | MR     |
|   | Terrace Level  |                                      | Maintained by Ambien   |        |
| -   | Discharge of pump.   | N/A                                  | N/A                    | N/A    |
|   | <ul><li>Head of pump.</li></ul>                                    | N/A                                  | N/A                    | N/A    |
|   | > Power supply.  | N/A                                  | N/A                    | N/A    |
|   | > Auto starting of pump.   | N/A                                  | N/A                    | N/A    |
| 14.                                       | Captive water storage for Fire Fighting.                           |                                      | Maintained by Ambien   |        |
| I.T.                                      | Underground tank capacity.   | 5,00,000 Ltr                         | As above               | MR     |
|   | > Draw-off connection.   | Required                             | As above               | MR     |
|   | Fire Service Inlet.  | Required                             | As above               | MR     |
|   | Access to tank.  | Required                             | As above               | MR     |
|   | Overhead tank capacity.  | 20,000 Ltr                           | As above               | MR     |
| 15.                                       | Exit Signage.  | Required                             | Provided               | MR     |
|   | Provision of Lifts.  |                                      | Maintained by Ambien   |        |
| 10.                                       | Pressurization of lift shaft.                                      | N/A                                  | N/A                    | N/A    |
|   | <ul> <li>Pressurization of lift lobby.</li> </ul>                  | N/A                                  | N/A                    | N/A    |
|   | Communication in lift car.   | N/A                                  | N/A                    | N/A    |
|   | • Fireman's switch.  | N/A                                  | N/A                    | N/A    |
|   |  | N/A                                  | N/A                    | N/A    |
| 17  | Lift signage.  Standby Power Symply.                               | Required                             | Provided (DG Set)      | MR     |
|   | Standby Power Supply   | Required                             | Tiovided (DO Set)      | IVII   |
| 18.                                       | Refuge Area  | N/A                                  | N/A                    | N/A    |
|   | <ul><li>Total area</li><li>Location</li></ul>                      | N/A                                  | N/A<br>N/A             | N/A    |
|   | • Location   | IN/A                                 | IN/A                   | IN/A   |

| 19. | Fire Control Room.                            | Provided & | Provided & Maintained by Ambience Mall |     |  |  |
|-----|---|------------|--|-----|--|--|
|     | Detector System Panel.                        | N/A        | As above                               | N/A |  |  |
|     | Flow Switch Panel.                            | N/A        | As above                               | N/A |  |  |
|     | • PA system Panel.                            | N/A        | As above                               | N/A |  |  |
|     | Battery backup                                | N/A        | As above                               | N/A |  |  |
|     | Building floor plan                           | N/A        | As above                               | N/A |  |  |
| 20. | <b>Special Fire Protection System for the</b> | N/A        | As above                               | N/A |  |  |
|     | Protection of special Risk, if any:           |            |  |     |  |  |

The Fire protection systems provided in the building were checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2014/SZ/942 Dated 30/07/2014, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

: R.N. Singh Designation: ADO

M/s Pizza Express Restt, T-303 B, Third floor, Ambience Mall, Vasant Kunj, New Delhi

Put up with FSC of Mall.

Siv FSC of mal placed at c. 14 pl