## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

F.6/DFS/MS/EH/2017/SZ/983 No.

## FIRE SAFETY CERTIFICATE

Certified that the M/s Chungwa Super Caterers (Restaurant) located at M-34, Greater Kailash-II, Market, New Delhi-110048, comprised of basement, ground plus three upper floors (Restt. running at Ground & First floor with seating capacity of 80 persons) was granted FSC by this department vide letter No. F.6/DFS/MS/EH/2014/SZ/563 dated 02.05.2014. The premises was re-inspected by the officer concerned of this department on 20/06/2017 in the presence of Mr. Manoj Rajvanshi (Manager) of the eating house and observed that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class "Assembly Building" (Eating House) as above with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 10 07 2617 at New Delhi by

(Vipin Kental) Chief Fire Officer

Dated: 1.0. 97 2017

Copy to: -

1. M/S Chungwa Super Caterers, M-34, Greater Kailash-II, Market, New Delhi-110048

2. The DHO (CZ), South MCD, Health Deptt. Jal Vihar, Lajpat Nagar, New Delhi

## Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- 2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
- 4. The basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
- 6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

	INSPECTIO	N REPORT				
1	Name & Address of the Building	M/s Chungwa Super Caterers (Restaurant), M-34, Greater Kailash-II Market, New Delhi-48 Group-D "Assembly" (Restaurant)				
L. Child	value & radiess of the Burtaing					
2	Type of Occupancy					
	Type of Occupancy Building Comprised of	Basement, Ground plus three upper floors				
		Renewal				
	Type of Case  Details of Previous NOC	F.6/DFS/MS/EH/2014/SZ/563 Dated 02-05-2014				
	Fire Safety Directives Letter No					
	Date of Inspection	No. 4/22/2004/HP-III/356–359 dated 22/03/2005 20.06.2017				
	Name of the Inspecting Officers	ADO R.N. Singh				
	Name & Designation of	Mr. Manoj Rajvanshi (Manager)				
	Officers from the building side	Wir. Manoj Kajvanshi (Manager)				
	Year of construction	1995 Restt running at ground & first floor only				
	Applicant letter No.	Nil dated Nil (PUC at C-25)				
S. No	Minimum standards on Fire Prevention and			Remarks		
	Fire Safety U/R 33	(13/12/2005) requirements		MR/NMF		
1	Access to Building.					
	Road width	Required	15 mtr	MR		
	Gate width	N/A	N/A	N/A		
	Width of internal road	N/A	N/A	N/A		
2	Number, width, type & arrangement of exits	<u> </u>				
	a. Number of Staircase	1		> <b>(</b>		
	Upper floors	Two	Two	MR		
	Basement floor	Two	Two	MR		
	b. Width of Staircase		A			
	Upper floors	Required	0.89m & 1m	MR (old case		
	Basement floor	Required	0.81m & 1m	MR (old case		
H	Protection of exits     Fire check door	Required	Provided	MR		
	Pressurization	N/A	N/A	N/A		
		Required	One	MR		
1		N/A	N/A	N/A		
11				MR		
	f. Door size	Required	1.05m & 0.90m 0.84m	m (old case)		
3	Compartmentation.			× × ×		
	Fire check door.	Required	Provided	MR		
and the same of th	<ul> <li>Sealing of electrical shafts.</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Fire rating of shaft door.</li> </ul>	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
	Fire dampers.	N/A	N/A	N/A		
4.	Smoke Management system.			1 100		
	Basement	Required	Provided	MR		
	Upper floors	Required	Provided	MR		
5.	Fire Extinguishers.		2027	1		
	<ul> <li>Total numbers</li> </ul>	ISI marked	09 No's	MR		
	• Types		ABC-06, Co2-03	MR		
	ISI Marking		Provided	MR		
6.	First Aid Hose Reels.			· · · · · · · · · · · · · · · · · · ·		
	Total numbers on each floor.		One (Restt area)	MR		
	<ul> <li>Length of hose-reel hose.</li> </ul>	Hose-reel	30 m	MR		
	Nozzle Diameter	A	05 mm	MR		

M/s Chungwa Super Caterers Restt, M-34, Greater Kailash-II Market, New Delhi-48

	4			
7 Au	utomatic fire detection & alarming system	N/A	N/A	NI/A
	Type of detectors			N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A N/A	N/A N/A	N/A
	Alternate source of power			N/A
	Hooter's location	N/A	N/A	N/A
	OEFA / MCP's	Required	Provided	MR
	ablic Address System	N/A	N/A	N/A
10. At	utomatic Sprinkler System	Daminad	Descided	MD
	Basement	Required	Provided	MR
	Upper floors	Required	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
11. In	ternal Hydrants.		100	
	Size of Riser/Down-comer	Required	100 mm	MR
	Number of Hydrant per floor	N/A	One	N/A
	Hose box.	N/A	One	N/A
12. Ya	ard Hydrants.			
	<ul> <li>Total number of hydrants.</li> </ul>	N/A	N/A	N/A
	• 2. Hose box.	N/A	N/A	N/A
13. Pu	imping arrangements.			
	Ground Level			
	Discharge of main pump.	N/A	N/A	N/A
	Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	> Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	> Standby Pump output.	N/A	N/A	N/A
	> Standby Pump head.	N/A	N/A	N/A
	Auto Starting / Manual Stopping.	N/A	N/A	N/A
	> Access to pump house	N/A	N/A	N/A
•	Terrace Level			
	Discharge of pump.	450 LPM	450 LPM	MR
	Head of pump.	39 mtr	Provided	MR
	Power supply.	Required	Provided	MR
- 1	> Auto starting of pump.	Required	Provided	MR
	aptive water storage for Fire Fighting.	L.		
	Underground tank capacity.	N/A	N/A	N/A
	Draw-off connection.	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	N/A
•		5,000 Ltr	5,000 Ltr	MR
	kit Signage.	Required	Provided	MR
16. Pr	ovision of Lifts.			
	<ul> <li>Pressurization of lift shaft.</li> </ul>	N/A	N/A	N/A
	<ul> <li>Pressurization of lift lobby.</li> </ul>	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
3.30	Fireman's switch.	N/A	N/A	N/A
	Lift signage.	N/A	N/A	N/A
17 St	andby Power Supply	Required	Provided	MR
	efuge Area			
	Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
	M/s Chungwa Super Caterers Restt, M-34,			

M/s Chungwa Super Caterers Restt, M-34, Greater Kailash-II Market, New Delhi-48

19.	Fire Control Room.			
	Detector System Panel.	N/A	N/A	N/A
	Flow Switch Panel.	N/A	. N/A	N/A
	PA system Panel.	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
1	Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any:	N/A	N/A	N/A

The Fire protection systems provided in the building were checked randomely and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2014/SZ/563 Dated 02/05/2014, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: R.N. Singh Designation: ADO

M/s Chungwa Super Caterers Restt, M-34, Greater Kailash-II Market, New Delhi-48

1004/ Crash - Dy 2

Dyc (0(32)

Renewal for FEC, he

CFOCS TO

nisceu PT