

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE

NEW DELHI- 110 001

No.

F6/DFS/MS/EN/2017/1010

Dated

11/07/17

FIRE SAFETY CERTIFICATE

Certified that the **Great Plates Restaurant** running at shop no.1,2,3,(ground floor only), DLF Gallaria Mall, plot no.1B, District Centre, Mayur Vihar-1, Delhi, comprised of basement, ground plus two upper floors owned/occupied by (A unit of M/s Avisons works Pvt. Ltd.,) was granted FSC vide letter No. F6/DFS/MS/EH/NDZ/2014/75 Dated 17/01/14. The Premises was re-inspected by the officer concerned of this department on 05/06/17 in the presence of **Mr. Avi Jain (owner)** and found that the restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with the NBC Part-IV and found that the building (shop 1,2,3) is fit for occupancy class D"Assembly Building" with effect from11/07/17 for a period of **three** years, subject to conditions printed overleaf.

Issued on.....11/07/17.....at New Delhi by


(Vipin Kental)

Chief Fire Officer

To

Great Plates Restaurant A unit of M/s Avisons works Pvt. Ltd.,
Shop no.1,2,3 GF,DLF Gallaria Mall, plot no.1B,District
Centre,Mayur Vihar-1, Delhi.

Copy to-

The Deputy Health Officer,
Shahdara (South) Zone, EDMC,
Health Department, Shahdara South Zone, Karkardooma, Delhi

Conditions

1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
2. All the means of escape shall be kept free of all type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
6. This FSC may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
7. Basement shall be used as per BBL
8. The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J'[sub rule(1) of rule 37] along with a copy of this certificate,six months prior to its expiry"
9. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

1. Name & address of the building : Great Plates Restaurant at shop no.1,2,3
GF,DLF Gallaria Mall, plot no.1B,District
Centre,Mayur Vihar-1, Delhi.
2. Building is comprised of : B,G+2 upper floors (Restaurant at ground floor
only)
3. Type of Occupancy : Assembly
4. Type of Case : Renewal
5. Details of Previous FSC : F6/DFS/MS/EH/NDZ/2014/75 Dated 17/01/14
6. Fire Safety direction letter No : Nil
7. Date of Inspection : 05/06/17 & 15/06/17
8. Name of the Inspecting Officers: : R.K.Yadav ADO
9. Name of the designation of Officer
from the building side : Mr.Avi Jain (owner)
10. Year of Construction : 2006
- 11.Applicant's letter No : Nil Dated 04/06/17

	Minimum Standards on fire prevention and fire safety U/R33	NBC Requirement	Provided at Site	Remarks MR/NMR
1	Access to building			
	Road width	12 m	24 m	MR
	Gate width	4.5 m	4.5 m	MR
	Width of internal road	06 m	06 m	MR
2	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases			
	Upper Floor	NA	NA	NA
	Basement	NA	NA	NA
	b. Width of Staircases			
	Upper Floor	NA	NA	NA
	Basement	NA	NA	NA
	c. Protection of exits			
	Fire check door	Required	Provided	MR
	Pressurization	NA	NA	NA
	e. No. of continuous staircases to terrace	NA	NA	NA
	g. Width of Corridor	NA	NA	NA
	h. Door Size	2 m	One no 2 m, three no 1.20 m	MR
3	Compartmentation.			
	• Fire check door	Required	Provided	MR
	• Sealing of electrical shafts	Required	Provided	MR
	• Fire rating of shaft door	Required	Provided	MR
	• Water curtain	N/A	N/A	N/A
	• Fire Dampers	Required	Provided	MR
4	Smoke Management System.			
	• Basement	N/A	N/A	N/A
	• Upper floor	Required	Provided	MR


IRN/G

5.	Fire Extinguisher			
	• Total numbers	04 no.	04 no.	MR
	• Types	CO ₂ & ABC	CO ₂ & ABC	MR
	• ISI marking	ISI marked	ISI marked	MR
6	First-aid-Hose Reels. (common with entire mall/bldg)			
	Total numbers of each floor	01 no.	01 no	MR
	Length of hose reel hose	30 m	30 m	MR
	Nozzle diameter	5 mm	5 mm	MR
7	Automatic fire detection and alarming system.			
	Type of detectors	Heat/smoke	Provided	MR
	Location of main panel	Reception	Provided	MR
	Location of repeater panel	Reception	Provided	MR
	Alternate source of power	Battery & DG Set	Provided	MR
	Hooter's location	Different location	Provided	MR
8	MOEFA (common with entire mall/bldg)	Required	Provided	MR
9	Public address System.(common with entire mall/bldg)	Provided	Provided	MR
10	Automatic Sprinkler System. (common with entire mall/bldg)			
	basement	NA	NA	NA
	upper floor	NA	NA	NA
	sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants			
	size of riser/down-comer	NA	NA	NA
	Number of hydrants per floor	NA	NA	NA
	Hose Box	NA	NA	NA
12	Yard Hydrants.			
	Total number of hydrants	NA	NA	NA
	Hose Box	NA	NA	NA
13	Pumping Arrangements. (Provided for entire mall/bldg.)			
	• Ground Level			
	➤ Discharge of main Pump	4500 LPM	4500 LPM	MR
	➤ Head of Main Pump	60 M	60 M	MR
	➤ Number of main pumps	2 Nos	2 Nos	MR
	➤ Jockey pump out put	180 LPM	180 LPM	MR
	➤ Jockey pump head	60 M	60 M	MR
	➤ Standby pump out put	4500 LPM	4500 LPM	MR
	➤ Standby pump Head	60 M	60 M	MR
	➤ Auto Starting /Manual stopping	Required	Provided	MR
	➤ Pump House Access	Required	Provided	MR
	• Terrace Level			
	➤ Discharge of pump	450 LPM	450 LPM	MR
	➤ Head of the Pump	60 M	Provided	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR


14	Captive Water Storage for Fire Fighting. (Provided for entire mall/bldg.)			
	Underground tank capacity	4,50,000 Ltrs	4,50,000 Ltrs	MR
	Draw-off connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	Overhead Tank capacity	20,000 Liters	20,000 Liters	MR ✓
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts. Provided in main building			
	Pressurization of Lift Shaft	Required	Provided	MR
	Pressurization of Lift lobby	Required	Provided	MR
	Communication in lift car	Required	Provided	MR
	Firemen's grounding switch	Required	Provided	MR
	Lift Signage	Required	Provided	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room (Provided for entire mall/bldg.)			
	Detector system panel	Required	Provided	MR ✓
	Flow switch panel	Required	Provided	MR
	PA system panel	Required	Provided	MR
	Batter backup	Required	Provided	MR
	Building Floor Plans	Required	Provided	MR
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested checked and found functional at the time of inspection. The mall building was issued FSC vide letter no F6/DFS/MS/NDZ/2017/698 Dated 16/05/17.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The fire safety certificate issued vide letter no. F6/DFS/MS/EH/NDZ/2014/75 Dated 17/01/14 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.


 Signature of the Inspecting Officer
 Name:-R.K.Yadav
 Designation :-ADO(LN)

DO(ED)


 Date: 01/7