

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE

NEW DELHI- 110 001

No. F6/DFS/MS/EH/2017/982

Dated: 10/07/17

FIRE SAFETY CERTIFICATE

Certified that the Restaurant/Eating House at Swaminarayan Akshardham, N.H.24, off. Nizamuddin Bridge, Akshardham Setu, New Delhi-92, owned/occupied by M/s Suvasini Charitable Trust, comprised of ground plus one upper floor was granted NOC by this department vide letter no. F6/DFS/MS/EH/2014/925 Dated 24/07/2014. The Restaurant was re-inspected by the officer of this department on dated 17/06/17 in the presence of Sh. Jayesh Gadhia (Manager) and found that the restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010, and found that the premises is fit for occupancy **Group D Assembly Building "Restaurant"** with effect from 10/07/17 for a period of three years, subject to conditions printed overleaf.

Issued on 10/07/17 at New Delhi by

VK
(Vipin Kental)
Chief Fire Officer
Delhi Fire Service

To,

Sh. Jayesh Gadhia
M/s Suvasini Charitable Trust,
Swaminarayan Akshardham, N.H.24,
Off. Nizamuddin Bridge, Akshardham Setu,
Delhi 92.

Copy to-

The Dy. Health Officer,
EDMC Health Department,
Shahadra (South Zone),
Karkardooma, Shahadara, Delhi

CONDITIONS:

1. All the means of escape shall be kept free of all the type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
5. This Fire Safety Certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
6. All comments/ directions of the Licensing Department shall always be permitted and followed.
7. The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"
8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

- 1 Name & address of the building : Restauranc/Eating House at Swaminarayan Akshardham N.H.24, Off. Nizammuddin Bridge, Akshardham Setu, Delhi-92.
- 2 Building is comprised of : Ground + One upper floor.
- 3 Type of Occupancy : Assembly (Restaurant/ Eating House)
- 4 Type of Case : Renewal
- 5 Details of Previous NOC letter : F.6/DFS/MS/EH/2014/925 Dated 24/07/2014
- 6 Fire Safety direction letter No : NBC Part- IV
- 7 Date of Inspection : 17/06/2017
- 8 Name of the Inspecting officers : ADO Om Prakash
- 9 Name and designation of Officer from the building side : Sh. Jayesh Gadhia (Manager)
- 10 Year of Construction : 2009
- 11 Applicant's letter No : letter No. Nil dated 30/05/2017

N O.	Minimum Standards on fire prevention and fire safety U/R33	NBC(Old) Requirement	Provided at Site	Remarks MR/NMR
1	Access to building			
	• Road width	12 Mtrs	30 Mtrs.	MR
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases			
	• Upper Floor	02 Nos.	03 Nso.	MR
	• Basement	N/A	N/A	N/A
	B. Width of Staircases			
	• Upper Floor	1.5 M	1.35,1.35 & 1.46 M	MR (Old case)
	• Basement	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	e. No. of continuous staircases to terrace	N/A	N/A	N/A
	g. Width of Corridor	2.0 M	3.0 M	MR
	h. Door Size	2.0 Mtr.	3.0 M, 1.8 M	MR
3	Compartmentation.			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	Required	Sealed	MR
	• Fire rating of shaft door	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System.			
	• Basement	N/A	N/A	N/A
	• Upper floor	Required	Provided	MR
5.	Fire Extinguishers			
	• Total numbers	08 Nos.	12 Nos.	MR
	• types	ABC & Co2	ABC & Co2	MR
	• IS marking	ISI marked	ISI marked	MR

6	First-aid-Hose Reels.			
	Total numbers of each floor	2 nos.	3 Nos.	MR
	• Length of hose reel hose	30 m	30 m	MR
	• Nozzle diameter	5 mm	5 mm	MR
7	Automatic fire detection and alarming system.			
	• Type of detectors	N/A	Heat & smoke	MR
	• Location of main panel	N/A	Provided	MR
	• Location of repeater panel	N/A	Provided	MR
	• Alternate source of power	N/A	Provided	MR
	• Hooter's location	N/A	Provided	MR
8	MOEFA	Required	Provided	MR
9	Public address System.	N.A	N.A	N.A
10	Automatic Sprinkler System.			
	• Basement	N/A	N/A	N/A
	• upper floor	N/A	N/A	N/A
	• sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants			
	• size of riser/down-comer	100 MM	100 MM	MR
	• Number of hydrants per floor	2 Nos.	3 Nos.	MR
	• Hose Box	2 Nos.	3 Nos.	MR
12	Yard Hydrants.			
	• Total number of hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13	Pumping Arrangements.			
	• Ground Level			
	➤ Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main Pump	N/A	N/A	N/A
	➤ Number of main pumps	N/A	N/A	N/A
	➤ Jockey pump out put	N/A	N/A	N/A
	➤ Jockey pump head	N/A	N/A	N/A
	➤ Standby pump out put	N/A	N/A	N/A
	➤ Standby pump Head	N/A	N/A	N/A
	➤ Auto Starting /Manual stopping	N/A	N/A	N/A
	➤ Pump House Access	N/A	N/A	N/A
	• Terrace Level			
	➤ Discharge of pump	450 LPM	450 LPM	MR
	➤ Head of the Pump	40 M	40 M	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Auto	MR
14	Captive Water Storage for Fire Fighting.			
	• Underground tank capacity	N/A	1,00,000 Ltrs.	MR
	➤ Draw-off connection	N/A	Provided	MR
	➤ Fire service inlet	N/A	Provided	MR
	➤ Access to tank	N/A	Provided	MR
	• Overhead Tank capacity	10,000 Ltrs.	35,000 Ltrs.	MR
15	Exit Signage.	Required	Provided	MR

16	Provision of Lifts.			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication in lift car	N/A	N/A	N/A
	• Firemen's grounding switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector system panel	N/A	N/A	N/A
	• Flow switch panel	N/A	N/A	N/A
	• PA system panel	N/A	N/A	N/A
	• Battery backup	Required	Provided	MR
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The fire fighting system provided in the building were tested/checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The NOC issued vide letter no. F6/DFS/MS/EH/2014/925 Dated-24/07/2014 is recommended to renew Fire Safety Certificate.

Om Prakash
21/6/17

Signature of the Inspecting Officer
Name- Om Prakash
Designation- ADO

Submitted please.

DO (East)

Line
24/6

DCFO/NDZ

h
C.F.O.

conditions as DFA not mentioned do it in FT.

FT in

M.Scell

U
23/6

187/CF/NDZ
28/6/17/17