GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELEM HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/SZ/2017/ 988

Dated: 11/7/17

FIRE SAFETY CERTIFICATE

Certified that building complex at General Pool Housing 384 T-III Qtrs in phase- II is Central Govt. Employees at Dev Nagar, New Delhi, having seven blocks. Each blocks having two towers. Block G & H (G1, G2, H1, H2) are comprised of stilt plus 08 upper floors each and Blocks ! J, K, L & M (I₁, I₂, J₁, J₂, K₁, K₂, L₁, L₂ M₁, M₂) are comprised of stilt plus 06 floors each owned. occupied by CPWD. The said buildings was inspected by the officer concerned of this department on 26/06/17 in the presence of Sh. M. Prasad, E.E(Civil), Sh. Vijay Kumar, A.E(Civil), Sh. Safreb Kumar, A.E(Elect.), CPWD and found that the said building have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class (residential), with effect from __tf period of five years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued 11/7/17—at New Delhi by.

(VIPEN KENTAL) CHIEF FIRE OFFICER

Copy to:-

The Executive Engineer, Dev Nagar Project Division-I, CPWD, Dev Nagar, New Delhi 2. The Chief Project Manager, Dev Nagar Project Zone, CPWD, Dev Nagar, New Delhi.

3. The Assistant Engineer (E), Dev Nagar Project Division-I, CPWD, Dev Nagar, New Delhi

4. The Secretary, DUAC, India Habitate Centre, Lodhi Road, New Delhi.

Following Fire Safety Directives Must Be Adhered To:-

Providing of fire safety measures does not give any guarantee that there will be No fire. These equipments/installation can minimize the losses if maintained in good working condition and handled

All the fire safety arrangements provided therein shall be maintained in good working condition at all

The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of Any loss of life or property due to non-functional fire safety measures shall be at the risk and

The trained staff should be available round the clock.

Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency

The certificate may not be treated in any case for the regularization of the unauthorized construction.

The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

1. Name & address of the building

: General Pool Housing 384 T-III Qtrs in phase- II for Central Govt. Employees at Dev Nagar, New Delhi

Type of Occupancy

: Residential

3. Type of Case

: New Case

4. Details of previous NOC

: N/A

5. Fire Safety directives letter No

: F.6/DFS/MS/CGFS/BP/2007/1356 dated 15.05.2007

6. Date of inspection

: 26-06-2017

Name of the Inspecting Officers

: M.K. Chattopadhyay, DO(South West),

8. Name and designation of officers

from the building side

: Sh. M. Prasad, E.E(Civil), Sh. Vijay Kumar, A.E(Civil),

Sh. Satish Kumar, A.E(Elect.), CPWD

9. Year of Construction

: 2015-16

10. Applicant's letter No.

: 54(I)/EE/DNPD-I/2017/62 dated 30.05.2017

The said complex is comprised seven blocks. Each blocks have two towers. Block G & H (G1, G2, H1, H₂) are comprised of stilt plus 08 upper floors each and Blocks I, J, K, L & M (I₁, I₂, J₁, J₂, K₁, K₂, L₁, $L_2 M_1, M_2$) are comprised of stilt plus 06 floors each

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per NBC/BBL	Provided at site	Remarks MR/NMR				
1	Access to building							
	Road width	06 mts	Provided	MR				
	Gate width	05 mts	Provided	MR				
	Width of internal road	06 mts	Provided	MR				
2	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases	-	-	-				
	Upper Floors	02 Nos. each block	Provided	MR				
	Basements	N/A	N/A	N/A				
	b. Width of staircases	-	-	MR				
	Upper Floors	1.25 mts each	Provided	MR				
	Basements	N/A	N/A	N/A				
	c. Protection of exits	-	-	-				
	Fire check door	Required	Provided	MR				
	• Pressurization	N/A	N/A	N/A				
	e. No. of continuous staircases to	02	02	MR				
	terrace	N/A	N/A	N/A				
	g. Width of Corridor h. Door Size	1.0 mt.	1.0 mt.	MR				
3	Compartmentation.							
	Fire check door	Required	Provided	MR				
	Sealing of electrical shafts	Required	Sealed	MR				
	Fire Rating of shaft door	N/A	N/A	N/A				
	Water Curtain	N/A	N/A	N/A				

	• The Dampers	IV/A	N/A		IV/A
4	Smoke Management System.				7
	Basements	30 a/c per hour	N/A		N/A
	• Upper floors	12 a/c per hour	Natural Ventilation		MR
5	Fire Extinguishers				
	Total numbers	158	Provided		MR
	• Types	ABC & CO ₂ type	ABC & CO ₂ type		MR
	IS marking	ISI marked	Provided		MR
6	First-Aid Hose Reels.				
	Total numbers on each floor	01	Provided	Y I	MR
	• Length of hose reel hose	30 m	Provided		MR
	Nozzle diameter	5 mm	Provided		MR
7	Automatic fire detection and alarming	g system.			
	Type of detectors	N/A	N/A		N/A
	Location of Main Panel	N/A	N/A		N/A
	Location of Repeater Panel	N/A	N/A		N/A
	Alternate source of power	N/A	N/A		N/A
	Hooters' Location	N/A	N/A		N/A
8	MOEFA	Required	Provided		MR
9	Public Address System.	Required	Provided		MR
10	Automatic Sprinkler System.			8	
	Basement	N/A	N/A		N/A
	Upper Floor/Ground Floor	N/A	N/A		N/A
	Sprinkler above false ceiling	N/A	N/A		N/A
11	Internal Hydrants			0.8:	
	Size of riser/down-comer	100 mm	Provided		MR
	Number of hydrants per floor	01 No.	Provided		MR
	Hose Box	01 No.	Provided		MR
12	Yard Hydrants.				
	Total number of hydrants	14 No.	Provided		MR
	Hose Box	14 No.	Provided	-	MR
13	Pumping Arrangements.				
	Ground Level				
	> Discharge of main Pump	N/A	N/A		N/A
	➤ Head of Main pump	N/A	N/A		N/A
	Number of main pumps	N/A	N/A		N/A
1	> Jockey Pump out put	N/A	N/A		N/A
	> Jockey pump head	N/A	N/A		N/A
	> Standby Pump out put	IN/A	IN/A		27/1

Mr.	Auto Starting/ Manual	N/A	N/A	N/A				
7	stopping	N/A	N/A	N/A				
	> Pump House Access							
	Terrace levelDischarge of pump	900LPM (02 Nos.)	Provided 02 nos (900 LPM each)	MR				
	➤ Head of the pump	70 mts each	Provided	MR				
	> Power Supply	Required	Provided	MR				
	Auto Starting of pump	Required	Provided	MR				
4	Captive Water Storage for fire fighting	g.						
	Underground tank capacity	2,00,000 lts	Provided	MR				
	> Draw-off connection	Required	Provided	MR				
	Fire service inlet	Required	Provided	MR				
	> Access to tank	Required	Provided	MR				
	Overhead Tank capacity	25,000 lts at each block	Provided	MR				
5	Exit Signage.	Required	Provided	MR				
6.	Provision of Lifts.							
	Pressurization of Lift Shaft	Required	Provided	MR				
Seption	Pressurization of Lift lobby	N/A	z N/A	N/A				
	Communication In lift Car	Required	Provided	MR				
	Fireman's Grounding Switch	Required	Provided	MR				
	Lift Signage	Required	Provided	MR				
7	Standby power supply	Required	Provided	MR				
8	Refuge Area.							
	> Total Area	N/A	N/A	N/A				
	> Location	N/A_	N/A	N/A				
9	Fire Control Room							
	Detector System Panel	N/A	N/A	N/A				
	Flow Switch Panel	N/A	N/A	N/A				
	PA System Panel	Required	Provided	MR				
	Batter backup	Required	Provided	MR				
	Building Floor Plans	N/A	N/A	N/A				
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A				

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Note: - All the shortcomings pointed out by this department in earlier inspection vide letter No. F 6/DFS/MS/2017/SZ/1434 dated 02.06.2017 have been complied with.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under Delhi Fire Service 2007 & Rules- 2010.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer (M.K. CHATTOPADHYAY) Divisional Officer, (South West)

of all the sochs for which recommendations were issued jude letter at 15.507 by deport have been constructed or there are some sochs Brill lest.