GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/2017/ HOZ 1066

FIRE SAFETY CERTIFICATE

(Sunil Chowdhary) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

1. The Addl. Commissioner of Police (Lic),
First Floor, P.S. Defence Colony New Delhi Ref. letter No. 1067-1068/Addl. C.P./Lic.(H) dated 01/06/2017.

2. The Manager

Kamal Place Guest House at 3339, Hari Mandir Lane Pahar Ganj New Delhi Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. The means of escape shall be kept unobstructed / unlocked & remain available for speedy evacuation of occupants in case of an emergency.
 - 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
 - 4. The trained fire fighting staff should be available round the clock.
 - 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
 - 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
 - 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
 - 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

H127 -

INSPECTION	REPORT
------------	--------

1. Name & address of the building Kamal Place Guest House at 3339, Hari Mandir Lane, Pahar Ganj New Delhi

2. Type of occupancy:- Residential, Sub Division-A-1

Gr. + 03 Upper floors (total 13 + 6 = 19 Guest rooms) ground floor +01 guest room, 1^{st} to 3^{rd} floor 06 guest rooms at each floor.

3. Type of case:- Renewal

4. Details of previous FSC:- No. F6/DFS/MS/GH/2016/NDZ/1157 dated 18/07/16.

5. Fire safety directives No.-

6. Date of inspection:-

7. Name of the inspecting officer:-

8. Name & designation of officer From the building side:-

9. Year of construction:-

10. Applicant's letter No:-

N/A

14/07/17

D.O. Gurmukh Sigh

Mr. Jatin 2000

No. 1067-1068/Addl.C.P./Lic.(H) dated

01/06/2017.

S.No.	Minimum Standards on fire	Requirement	Provided at site	Old Case Remarks
	Prevention and fire safety	Existing fire		MR/NMR
	U/R 33	safety		
1.	Access to Building	arrangement		
1.				
	1) Road width	N/A	06 mtr.	N/A
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arr	angement of E	xits	
	A. Number of staircases			
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	0.80 mtr.	0.83 mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	N/A	N/A	N/A
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	1 mtr.	1 mtr.	MR
3.	Compartmentation			:
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
117	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A ·	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
3	1) Basements	30 ACPH	N/A	N/A

-H/78-

-		11/10		
-	2) Upper floors	12 a/c per hour	Natural	MR
5.	Fire Extinguishers			
	1) Total numbers	10 Nos.	10 Nos.	
	2) Types	ABC & CO		MR
	3) ISI marking	Required		
6.	First-Aid Hose Reel		Provided	MR
	1) Total number of eachfloo	or 01	01	
	2) Length of hose reel hose	30 mtr.	01	MR
	3) Nozzle diameter	05 mm	30 mtr.	MR
7.	Automatic Fire Detection of	& Alexania G	05 mm	MR
	1) Type of detectors	N/A		
	2) Location of main panel		N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power		N/A	N/A
	5) Hooter's Location		N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.		N/A	N/A	N/A
10.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System 1) Basement			IVA
		N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	
1.	ceiling			N/A
1.	Internal Hydrants			
	1) Size of riser/down-comer	N/A	N/A	DT/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor		11/11	N/A
2	3) Hose box	N/A	N/A	DI/A
2.	Yard Hydrants		14/11	N/A
	1) Total number of hydrants	N/A	N/A	77/4
	2) Hose box	N/A	N/A	N/A
•	Pumping Arrangement		IVA	N/A
	1) Ground level	N/A	N/A	
	a) Discharge of main	N/A		N/A
*	pump	- 11.	N/A	N/A
-	b) Head of main pump	N/A	NI/A	
	c) Number of main pump	N/A	N/A	N/A
A. 11.	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	77/4	N/A	N/A
	stopping	IV/A	N/A	N/A
	2) Terrace level			
-	a) Discharge of pump	450 I D		-1 -1 -1
	b) Head of pump	00	450 LPM	MR
	c) Power supply		30 mtr.	MR
	d) Auto starting of pump	Required	Provided	MR
	of nilmn	Required	Provided	MR

-11/23-

14.	Captive Water Storage for 1	Fire Fighting		
	1) Under ground tank capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	5000 ltr.	5000 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
4	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syste Risk, if any:	em for Protec	tion of special	NA

The existing store/staff rooms at third floor in the building as shown in our inspection report from N/6 to N/13 have been converted/added in to 6 guest rooms for guest house purpose and no addl. Construction is made, as affidavit given by proprietor.

The fire protection systems provided in the guest house building were randomly

tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2016/NDZ/1157 dated 18/07/2016 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Gurmukh Singh Divisional Officer

DYCED(NDZ)

M.S.

all