GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2017/SZ / 1097

Dated: 26/7/17

FIRE SAFETY CERTIFICATE

Certified that the **Goodwill Public School**, Surakhpur More, Gopal Nagar, Najafgarh, New Delhi-110043 comprised of ground plus one upper floor owned/occupied by Goodwill Public School was issued Fire Safety Certificate by this department vide letter No F6/DFS/MS/School/2014/SZ/873 dated 17.07.2014. The school building was re- inspected by the officer concerned of this department on 29.06.2017 in the presence of Sh. Rajesh (Chowkidar) and found that Goodwill Public School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on. 2.6/7/17 at New Delhi.

(VIPIN KENTAL)

OUCHIEF FIRE OFFICER

Copy to:-

- The Manager, Goodwill Public School, Surakhpur More, Gopal Nagar, Najafgarh, New Delhi-110043
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

School building is comprised of ground plus one upper floor INSPECTION REPORT Goodwill Public School, Surakhpur More, Gopal Nagar, Najafgarh, New 1. Name & address of the building: Delhi-110043. Educational 2. Type of Occupancy Renewal 3. Type of Case F6/DFS/MS/School/2014/SZ/873 dated 17.07.2014 4. Details of Previous NOC Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 5. Fire Safety directives letter No 6. Date of inspection A.D.O. Sandeep Duggal 7. Name of Inspecting Officer 8. Name and designation of officers Sh. Rajesh (Chowkidar) From the building side 1996 9. Year of Construction FGPSS/DFS/2017/ dated 01.06.2017 10. Applicant's letter No. Remarks Requirement Provided at Minimum Standards on fire prevention and S. No. MR/NMR as per FSC dt. site fire safety U/R 33 17.07.2014 Access to building 1. M/R 08 mtrs Accessible Road width M/R Directly accessible 4.5 mtrs Gate width from road N/A N/A N/A Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases MR 02 No.'s 02 No.'s Upper Floors N/A N/A Basements N/A b. Width of staircases Upper Floor MR 150 cms/additional 110 & 143 Basements staircase of 75 cms cms if less than 150 cms N/A N/A N/A c. Protection of exits Fire check door N/A Pressurization N/A N/A N/A N/A N/A d. No. of continuous staircases to terrace N/A N/A N/A Width of Corridor M/R 155 cms 150 cms Door Size M/R 105 cms 100 cms Compartmentation 3. N/A N/A N/A Fire check door N/A N/A Sealing of electrical shafts N/A N/A Fire Rating of shaft door N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System 4. N/A N/A N/A Basement MR Natural Required Upper floors ventilation Fire Extinguishers 5. MR Provided 08 no's Total numbers MR Provided ABC type Types MR Provided IS marking ISI marked First-Aid Hose Reels 01no. provided N/A N/A Total numbers on each floor N/A Provided N/A Length of hose reel hose N/A Provided NT/A

	7.	Automatic fire detection and alarming system							
		Type of detectors	N/A	N/A	N/A				
		 Location of Main Panel 	N/A	N/A	N/A				
1		 Location of Repeater Panel 	N/A	N/A	N/A				
		Alternate source of power	N/A	N/A	N/A				
*		Hooters' Location	N/A	N/A	N/A				
	8.	MOEFA	N/A	N/A	N/A				
	.9.	Public Address System	N/A	Provided	N/A				
	10.	Automatic Sprinkler System	NI/A		DI/A				
		Basement Grand Flagge	N/A N/A	N/A N/A	N/A N/A				
		Ground Floor Sprinkler above false cailing							
1	11.	• Sprinkler above false ceiling N/A N/A N/A Internal Hydrants							
	11.	Size of riser/down-comer	N/A	N/A	N/A				
		Number of hydrants per floor	N/A	N/A	N/A				
		Hose Box	N/A	N/A	N/A				
	12.	·							
(Total number of hydrants	N/A	N/A	N/A				
.,1		Hose Box	N/A	N/A	N/A				
	13.	13. Pumping Arrangements							
N		Ground Level			Carlotte Hart				
		Discharge of main Pump	N/A	N/A	N/A				
		➤ Head of Main pump	N/A	N/A	N/A				
		Number of main pumps	N/A	N/A	N/A				
100		> Jockey Pump out put	N/A	N/A	N/A				
		> Jockey pump head	N/A	N/A	N/A				
		Standby Pump out put	N/A	N/A	N/A				
		Standby Pump HeadAuto Starting/Manual Stopping	N/A	N/A	N/A				
		Auto Starting/Manual Stopping	N/A	N/A	N/A				
		Pump House AccessTerrace level	N/A	N/A	N/A				
		Discharge of pump	N/A	220 LPM	N/A				
	- 7: - 1	Head of the pump	N/A N/A	30 mtrs	N/A N/A				
		> Power Supply	N/A	N/A	N/A				
		Auto Starting of pump	N/A	N/A	N/A				
	14. Captive Water Storage for fire fighting								
		I I I I I I I I I I I I I I I I I I I	N/A	N/A	N/A				
		 Underground tank capacity Draw-off connection 		N/A N/A	N/A N/A				
		Fire service inlet	N/A		N/A N/A				
		Access to tank	N/A	N/A N/A	N/A N/A				
V.		Overhead Tank capacity	N/A						
			N/A	2,500 ltrs N/A	N/A N/A				
	15.	Exit Signage.	N/A	N/A	IN/A				
	16.	Provision of Lifts.			(No Lift)				
	4	Pressurization of Lift Shaft	N/A	N/A	N/A				
		Pressurization of Lift lobby	N/A	N/A	N/A				
		Communication In lift Car	N/A	N/A	N/A				
		Fireman's Grounding Switch	N/A	N/A	N/A				
**		Lift Signage			N/A				
			N/A	N/A					
	17.	Standby power supply	N/A	N/A	N/A				
	18.	Refuge Area							
		> Total Area	N/A	N/A	N/A				
1	有明	> Location	N/A	N/A	N/A				

1/12

19.	Fire (Control Room			
		Detector System Panel	N/A	N/A	N/A
	•	Flow Switch Panel	N/A	N/A	N/À
1	•	PA System Panel	N/A	N/A	N/A
	•	Battery backup	N/A	N/A	N/A
	•	Building Floor Plans	N/A	N/A	N/A
20.		al Fire Protection System for Protection ecial Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F6/DFS/MS/School/2014/SZ/873 dated 17.07.2014 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

10-7-17

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

452/00(500)

D.O. (South West)

3

DGP (S2)

Land

10112/24/24