GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELH HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F6/DFS/MS/Hotel/2017/ NO 2/1114

Dated:- 27/7/17

FIRE SAFETY CERTIFICATE

Certified that Hotel The Royal Plaza (A Unite of Hotel Queen Road Pvt. Ltd.) located at 19, Ashoka Road, New Delhi comprised of Basement + Ground + Mezzanine + 18 Upper floors was granted FSC by this department vide letter No. F6/DFS/MS/Hotel/2014/NDZ/656 dated 30/05/14. The premises was re-inspected by the officer concerned of this department on 11/07/17 in the presence of Sh. Manish (Fire Officer) and found that the said Hotel building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential Sub division A-5 Hotel with effect from 2-2/15 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .27/7/17...... at New Delhi by.

(Vipin Kental) Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Joint Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi.
- The Manager, Hotel The Royal Plaza (A Unite of Hotel Queen Road Pvt. Ltd.) at 19, Ashoka Road, New Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

14/25

INSPECTION REPORT

1. Name & address of the building Hotel The Royal Plaza, (Hotel Queen Road Pvt. Ltd.), 19, Ashoka Road, New Delhi – 110001.

2. Type of occupancy:- Residential (Hotel) B + Gr. + Mezz. 18 upper floors

3. Type of case:- Renewal

4. Details of previous FSC:- No. F6/DFS/MS/2014/Hotel/NDZ/656

dated 30/05/14.

5. Fire safety directives No.- NA

6. Date of inspection:- 11/07/17

7. Name of the inspecting officer:- Sh. Sunil Chawdhary Dy. CFO (NDZ),

Sh. Manoj Kumar Sharma (ADO/CC)

8. Name & designation of officer from the building side:-

Sh. Manish (Fire Officer)

9. Year of construction:- 1982

10. Applicant's letter No:- Nil dated 04/07/2017.

				Old Case	
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR	
1.	Access to Building				
	1) Road width	13 mtr.	13 mtr.	MR	
	2) Gate width	06 mtr.	06 mtr.	MR	
	3)Width of internal road	06 mtr.	06 mtr.	MR	
2.	Number, Width Type & Arr				
	A. Number of staircases				
	1. Upper floors	03Nos.	03 Nos.	MR	
	2. Basements	01Nos.	01 Nos.	MR	
	B. Width of staircase				
	1. Upper floors	1 mtr.	1.15 mtr. & 02 Nos. 0.85 mtr. each	MR	
	2. Basements	1 mtr.	0.95 mtr.	MR	
	C. Protection of exits				
	1. Fire check door	Required	Provided	MR	
	2. Pressurization	Required	Provided	MR	
	D. No. of continuous	01	01	MR	
	staircase to terrace				
	E. Width of corridor	01 mtr.	1.05 mtr.	MR	
	F. Door size	01 mtr.	1.05 mtr.	MR	
3.	Compartmentation				
,	1) Fire check door	Required	Provided	MR	
	2) Sealing of electrical shafts	Required	Provided	MR	
	3) Fire rating of shaft door	Required	Provided	MR	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	Required	Provided	MR	
4.	Smoke Management System				
	1) Basements	30 ACPH	Mechanical	MR	
	2) Upper floors	12 a/c per hour	Natural	MR	
5.	Fire Extinguishers				
	1) Total numbers	220 Nos.	233 Nos.	MR	
	2) Types	ABC & CO2	ABC & CO2	MR	
	3) ISI marking	Required	Provided	MR	

6.	First-Aid Hose Reel			
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
100	3) Nozzle diameter	06 mm	06 mm	MR
7.	Automatic Fire Detection &	Alarming Syste	em	
	1) Type of detectors, Heat/Smoke	Smoke & Heat	Smoke & Heat	MR
	2) Location of main panel	Basement	Basement	MR
	3) Location of repeater panel	Required	Provided	MR
	4) Alternate source of power	UPS	UPS	MR
	5) Hooter's Location	Each floor	Each floor	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	1) Basement	Required	Provided	MR
	2) Upper floors	Required	Provided	MR
	3) Sprinkler above false	Required	Provided	MR
	ceiling			
11.	Internal Hydrants			
	1) Size of riser/down-comer	150 mm	150 mm	MR
1	2) Number of hydrants per	01	01	MR
1 1 2 2	floor			
	3) Hose box	01	01	MR
12.	Yard Hydrants			
204	1) Total number of hydrants	06	06	MR
	2) Hose box	06	06	MR
13.	Pumping Arrangement			
	1) Ground level		The state of the s	
	a) Discharge of main	2280 LPM	2280 LPM	MR
	pump	120	120	
	b) Head of main pump	120 mtr.	120 mtr.	MR
	c) Number of main pump		02	MR
	d) Jockey pump out put	180 LPM	180 LPM	MR
	e) Jockey pump head	96 mtr.	96 mtr.	MR
	f) Stand by pump output	2250 LPM	2250 LPM	MR
	g) Stand by pump head	120 mtr.	120 mtr.	MR
	h) Auto starting/Manual	Required	Provided	MR
	stopping 2) Terrace level			
		N/A	N/A	N/A
		N/A N/A	N/A N/A	N/A N/A
	b) Head of pump c) Power supply	N/A N/A	N/A N/A	N/A N/A
	d) Auto starting of pump	N/A N/A	N/A N/A	N/A N/A
14.	Captive Water Storage for F	· · · · · · · · · · · · · · · · · · ·	IN/A	IV/A
17.	1) Under ground tank	2,00,000 litr.	2,00,000 litr.	N/A
	capacity	2,00,000 III.	2,00,000 IIII.	IVA
	a) Draw-off connection	Required	Provided	MR
	b) Fire service inlet	Required	Provided	MR
	c) Access to tank	Required	Provided	MR
			2.0.1000	1

my

	d) Over head tank capacity	20,000 ltr.	95,000 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	Required	Provided	MR
	b) Pressurization of lift lobby	Required	Provided	MR
	c) Communication in lift car	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
	e) Lift signage	Required	Provided	MR
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	300 Sq. feet	300 Sq. feet	MR
	Total area location	15 th floors	15 th floors	MR
19.	Fire Control Room			
7	a) Detector system panel	Required	Provided	MR
	b) Flow switch panel	Required	Provided	MR
	c) PA system panel	Required	Provided	MR
	d) Battery backup	Required	Provided	MR
	e) Building floor plan	Required	Provided	MR
20.	Special Fire Protection Sy Risk, if any: CO2 flooded pa		ection of special	MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Shortcomings communicated vide letter No. F6/DFS/MS/2017/1728 dated 07/07/2017

have been rectified.

In view of the deemed compliance of the minimum standards of fire prevention and fire measures as required under the rules the FSC issued vide letter no. safety F6/DFS/MS/Hotel/2014/NDZ/656 dated 30/05/2014 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name :- Sh. Sunil Chowdhary Designation :- DCFO (NDZ)

Signature of the Inspecting Officer

Name: - M.K. Sharma Designation: - ADO (CC)

C.F.P. F. P.W) Sterrebuntom house priscell FTM 24/2