

FORM 'H'
FORM FOR ISSUING FIRE SAFETY CERTIFICATE
[Refer sub - rule (1) of rule 35]
GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

No. F-6/DFS/MS/2017/WZ/ 1123

Dated: 28/07/17

FIRE SAFETY CERTIFICATE

Certified that the **Mohan Leela Royal (A Unit of Mittal Hotels Pvt. Ltd.) Banquet Hall** located at **Ground Floor, A8/3, Wazirpur Industrial Area, Delhi** in a building comprised of (Basement + Ground + Two Upper Floors) was issued FSC vide Letter No. F-6/DFS/MS/2014/WZ/802 dated- 27/06/2014. The premises was re inspected by the officers concerned of this department on 17-07-2017 in the presence of Sh. Sameer Mittal (Owner) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class " Assembly" Group D with effect from 28/07/17 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 28/07/17..... at New Delhi by.


(Atul Garg)
Chief Fire Officer
Delhi Fire Service

Copy to:

1. Sh. Sameer Mittal (Owner), Mohan Leela Royal (A Unit of Mittal Hotels Pvt. Ltd.)
Banquet Hall, Ground Floor, A8/3, Wazirpur Industrial Area, Delhi

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
6. Basement shall be used as per building bye laws.
7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1. Name & address of the building: **Mohan Leela Royal (A Unit of Mittal Hotels Pvt. Ltd.) Banquet Hall** located at **Ground Floor, A8/3, Wazirpur Industrial Area, Delhi**
2. Type of Occupancy: Banquet, (Basement + Ground + Two Upper Floors)
3. Type of Case :Renewal
4. Details of previous NOC ; F-6/DFS/MS/2014/WZ/802 dated- 27/06/2014
5. Fire Safety directives Letter No. :Nil
6. Date of inspection : 17-07-2017
7. Name of the Inspecting Officer : DO/W & ADO (WP)
8. Name and designation of Officer
 from the building side : Sh. Sameer Mittal (Owner)
 Year of Construction : 1990
9. Applicant's letter No. : Nil Dated -26/06/2017

S No	Minimum standards on fire prevention and fire safety U/R 33	NBC Requirements	Provided at site	Remarks MR/N
1.	Access of building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	06 m	Provided	MR
		Required	Provided (On open Road)	MR
		NA	NA	NA
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases			
	• Upper floors	NA	2 Provided	NA
	• Basements	NA	2 Provided	NA
	b. Width of staircases			
	• Upper floors	NA	NA	NA
	• Basements	NA	NA	NA
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	NA	NA	NA
	d. No of continuous staircase to terrace	01	Provided	MR
	e. Width Of Corridor	NA	Open Hall	NA
	f. Door Size	2x2m	GF=2x206cm, 1x170cm & 1x150cm	MR
3.	Compartmentation			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4.	Smoke managements System			
	• Basements	30a/c per hrs	Exhaust Fan Provided	MR
	• Upper floors	12 a/c per hour	Provided	MR
5.	Fire Extinguishers			
	• Total numbers	17	18 Provided	MR
	• Types	ABC, CO2 & WCO2	Provided	MR
	• IS marking	ISI marked	Provided	MR
6.	First – Aid Hose Reels			
		1	1 Provided	MR

Automatic fire detection and alarming system				
7.	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	NA	NA	MR
		NA	NA	MR
		NA	NA	MR
		NA	NA	MR
		NA	NA	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	<ul style="list-style-type: none"> Basements Upper Floor Sprinkler above false ceiling 	Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
11	Internal Hydrants			
	<ul style="list-style-type: none"> Size of riser/down- comer Number of hydrants per floor Hose Box 	100 mm	Provided	MR
		2	Provided	MR
		2	Provided	MR
12	Yard Hydrants			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	NA	NA	NA
		NA	NA	NA
13	Pumping Arrangements			
	<ul style="list-style-type: none"> Ground Level Discharge of main pump ➤ Head of main pump ➤ Number of main pumps ➤ Jockey pump out put ➤ Jockey pump head ➤ Standby Pump out put ➤ Standby Pump Head ➤ Auto Staring/Manual stopping ➤ Pump House Access Terrace level ➤ Discharge of pump ➤ Head of the pump ➤ Power supply ➤ Auto starting of pump 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		2pumps=450 lpm,225 lpm	Provided	MR
		40m	40 m Provided	MR
		Required	Provided	MR
Required	Provided	MR		
14	Captive water Storage for fire fighting			
	<ul style="list-style-type: none"> Under ground tank capacity ➤ Draw of connection ➤ Fire service inlet ➤ Access to tank Overhead Tank cpty 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		5, 000 litres	Provided	MR
15	Exit Signage	Required	Provided	MR
16	Provision of Lifts			
	<ul style="list-style-type: none"> ➤ Pressurization of Lift Shaft ➤ Pressurization of lift lobby ➤ Communication in lift Car ➤ Fireman's Grounding Switch ➤ Lift Signage 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
17	Standby power supply	Required	Provided	MR
18	Refuge Area			
	<ul style="list-style-type: none"> ➤ Total area ➤ Location 	NA	NA	NA
		NA	NA	NA
19	Fire control room			
	<ul style="list-style-type: none"> ➤ Detector system panel ➤ Flow Switch Panel ➤ PA System Panel ➤ Battery backup 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA


20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA
-----	--	----	----	----

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the FSC issued vide letter no. F-6/DFS/MS/2014/WZ/802 dated- 27/06/2014 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Note;- Earlier two hose reel were seen at ground floor but now one found removed however it meet with requirement with one hose reel.


Signature of the Inspecting Officer



Name Uday Vir Singh

Designation ADO (WP)

Signature of the Inspecting Officer



Name Sh Mukesh Verma

Designation DO (W)

Dy (FOW) 29/7/17
CPD Wd
25/07/17
FTPLS
Mukesh Verma