GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI <u>HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001</u> Fax No. 011-23412593, Ph. 011-23412225

F.6/DFS/MS/EH/2017/SZ/ 1175

FIRE SAFETY CERTIFICATE

Certified that the restaurant Summer House Café (A Unit of Shaktiraj Hospitality Pvt Ltd) located at First Floor, DDA Shopping Complex, Aurobindo Place Market, Hauz Khas, New Delhi, comprised of Ground and First floor was granted FSC by this department vide letter No. F.6/DFS/MS/EH/2014/941 dated 30/07/2014. The premises was re-inspected by the officer concerned of this department on 29-07-2017 in the presence of Mr. Sanju Walia (Manager) and observed that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class-D "Assembly Building" as above with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on \$ 8 17 at New Delhi by

(Vipin Kental) Chief Fire Officer

Copy to: -

No.

1. The DHO (SZ), South MCD, Health Deptt, Green Park, New Delhi-110016

2. M/s Summer House Cafe, First floor, Aurobindo Place Market, Hauz Khas, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- 2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
- 4. The basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
- 6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

	INSPECTI	ON REPORT	34		
1	Name & Address of the Building	Summer House Ca	afe, First Floor, DDA	Shopping	
		Complex, Aurobia	do Place Mkt, Hauz Khas, N Delhi		
		(A Unit of Shaktiraj Hospitality Pvt Ltd)			
2	Type of Occupancy	1	ly Building. (Restaura	nt)	
3	Building comprised of	Ground + One up	per floor.		
4	Type of Case	Renewal			
5	Details of Previous NOC		H/2014/SZ/941 Dated		
6	Fire Safety Directives Letter No	Delhi Fire Service Act-2007 and Rules 2010			
7	Date of Inspection	29-07-2017			
8	Name of the Inspecting Officers	ADO R.N. Singh			
9	Name & Designation of Officers	Mr. Sanju Walia (Manager)			
	from the building side				
10	Year of construction	2005-06 Restt. running at first floor of the building			
11	Applicant letter No.	DHO/SZ/2017/D-541 dated 13/07/2017			
S.	Minimum standards on Fire Prevention	Old FSC Provided at Site Remarks			
No	and Fire Safety U/R 33	(14/10/2005)		MR/NMR	
		requirement			
1	Access to Building.				
	 Road width 	Required	6 mtr	MR	
	Gate width	N/A	Directly accessible	N/A	
		NT/A	from the road	N/A	
	Width of internal road	N/A	N/A	19/A	
2	Number, width, type & arrangement of exits				
	a. Number of Staircase	T	Two	MR	
	Upper floors	Two	N/A	N/A	
	Basement floor	N/A	N/A	IN/A	
	b. Width of Staircase		1.55.0.0.55	N/D (-11	
	 Upper floors 	Required	1.57 & 0.75 mtr	MR (old case	
	Basement floor	N/A	N/A	N/A	
	c. Protection of exits			27/1	
	 Fire check door 	N/A	N/A	N/A	
	 Pressurization 	N/A	N/A	N/A	
	d. No. of continuous staircase to terrace	Required	Two	MR	
	e. Width of corridor	N/A	N/A	N/A	
	f. Door size	Required	1.44 mtr	MR (old case	
3	Compartmentation.				
	Fire check door.	N/A	N/A	N/A	
	 Sealing of electrical shafts. 	N/A	N/A	N/A	
	• Fire rating of shaft door.	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
	• Fire dampers.	N/A	N/A	N/A	
4.	Smoke Management system.				
7.	Basement	30 a/c per hour	N/A	N/A	
	Upper floors	12 a/c per hour	Provided in kitchen	MR	
5.	Fire Extinguishers.				
Jo	Total numbers		14 No's	MR	
	• Types	ISI marked	ABC-10 & Co2-04	MR	
	ISI Marking		Provided	MR	
_	First Aid Hose Reels.			- i	
6.			One	MR	
	Total numbers on each floor.	Hose Reels	30 m	MR	
	 Length of hose-reel hose. 	1105C IXCCIS	5 mm	MR	
	 Nozzle Diameter 		Jiiiii	1411	

Summer House Cafe, DDA Shopping Complex, Aurobindo Place Mkt, Hauz Khas, New Delhi

100000000000000000000000000000000000000	matic fire detection & alarming system.			
	Type of detectors	Required	Heat & Smoke	MR
	Location of Main Panel	Required	1st floor (Reception)	MR
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	Required	Provided	MR
	Hooter's location	Required	Provided	MR
8. MOI	EFA / MCP's	Required	Provided	M/R
	ic Address System	N/A	N/A	N/A
	matic Sprinkler System	1477	14/71	IN/A
	Basement	N/A	N/A	N/A
•	Upper floors	Required	Provided in Restt.	M/R
	Sprinkler above false ceiling	N/A	N/A	N/A
11. Inter	nal Hydrants.			14/21
	Size of Riser/Down-comer	Required	100 mm	M/R
		Required	One	M/R
		Required	One	M/R
12. Yard	Hydrants.			A.D.A.
		N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13. Pum	ping arrangements.			1 1/21
	round Level			
D	Discharge of main pump.	N/A	N/A	N/A
>		N/A	N/A	N/A
>		N/A	N/A	N/A
>		N/A	N/A	N/A
>	The state of the s	N/A	N/A	N/A
>	The state of the s	N/A	N/A	N/A
>	The state of the s	N/A	N/A	N/A
>	The state of the s	N/A	N/A	N/A
• T	errace Level			
>	District of pump.	450 LPM	450 LPM	MR
>	- Parily	40 mtr	40 mtr	MR
>	Power supply.	Required	Provided	MR
11 5	The state of paints.	Required	Provided	MR
	ve water storage for Fire Fighting.			
	nderground tank capacity.	N/A	N/A	N/A
2	Diaw off conficction.	N/A	N/A	N/A
		N/A	Provided	N/A
	Access to tank.	N/A	N/A	N/A
	ignage.	5,000 Ltr	10,000 Ltr.	M/R
	sion of Lifts.	Required	Provided	M/R
110415	Pressurization of lift shaft.	N/A	NI/A	- DT/A
	Pressurization of lift lobby.	N/A N/A	N/A N/A	N/A
	Communication in lift car.	N/A	N/A N/A	N/A
	Fireman's switch.	N/A	N/A N/A	N/A
	Lift signage.	N/A	N/A N/A	N/A
17 Stand	by Power Supply	Required Required		N/A
	e Area	Required	Provided	MR
o. Ittiug	Total area	N/A	N/A	NI/A
	Location	7		N/A
	House Cafe, DDA Shopping Complex	N/A	N/A	N/A

Summer House Cafe, DDA Shopping Complex, Aurobindo Place Mkt, Hauz Khas, New Delhi

19.	Fire Control Room.			
	Detector System Panel.	N/A	N/A	N/A
	Flow Switch Panel.	N/A	N/A	N/A
	PA system Panel.	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the	Required	One Co2 type fire extinguisher	N/A
	Protection of special Risk, if any:	,	provided near electrical panel	

The Fire protection systems provided in the restaurant building were checked/ tested at random and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/DFS/MS/EH/2014/SZ/941 dated 30-07-2014, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: R.N. Singh Designation: ADO

Summer House Cafe, DDA Shopping Complex, Aurobindo Place Mkt, Hauz Khas, New Delhi

DOCOSO)

WISTISTOCS MANGE

FT letter is furtup for sign ply

CHO/sp

M. SCEM WIST

M.