GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2017/SZ/ 1273

Dated: 24/08/17

FIRE SAFETY CERTIFICATE

Certified that the Govt. Sarvodaya Kanya Vidyalaya, SPS Block, A-Block, Janak Puri, New Delhi-110058, consisting of a new block comprised of ground floor plus three upper floors having total 40 rooms (including Class rooms, Lab., Office & Store etc.) owned/occupied by Govt. of NCT of Delhi was inspected by the officer concerned of this department on 04.8.2017 in the presence of Sh. Praveen Grover (Contractor) and found that the Govt. Sarvodaya Kanya Vidyalaya have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (SPS Block only) is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on. 24. 58. 17. at New Delhi.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

- The Principal, Govt. Sarvodaya Kanya Vidyalaya, A-Block, Janak Puri, New Delhi-110058.
- '2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Govt. Sarvodaya Kanya Vidyalaya, A-Block, Janak Puri, New Delhi-58 1. Name & address of the building: Type of Occupancy Educational 2... New 3. Type of Case 4. Details of Previous NOC N/A 5. Fire Safety directives letter No N/A 6. Date of inspection 04.8.2017 7. Name of Inspecting Officer A.D.O. Sandeep Duggal 8. Name and designation of officers Sh. Praveen Grover (Contractor) From the building side Year of Construction 2017 54(SPS SCHOOL)/38 dated 13.6.2017 10. Applicant's letter No. NBC A BBL Remarks Provided at S. No. Minimum Standards on fire prevention and requirements site MR/NMR fire safety U/R 33 Access to building 1. Accessible 06 mtrs 12 mtrs M/R Road width 4.5 mtrs MR 06 mtrs Gate width N/A N/A N/A Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases Upper Floors 02 No.'s 02 No.'s M/R Basements N/A N/A N/A b. Width of staircases 165 & 172 cms M/R 150 cms. Upper Floor N/A N/A N/A Basements c. Protection of exits N/A N/A N/A Fire check door N/A N/A N/A Pressurization M/R Two d. No. of continuous staircases to Required terrace 175 cms. M/R 150 cms. Width of Corridor M/R 100 cms. 115 cms (Double door) Door Size Compartmentation 3. N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System 4. N/A N/A N/A Basements M/R Required Natural ventilation Upper floors provided **Fire Extinguishers** 5. 03 no's Provided M/R Total numbers at each floor ABC/CO₂ type M/R Types Provided IS marking Provided M/R ISI marked First-Aid Hose Reels M/R Provided Two Total numbers on each floor 30 mtrs Provided M/R Length of hose reel hose 5 mm M/R Provided Nozzle diameter

New Building 575 block is comprised of Ground plus unce upper floors.

INSPECTION REPORT

...

	7.:	Automatic fire detection and alarming system	al balls 897 ballst	a was to the			
		Type of detectors	N/A	N/A	N/A		
		Location of Main Panel	N/A	N/A	N/A		
		 Location of Repeater Panel 	N/A	N/A	N/A		
		Alternate source of power	N/A	N/A	N/A		
		Hooters' Location	N/A	N/A	N/A		
	.8.	MOEFA	N/A	N/A	N/A		
	9.	Public Address System	N/A	N/A	N/A		
	10.	Automatic Sprinkler System					
		Basement	N/A	N/A	N/A		
		• Ground Floor	N/A	N/A	N/A		
.11	11.	Sprinkler above false ceiling	N/A	N/A	N/A		
	11.	Internal Hydrants • Size of riser/down-comer	N/A	N/A	N/A		
		Number of hydrants per floor	N/A	N/A N/A	N/A		
	· ·	Hose Box	N/A	N/A	N/A		
	12.	Yard Hydrants	17/11	14/1	14/71		
		Total number of hydrants	N/A	N/A	N/A		
		Hose Box	N/A	N/A	N/A		
	13.	Pumping Arrangements	AUAK	1111	11/11		
		Ground Level					
		Discharge of main Pump	N/A	N/A	N/A		
	· .	Head of Main pump	N/A	N/A	N/A		
		Number of main pumps	N/A	N/A	N/A		
		> Jockey Pump out put	N/A N/A	N/A N/A			
		Jockey pump headStandby Pump out put			N/A		
		> Standby Pump Head	. N/A	N/A	N/A		
		> Auto Starting/Manual Stopping	N/A _	N/A	N/A		
		3	N/A	N/A	N/A		
			N/A	N/A	N/A		
		> Pump House Access	N/A	N/A	N/A		
	to 1	Terrace level					
		Discharge of pump	450 LPM	450 LPM (02	M/R		
		Head of the pump	30 mtrs	no.'s) provided Provided	M/R		
		Power Supply	Required	Provided	M/R		
		Auto Starting of pump	Required	Provided	M/R		
	14.	Captive Water Storage for fire fighting					
	10 M 10 M 10 M	Underground tank capacity	N/A	N/A	N/A		
		Draw-off connection	N/A	N/A	N/A		
		Fire service inlet	N/A	N/A	N/A		
		Access to tank	N/A	N/A	N/A		
	2	 Overhead Tank capacity 	10000 ltrs	Provided	M/R		
	15.	Exit Signage.	Required	Provided	M/R		
			resquired	11011404			
				- Marie - Mari			
	16.	Provision of Lifts.	*****	No Lift	27/1		
		Pressurization of Lift Shaft Pressurization of Lift Shaft	N/A	N/A	N/A		
		Pressurization of Lift lobbyCommunication In lift Car	N/A	N/A	N/A		
	•	Fireman's Grounding Switch	N/A	N/A	N/A		
		Lift Signage	N/A	N/A	N/A		
		2 5.6	N/A	N/A	N/A		
			N/A	N/A	N/A		
	17.	Standby power supply					
	19	Defuge Area					
	18.	Refuge Area. > Total Area	N/A	N/A	N/A		
		> Location	<u></u>	San Parallel San St.	1		
THE STATE OF THE S			N/A	N/A	N/A		

9.	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	 PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
:	Building 1 foor 1 fairs	N/A	N/A	N/A
0.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Note:- As per letter submitted (placed at C-18) by the Assistant Engineer (E), Education Maint Sub-Divn M1-1, PWD, ITI Campus Pusa, New Delhi-110012 electrical connection/supply given to Govt. SKV, A-Block, Janak Puri, New Delhi-110058 will remain available at all time till alternate arrangement has not been made & electrical equipment installed in school shall remain functional through this electrical supply

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

Deto(32)

10/08/17

Deto(32)

10/08/17

Deto(32)

10/08/17

Deto(32)

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/17

10/08/