GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS /GH/ 2017 / W2 /1278

Dated: 25/08/2017

FIRE SAFETY CERTIFICATE

Certified that the Grand Venizia Guest house, 6, Bhama Shah Marg, Opp. Kripal Bagh Ashram, Near Model Town, Delhi-110009 comprised of Basement + Ground and three upper floors owned/ occupied by Sh. Arpit Bindal has already been issue fire safety certificate vide letter no. F6/DFS/MS/GH/2014/WZ/1017 dated 12/08/2014. The premises was re-inspected by the officer concerned of Fire Service on 22/08/2017 in the presence of Sh. Arpit Bindal (Owner) and observed that all the fire prevention & fire safety arrangements as provided in the premises found in good working condition The premises have therefore, deemed complied with the requirement under rule 33 of Delhi Fire Service Rules, 2010 and the building is fit for occupancy class Group A-1 Residential for 40 rooms only with effect from ---/---/2017 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

Issued on 25/08/2017 at New Delhi by

(Atul Garg) Chief Fire Officer Ph:-011-23414250

Copy to:-

- 1. The Additional Commissioner of Police (Lic), 1st floor, Police Station, Defence Colony, New Delhi.
- 2. The Manager, Grand Venizia Guest House, 6, Bhama Shah Marg, Opp. Kripal Bagh Ashram, Near Model Town, Delhi-110009.

INSPECTION REPORT

1. Name & address of the building :Grand Venizia Guest House, 6, Bhama Shah Marg, Opp. Kripal Bagh

Ashram, Near Model Town, Delhi-110009.

2. Type of Occupancy :Guest House (B+G+03 upper floors),

3. Type of Case :Renewal

4. Details of previous NOC :F6/DFS/MS/GH/2014/WZ/1017 Dated: 12/08/2014

5. Fire Safety directives letter No :F.6/DFS/MS/GH/2011/726 dated 21/04/2011

6. Date of inspection :22/08/2017

7. Name of the Inspecting Officers :ADO (RN)

8. Name and designation of officers

from the building side :Mr. Arpit Bindal (Owner)

9. Year of Construction : 2010

10. Applicant's letter No. :Nil Dated 07/08/2017

	Minimum Standards on fire prevention and fire safety U/R 33	NBC/ BBL Requirement	Provided at site	Remarks MR/NMR	
1	Access to building				
	Road width	09m	24m	MR	
	Gate widthWidth of internal road	05m	05m	MR	
		NA	NA	NA	
	Number, Width, Type & Arrangement of Exits			1	
	a. Number of staircases Upper Floors				
	Basements b. Width of staircases	02	02	MR	
		02	02	MR	
	Upper Floors				
	Basements	1.50m	1.44m &1.30m	MR(old case)	
		1.50m	1.44m &1.30m	MR(old case)	
	Protection of exits Fire check door				
	Pressurization	Required	Provided	MR	
	d. No. of continuous staircases to terrace e. Width of Corridor	NA	NA	NA	
		02	02	MR	
		NA	NA	NA	
	f. Door Size	01m	01m	MR	

3	Compartmentation.				
	• Fire check door				
	The cheek door	Required	Provided	MR	
	Sealing of electrical shafts	NA	NA	NA	
	• Fire Rating of shaft door	NA	NA	NA	
	Water Curtain	NA	NA	NA	
	Fire Dampers	NA	ŇA	NA	
4	Smoke Management System.			NA	
	Smoke Wanagement System.				
	• Basements	30 a/c per hour	Exhaust fan	MR	
	Upper floors	12 a/c per hour	Exhaust fan	MR	
5	Fire Extinguishers		Exitatist fair	IVIK	
				D V	
	Total numbers	16nos	24nos	MR	
	TypesISI marking	ABC,W.Co2 & Co2	ABC - Co2	MR	
5	First-Aid Hose Reels.	Yes	Yes	MR	
	That-Aid Hose Reels.				
	Total numbers on each floor	02 at each floor	02 at each floor	MR	
	Length of hose reel hoseNozzle diameter	30m	30m	MR	
6		5mm	5mm	MR	
	Automatic fire detection and alarming syste	m.	,		
	Type of detectors	Required	Provided	MD	
	Location of Main Panel	Ground floor	Provided	MR MR	
	Location of Repeater Panel	NA	NA	NA	
	Alternate source of power	Required	Provided		
	Hooters' Location	2	3 *	MR	
	MOEFA	Required	Provided	MR	
		Required	Provided	MR	
	Public Address System.	Required	Provided	MR	
0	Automatic Sprinkler System.				
	Basement	D - 1		20	
	Upper Floor	Required	Provided	MR	
	• Sprinkler above false ceiling	NA	NA	NA	
	-Francisci doove talse celling	NA.	NA	NA	

1	Interna	Hydrants			
	•	Size of riser/down-comer	100mm	100mm	MR
		Number of hydrants per floor	02Nos.	02 Nos	MR
	•	Hose Box	02 Nos.	02 Nos	MR
12	Yard H	ydrants.			
	•	Total number of hydrants	Required	Provided	MR
	•	Hose Box	Required	Provided	MR
13	Pumping Arrangements.				
	•	Ground Level			
	-	> Discharge of main Pump	1600 lpm	1600 lpm	MR
		➤ Head of Main pump	40m	40m	MR
		Number of main pumps	NA	NA	NA
		> Jockey Pump out put	1600 lpm	1600 lpm	MR
		Jockey pump headStandby Pump out put	40m	40m	MR
	> Standby Pump Head	NA	NA	NA	
	1	> Auto Starting/ Manual stopping	Required	Provided	MR
		> Pump House Access	Required	Provided	MR
	Terrace level		2		
		Discharge of pump	900 lpm	900 lpm	MR
		> Head of the pump	40m	40m	MR
		> Power Supply	Required	Provided	MR
		> Auto Starting of pump	Required	Provided	MR
14	Captiv	e Water Storage for fire fighting.			
	•	Underground tank capacity	1,00,000 ltr	1,00,000 ltr	MR
	>	Draw-off connection	NA	NA	NA
	>	Fire service inlet	NA	NA	ŇA
	>	Access to tank	NA	NA	NA
	•	Overhead Tank capacity	20,000 ltr	20,000 ltr.	MR
15	Exit Si	gnage.	Required	Provided	MR
16	Provisi	ion of Lifts.			

Pressurization of Lift Shaft	N/A	N/A	N/A
 Pressurization of Lift lobby 	N/A	N/A	N/A
 Communication In lift Car Fireman's Grounding Switch Lift Signage 	Required	Provided	MR
	Required	Provided	MR
	Required	Provided	MR
tandby power supply	Required	Provided	MR
efuge Area.			
> Total Area	N/A	N/A	N/A
Location	N/A	N/A	N/A
re Control Room			
Detector System Panel	Required	Provided	MR
• Flow Switch Panel	N/A	N/A	N/A
	N/A	N/A	N/A
•	N/A	N/A	N/A
,	N/A	N/A	N/A
oecial Fire Protection Systems for otection of special Risks, if any:	N/A	N/A	N/A
	 Fireman's Grounding Switch Lift Signage tandby power supply efuge Area. Total Area Location ire Control Room Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	• Fireman's Grounding Switch • Lift Signage Required Possible Area N/A Location Possible Area N/A Possible Area N/A N/A Required N/A N/A N/A Required N/A N/A N/A Required N/A N/A N/A PA System Panel N/A PA System Panel N/A Padding Floor Plans N/A Padding Floor Plans N/A Padding Fire Protection Systems for N/A	• Fireman's Grounding Switch • Lift Signage Required Required Required Provided Required Provided Provided Required Provided Provided Required Provided N/A N/A Provided Provided

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate issued vide this department letter of even no. 1017 dated 12/08/2014under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name: - Rajesh Kumar Designation:- ADO/RN

ORINAD

26.8.2019

cho West Jall

24/8/17