GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/Motel/SZ/2017/ | 32|

Dated: 5/9/17

FIRE SAFETY CERTIFICATE

Certified that the The Golden Tulip Motel, located at Kh. No. 241, 244, 245, 246, min (1st), 249, 251, 252, 253, 256, Village Asola, New Delhi, comprised of Basement and Ground floor has already been issued **FSC** by this department vide letter F6/MS/DFS/Motel/2014/SZ/328 dated 19/03/2014. The premises was re-inspected by the officer concerned of this department on 21/08/2017 in the presence of Mr. Dhoodhnath (Maintenance Supervisor) & found to have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy Group A "Residential Building" with under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on. 5. 9. 1.7....at New Delhi by.

18 3118

(Vipin Kental) Chief Fire Officer Ph:-011-23412235

Copy to:-

- 1. The Joint Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi-
- 2. Executive Engineer (Bldg.), SDMC, Civic Center, Minto Road, New Delhi-110002
- 3. The Authorized Signatory, Golden Tulip Motel, Kh. No. 241, 244, 245, 246, min (1st), 249, 251, 252, 253, 256, Village Asola, New Delhi

Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 5. This fire safety certificate may not in any way be treated as regularization of unauthorized construction, if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

Golden Tulip Motel, Kh. No. 241, 244, 245, 246, min (1st), 249, 251, 252, 253, 256, Village Asola, New Delhi INSPECTION REPORT 1. Name & address of the building: Golden Tulip Motel, Kh. No. 241, 244, 245, 246, min (1st), 249, 251, 252, 253, 256, Village Asola, New Delhi 2. Type of Occupancy : Group A "Residential" (Motel) Building [Basement + G. Floor] 3. Type of Case 4. Details of Previous NOC : F6/MS/DFS/Motel/2014/SZ/328 Dated 19/03/2014 5. Fire Safety directives letter No : F6/DFS/MS/BP/2006/GH/2989 Dated 06/10/2006 6. Date of inspection : 21/08/2017 7. Name of Inspecting Officer : A.K. Malik. 8. Name and designation of officers From the building side : Mr. Dhoodhnath (Maintenance Supervisor) 9. Year of Construction : 2005 10. Applicant's letter No. : 3051/Joint C. P. Lic. (H)/New Delhi dated 08/11/16 & Outdoor diary no. 9398 dated 01/08/2017 S. Minimum Standards on fire prevention and Old NOC Provided at site Remarks No. fire safety U/R 33 (01-02-2011)MR/NMR Requirement 1. Access to building Road width Approachable 30m MR Gate width Adequate 5m x 4 Nos MR -NA-Width of internal road -NA--NA-2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors Two Provided MR Basements Four Provided MR b. Width of staircases Upper Floor Required 1.31m& 1.28m MR(old case) Basements Required 1.09m, 1.50m, MR(old case) c. Protection of exits 3.50m & 1.31m Fire check door Pressurization Required Provided MR d. No. of continuous staircases to terrace -NA--NA--NAe. Width of Corridor Required Two MR Door Size Required 1.70m MR(old case) Required 1.5m (Final Exit) MR(old case) Compartmentation Fire check door Required Provided MR Sealing of electrical shafts Required Provided MR Fire Rating of shaft door -NA--NA--NA-Water Curtain -NA--NA--NA-Fire Dampers -NA--NA--NA-Smoke Management System Basements 30 ACPH **Exhaust Fans** MR Upper floors 12 ACPH -NA--NA-Fire Extinguishers Total numbers Fire Total 30 No's MR **Types** Extinguishers ABC/W.Co₂/Co₂-MR IS marking 10/10/10 Nos Yes MR First-Aid Hose Reels Total numbers on each floor First-Aid Hose 3 No's MR Length of hose reel hose Reels 30m MR Nozzle diameter 5mm MR Automatic fire detection and alarming system Type of detectors -NA-Smoke & Heat -NA-Location of Main Panel -NA-Ground Floor -NA-Location of Repeater Panel -NA--NA--NA-Alternate source of power -NA-Provided -NA-Hooters' Location

NIA

All Floors

NIA

3.

4.

5.

6.

7.

	Upper Floors	Required	Provided	MR 🥎
CO TO TAKE	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.	Internal Hydrants			
	Size of riser/down-comer	-NA-	100mm	-NA-
	 Number of hydrants per floor 	-NA-	3 Nos	-NA-
	Hose Box	-NA-	3 Nos	-NA-
12.	Yard Hydrants			
	 Total number of hydrants 	-NA-	6 No's provided	-NA-
	Hose Box	-NA-	6 No's provided	-NA-
13.	Pumping Arrangements			
	Ground Level			
	Discharge of main Pump	Required	1620 LPM	MR
	Head of Main pump	Required	70m	MR
	Number of main pumps	Required	One	MR
	Jockey Pump out put	Required	180 LPM	MR
	Jockey pump head	Required	70m	MR
	> Standby Pump out put	Required	1620 LPM	MR
	> Standby Pump Head	Required	70m	MR
	> Auto Starting/Manual Stopping	Required	Provided	MR
	Pump House Access	Required	Provided	MR
	Terrace level	Required	Tioriaga	1711
	Discharge of pump	Required	900 LPM	MR
	Head of the pump	Required	40m	MR
	> Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR .
14.	Carting Water Standard for Sing Salating			
14.	Captive Water Storage for fire fighting			73
	Underground tank capacity	1,00,000 Lts	1,00,000 Lts	MR
	Draw-off connectionFire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	Overhead Tank capacity	Required	Provided	MR
15		20,000 Lts	20,000 Lts	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	Pressurization of Lift Shaft	-NA-	-NA-	-NA-
	Pressurization of Lift lobby	-NA-	-NA-	-NA-
	Communication In lift Car Fireman's Grounding Switch	-NA-	-NA-	-NA-
	Fireman's Grounding SwitchLift Signage	-NA-	-NA-	-NA-
	Ditt of Straige	-NA-	-NA-	-NA-
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.	•		
	> Total Area	-NA-	-NA-	-NA-
	> Location	-NA-	-NA-	-NA-
19.	Fire Control Room			
1	Detector System Panel	-NA-	-NA-	-NA-
1	Flow Switch Panel	-NA-	-NA-	-NA-
Thur.	PA System Panel	-NA-	-NA-	-NA-
100	Battery backup			
	Building Floor Plans	-NA-	-NA-	-NA-
	Zananig i toot i tallo	-NA-	-NA-	-NA-
20.	Special Fire Protection System for Protection	n of special Risks,	if any:	-NA-

The shortcomings communicated vide letter dated F6/DFS/MS/Motel/2017/SZ/1901 dated 27/07/2017 fond complied & the fire protection systems provided in the building were randomly tested, checked

Golden Tulip Motel, Kh. No. 241, 244, 245, 246, min (1st), 249, 251, 252, 253, 256, Village Asola, New Delhi the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to renew Fire Safety Certificate under rule 37 of the Delhi Fire Service Rules 2010. Accordingly DFA is put up for approval and signature. Signature of Inspecting Officer Name: A. K. Malik Designation: DO (SD) Dy. CFO (SZ) M. Scell