GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2017/SZ/ 357

Dated: 12/09/17

FIRE SAFETY CERTIFICATE

Certified that the **Govt. Girls Sr. Sec. School**, Paprawat, New Delhi-110043 comprised of three blocks namely Main block, 2nd block & 3rd block. Main block is having ground plus one upper floor, 2nd & 3rd block is having ground floor only owned/occupied by Govt. of NCT of Delhi was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/2011/3552 dated 16.12.2011. The school building was reinspected by the officer concerned of this department on 01.09.2017 in the presence of Sh. Ranjeet Kumar (Security Guard) and found that the Govt. Girls Sr. Sec. School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- The Principal, Govt. Girls Sr. Sec. School, Paprawat, New Delhi-110043
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

Comprised of three blocks namely Main block, 2nd block & 3rd block. Main block is having ground plus one upper floor and 2nd & 3rd block is having ground floor only.

INSPECTION REPORT

1. Name & address of the building : Govt. Girls Sr. Sec. School, Paprawat, New Delhi-110043

2. Type of Occupancy : Educational3. Type of Case : Renewal

4. Details of Previous NOC : F.6/DFS/MS/School/2011/3552 dated 16.12.2011

5. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

6. Date of inspection : 01.09.2017

7. Name of Inspecting Officer : A.D.O. Sandeep Duggal

8. Name and designation of officers

From the building side : Sh. Ranjeet Kumar (Security Guard)

S. No.	Applicant's letter No. : GGSSS/Pap/2 Minimum Standards on fire prevention and	Requirement	Provided at	Remarks			
	fire safety U/R 33	as per FSC dt. 16.12.2011	site	MR/NMR			
1.	Access to building						
	Road width	Accessible 06 mtrs	07 mtrs	MR			
	Gate width	4.5 mtrs	Directly accessible	M/R			
	Width of internal road	N/A	from road N/A	N/A			
2.	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	Upper Floors	02 no.'s in M blk	03 no.'s in M blk	MR			
	Basements	N/A	N/A	N/A			
	b. Width of staircases	2					
	• Upper Floor	150 cms/additional	140, 140 & 162	MR			
	Basements	staircase of 75 cms	cms	11111			
		if less than 150 cms N/A	N/A	N/A			
	c. Protection of exits	IN/A	IN/A	IN/A			
	Fire check door	N/A	N/A	NT/A			
	Pressurization			N/A			
		N/A	N/A	N/A			
	d. No. of continuous staircases to	D · ·		100			
	terrace	Required	two	MR			
	e. Width of Corridor	150 cms	152 cms	MR			
	f. Door Size	100 cms	100 cms (double door) in M blk & 90 cms (double door) in 2 nd & 3 rd blk	MR in Main Block MR, being old case in 2 nd & 3 rd block			
3.	Compartmentation						
	Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	N/A	N/A			
	Fire Rating of shaft door Witten Contains	N/A	N/A	N/A			
_	Water CurtainFire Dampers	N/A	N/A	N/A			
	File Dampers	N/A	N/A	N/A			
4.	Smoke Management System						
	Basements	N/A	N/A	N/A			
	Upper floors	Required	Natural Ventilation provided	MR			
5.	Fire Extinguishers						
	Total numbers	10 No's	Provided	MR			
Sitted	• Types	ABC/CO ₂ type	Provided	MR			
	IS marking	ISI marked	ISI marked	MR			
6.	First-Aid Hose Reels		201 mained	THE			
	Total numbers on each floor	N/A	N/A	N/A			
	I made of home well have	N/A	NI/A	DT/A			

	7	1	1
1		1	

Aut	omatic fire detection and alarming system	N/A	N/A	N/A
	Type of detectors Type of detectors	N/A	N/A	N/A
	Location of Main Panel Specific Panel	N/A	N/A	N/A
	Location of Repeater Panel Alexander of Power	N/A	N/A N/A	N/A
	Alternate source of power	N/A	N/A N/A	N/A
	Hooters' Location	N/A N/A	N/A N/A	N/A
. MO	DEFA	P	Provided	N/A
. Pul	olic Address System	N/A	Provided	14/21
O. Au	tomatic Sprinkler System	N/A	N/A	N/A
	• Basement	N/A	N/A	N/A
	Ground Floor Glassiling	N/A	N/A	N/A
	Sprinkler above false ceiling	IVA		
11. Int	ernal Hydrants	N/A	N/A	N/A
	Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	1012		
12. Ya	rd Hydrants	N/A	N/A	N/A
	 Total number of hydrants 	N/A	N/A	N/A
	Hose Box	11/11		
13. Pu	imping Arrangements			
	Ground Level Did have of main Pump	N/A	N/A	N/A
	Discharge of main PumpHead of Main pump	N/A	N/A	N/A
			N/A	N/A
	Number of main pumpsJockey Pump out put	N/A		N/A
	> Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	> Pump House Access	1		
	Terrace level	N/A	N/A	N/A
	Discharge of pump	N/A N/A	N/A	N/A
	> Head of the pump	N/A N/A	N/A	N/A
-	> Power Supply	N/A	N/A	N/A
	Auto Starting of pump	IN/A		
14.	Captive Water Storage for fire fighting	DT/A	N/A	N/A
	 Underground tank capacity 	N/A	N/A	N/A
	> Draw-off connection	N/A		N/A
	> Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	
	 Overhead Tank capacity 	N/A	N/A	N/A
15.	Exit Signage.	N/A	N/A	N/A
	Provision of Lifts.		rita	(No Lift)
10.		N/A	N/A	N/A
	Pressurization of Lift Shaft Pressurization of Lift Johby	N/A	N/A	N/A
	Pressurization of Lift lobbyCommunication In lift Car	N/A	N/A	N/A
	Communication in int Car	N/A	N/A	N/A
	• Fireman's Grounding Switch			N/A
	• Lift Signage	N/A	N/A	
17.	Standby power supply	N/A	N/A	N/A
10	Defuge Arag		The second	
18.	Refuge Area.			NI/A

P/5

Fire Control Room			27/4
Detector System Panel	N/A	N/A	N/A
Flow Switch Panel	N/A	N/A	N/A
PA System Panel	N/A	N/A	N/A
Battery backup	N/A	N/A	N/A
Building Floor Plans	N/A	N/A	N/A
Special Fire Protection System for Protection of	N/A	N/A	N/A
	Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans Special Fire Protection System for Protection of	Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans N/A Special Fire Protection System for Protection of N/A	Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number <u>F.6/DFS/MS/School/2011/3552</u> dated <u>16.12.2011</u> renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

DCFO(SZ) - on lawe

CFO (south)

FTA

Mscell Ggin

719./11/9.