GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6/DFS/MS/2017/School/w2/1338

Dated: 8 / 9 /2017

FIRE SAFETY CERTIFICATE

Certified that M C Primary Co-ed School located at Sec-9, Raja Pur Village, Rohini, Delhi-110085 comprised of 02 blocks- Ground and 01 upper floor owned/ occupied by North MCD granted **FSC** by this department vide Pry. Co-ed School was No.F6/DFS/MS/SCHOOL/2014/WZ/894 dated 18.07.2014. The premises was re-inspected by the officer concerned of this department on 30.08.2017 in presence of Smt. Manjula Singhal, **Principal** and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ a period of three years, subject to compliance of the conditions mentioned below:

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.Delhigovt.nic.in

Chief Fire Officer Ph:-011-234i4250

Copy to:-

- 1. The Addl. Director of Education, NMCD, Civic Centre, New Delhi.
- 2. The Principal, North MCD Pry. Co-ed School, Sec-9, Raja Pur Village, Rohini, Delhi-110085.

INSPECTION REPORT

1. Name & address of the building

: M C Primary Co-ed School, Raja Pur Village, Sec-9, Rohini, Delhi-85.

2. Type of Occupancy

:Educational

3. Type of Case

5

: Renewal (02 blocks- G+1 upper Floors)

4. Details of previous NOC

: F6/DFS/MS/School/2014/WZ/894 dated 18/07/2014

5. Fire Safety directives letter No

: Director of Education Circular dated 01.03.2011

6. Date of inspection

: 30/08/2017

7. Name of the Inspecting Officers

: ADO (RN)

8. Name and designation of officers

from the building side

: Smt. Manjula Singal, Principal

9. Year of Construction

: --

10. Applicant's letter No.

: Nil Dated-10.07.2017

	Minimum Standards on fire prevention and fire safety U/R 33	Circular of Director of Education	Provided at site	Remarks MR/NMR	
1	Access to building				
	Road width	6m	6m	MR	
	• Gate width	4.5m	3.50m(old Case)	MR	
	Width of internal road	NA	NA	NA	
2	Number, Width, Type & Arrangement of Exits				
	a. Number of staircases			9	
	• Upper Floors	02each blocks	02	MR	
	Basements			1) (c)	
	b. Width of staircases		1.50m each	MR	
	Upper Floors	1.5 m each blocks		NA	
	Basements	NA	NA	NA	
	c. Protection of exits				
	Fire check door	NA	NA	NA	
	Pressurization	NA	NA	NA	
	d. No. of continuous staircases to terrace	NA	NA	NA	
	e. Width of Corridor	NA	NA	NA	
	f. Door Size	1 m	1.0m	MR	
3	Compartmentation.				
	Fire check door	NA	NA	NA	

	Sealing of electrical shafts	NIA	NA I	2.7
22		NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	Water Curtain Fire Dampers	NA	NA	NA
	Fire Dampers	NA	NA	NA
4	Smoke Management System.			***
	Basements	30 a/c per hour	NA	NA
	Upper floors	12 a/c per hour	Natural Ventilated	MR
5	Fire Extinguishers			
	Total numbers	08nos	10 nos	MR
	• Types	ABC/Co2	ABC—10	MR
	ISI marking	ISI Marked	Yes	MR
6	First-Aid Hose Reels.			
	Total numbers on each floor	NA	NA	NA
	• Length of hose reel hose	NA	NA	NA
	Nozzle diameter	NA	NA	NA
7	Automatic fire detection and alarming system.			
	Type of detectors	NA	NA	NA ®
	Location of Main Panel	NA	NA	NA
	Location of Repeater Panel	NA	NA	NA
	Alternate source of power	NA	NA	NA
	Hooters' Location	NA	NA	NA
3	MOEFA	NA	NA	NA
)	Public Address System.	NA	NA	NA
10	Automatic Sprinkler System.			
	Basement	NA	NA	NA
	• Upper Floor	NA	NA	NA
	Sprinkler above false ceiling	NA	NA	NA
11	Internal Hydrants			
	Size of riser/down-comer	NA	NA I	NA
	Number of hydrants per floor	NA	NA	NA

	At a second	The state of the s				
	•	Hose Box	NA	NA	NA	
12	Yard Hydrants.					
	•	Total number of hydrants	NA	NA	NA	
	•	Hose Box	NA	NA	NA	
3	Pumping Arrangements.					
	•	Ground Level				
		Discharge of main Pump	N/A	N/A	N/A	
		Head of Main pump	N/A	e julia		
		Number of main pumps		N/A	N/A	
		Jockey Pump out put	N/A	N/A	N/A	
		Jockey pump head	N/A	N/A	N/A	
	18 4	> Standby Pump out put	N/A	N/A	N/A	
		> Standby Pump Head	N/A	N/A	N/A	
	_	Auto Starting/ Manual stoppingPump House Access	N/A	N/A	N/A	
	•	Terrace level	N/A	N/A	N/A	
	w.	Discharge of pump	• • • • • • • • • • • • • • • • • • • •			
		➤ Head of the pump	NA	N/A	NA	
		> Power Supply	NA	N/A	NA	
		➤ Auto Starting of pump	N/A	N/A	N/A	
			N/A	N/A	N/A	
	Captive Water Storage for fire fighting.					
	•	Underground tank capacity	NA	P	NA	
	>	Draw-off connection	NA	NA	NA	
	>	Fire service inlet	NA	NA va	NA	
	>	Access to tank	NA	NA	NA	
	•	Overhead Tank capacity	NA	N/A	NA	
	Exit Si	gnage.	NA	NA	NA	
5	Provision of Lifts.					
	•	Pressurization of Lift Shaft	N/A	N/A	N/A	
		Pressurization of Lift lobby	N/A	N/A	N/A	
		Communication In lift Car				



	Fireman's Grounding Switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
17	Standby power supply	N/A	N/A	N/A	
18	Refuge Area.				
	> Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19 Fi	Fire Control Room				
	 Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
0	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A.	N/A	

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no.894 dated 18.07.2014.

Signature of the Inspecting Officer

Name: - Rajesh Kumar Designation: - ADO/RN

31.8.17

Po