

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225


No. F.6/DFS/MS/2017/SZ/ 1423

Dated: 27/9/17

FIRE SAFETY CERTIFICATE

Certified that the **Bipin Chandra Pal Memorial Bhawan, A-81, Chittaranjan Park, New Delhi-110019**, comprised of Basement, Ground + One upper floor owned/occupied by **Bipin Chandra Pal Memorial Trust** was granted Fire Safety Certificate by this department vide letter No. F6/DFS/MS/2014/SZ/1101 dated 01/09/2014. The building was re-inspected by officer concerned of this department on 04/09/2017 in the presence of Mr. Manish (Manager) and observed that the said building/premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Assembly" (Community Hall) as above with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 27/9/17 at New Delhi by


(Vipin Kental)
Chief Fire Officer

Copy to: -

1. Mr. R.D. Choudhary (Executive Trustee), A-81, Bipin Chandra Pal Memorial Trust, Chittaranjan Park, New Delhi-110019
2. The Joint C.P. (Lic.), 1st floor, PS Defence Colony, New Delhi-110049

Conditions for the validity of Fire Safety Certificate

1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
4. The basement shall be used strictly as per the provisions of Building Bye Laws.
5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT				
1	Name & Address of the Building	BIPIN CHANDRA PAL MEMORIAL BHAWAN, A-81, CHITTARANJAN PARK, NEW DELHI-110019		
2	Type of Occupancy	Assembly Building "Group-D" (Community Hall)		
3	Building Comprised of	Basements, Ground and one upper floor		
4	Type of Case	Renewal		
5	Details of Previous NOC	F.6/DFS/MS/2014/SZ/1101 dated 01/09/2014		
6	Fire Safety Directives Letter No	F.6/DFS/MS/BP/95/483 dated 24.04.1995		
7	Date of Inspection	204-09-2017		
8	Name of the Inspecting Officers	ADO R.N. Singh		
9	Name & Designation of Officers from the building side	Mr. Manish (Manager)		
10	Year of construction			
11	Applicant letter No.	Nil dated 18-08-2017		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC requirements	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	• Road width	Required	9 mts.	MR
	• Gate width	Required	5.90 mtr (2 No's)	MR
	• Width of internal road	N/A	N/A.	N/A
2	Number, width, type & arrangement of exits.			
	a. Number of Staircase			
	1. Upper floors	Required	2 No's	MR
	2. Basement floor	Required	2 No's	MR
	b. Width of Staircase			
	1. Upper floors	1.20m	1.98m & 2.07m	MR
	2. Basement floor	1.20m	1.36m & 1.45m	MR
	c. Protection of exits			
	1. Fire check door	Required	Provided	MR
	2. Pressurization	N/A	N/A	N/A
	d. No. of continuous staircase to terrace	Required	2 No's	MR
	e. Width of corridor	N/A	N/A	N/A
	f. Door size	N/A	N/A	N/A
3	Compartmentation.			
	• Fire check door.	N/A	N/A	N/A
	• Sealing of electrical shafts.	N/A	N/A	N/A
	• Fire rating of shaft door.	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire dampers.	N/A	N/A	N/A
4.	Smoke Management system.			
	• Basement	30 ACPH	Exhaust fan provided	MR
	• Upper floors	12 ACPH	Natural	MR
5.	Fire Extinguishers.			
	• Total numbers	24 No's	24 No's	MR
	• Types	ABC / Co2	ABC-20 & Co2-04	MR
	• ISI Marking	ISI marked	Yes	MR
6.	First Aid Hose Reels.			
	• Total numbers on each floor.	One	One	MR
	• Length of hose-reel hose.	30 m	30 m	MR
	• Nozzle Diameter	5 mm	5 mm	MR

7	Automatic fire detection & alarming system.			
	• Type of detectors	N/A	N/A	N/A
	• Location of Main Panel	N/A	N/A	N/A
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooter's location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	• Basement	Required	Provided	MR
	• Upper floors	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants.			
	• Size of Riser/Down-comer	N/A	N/A	N/A
	• Number of Hydrant per floor	N/A	N/A	N/A
	• Hose box.	N/A	N/A	N/A
12.	Yard Hydrants.			
	• Total number of hydrants.	N/A	N/A	N/A
	• Hose box.	N/A	N/A	N/A
13.	Pumping arrangements.			
	a) Ground Level			
	➤ Discharge of main pump.	720 LPM	720 LPM	MR
	➤ Head of main pump.	37 mtr	37 mtr	MR
	➤ Number of main pumps.	N/A	N/A	N/A
	➤ Jockey Pump output.	N/A	N/A	N/A
	➤ Jockey Pump head.	N/A	N/A	N/A
	➤ Standby Pump output.	720 LPM	720 LPM	MR
	➤ Standby Pump head.	37 mtr	37 mtr	MR
	➤ Auto Starting/Manual Stopping.	Required	Provided	MR
	b) Terrace Level			
	➤ Discharge of pump.	N/A	N/A	N/A
	➤ Head of pump.	N/A	N/A	N/A
	➤ Power supply.	N/A	N/A	N/A
	➤ Auto starting of pump.	N/A	N/A	N/A
14.	Captive water storage for fire fighting.			
	• Underground tank capacity.	50,000 ltrs	50,000 ltrs	MRA
	• Draw-off connection.	N/A	N/A	N/A
	• Fire Service Inlet.	N/A	N/A	N/A
	• Access to tank.	N/A	N/A	N/A
	• Overhead tank capacity.	15,000 Ltr.	15,000 Ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	• Pressurization of lift shaft.	N/A	N/A	N/A
	• Pressurization of lift lobby.	N/A	N/A	N/A
	• Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	• Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18.	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A

N/17

19.	Fire Control Room.				
	1. Detector System Panel.	N/A	N/A	N/A	
	2. Flow Switch Panel.	N/A	N/A	N/A	
	3. PA system Panel.	N/A	N/A	N/A	
	4. Battery backup	N/A	N/A	N/A	
	5. Building floor plan	N/A	N/A	N/A	
20.	Special Fire Protection System for the Protection of special Risk, if any.		N/A	N/A	N/A

The Fire protection systems provided in the building were checked / operated randomly and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/DFS/MS/2014/SZ/1101 dated 01.09.2014, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

R.N. Singh
14/9/17

Signature of the Inspecting Officer
Name : R.N. Singh
Designation: ADO

BIPIN CHANDRA PAL MEMORIAL BHAWAN, A-81, C.R. PARK, NEW DELHI

D.O. (SD)

Anilam
15/9/17

cf/cfcs20

Long
15/9

cf/ef

m.s cell

FT/101

W
18/9

1246/cfcs2
26/9.

FT letter is put up for sign pl.e

cf/sp

m.s cell

W
25/9.

Puri
22/9

