GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/2017/SZ/ 1417

Dated: 09/10/17

FIRE SAFETY CERTIFICATE

Certified that M/s P. K. Delicacies Pvt. Ltd. Restaurant located at ground and first floor of Residence cum Office Complex, Yeshwant Palace, Chankyapuri, New Delhi, comprised of ground plus seven upper floors but restaurant at ground and first floor only, owned/Occupied by P. K. Delicacies Pvt. Ltd. was granted Fire Safety Certificate by this department vide letter No. F6/MS/DFS/EH/2013/224, dated 29-04-2013. The premises was re-inspected by the officer concerned of this department on 23-09-2017 in the presence of Sh. Manchan Kumar(Manager) and found that the said eating house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for Occupancy Class-D (Eating House) at ground and first floor only with effect from . D. P. J. 10. J. . . 2017 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on.. \triangle $\bigcirc .$. 2017 at New Delhi by.

Chief Fire Officer

T.No.011-23412225

Copy to:-1. Dr. P.K.Sharma, Medical Officer of Health, NDMC, Palika Kendra, New Delhi-01.

2. M/s P. K. Delicacies Pvt. Ltd. Restaurant at Residence cum Office Complex,

Yeshwant Palace, Chankyapuri, New Delhi

Conditions for the validity of fire safety certificate are as under:-

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate in form J, six month prior to its expiry.

INSPECTION REPORT

Name & address of the building: P. K. Delicacies Pvt. Ltd located at ground and first floor of

Residence cum office complex, Yeshwant Palace,

Chankyapuri, New Delhi.

2. Building comprises of

:G+7 but restaurant is at ground and first floor only.

Type of Occupancy

: Group-D.(Eating House)

4. Type of Case

: Renewal of Fire NOC

Details of previous NOC

: F6/MS/DFS/EH/2013/224, dated 29.04.2013.

Fire Safety directives Letter No.: Nil

Date of inspection

: 23.09.2017

8. Name of the Inspecting Officer: Vedpal (ADO).

9. Name and designation of Officer

from the building side

: Sh. Manchan Kumar (Manager).

10. Year of Construction

: 1975

11. Applicant's letter No.

: No. D/MOH/433/Lic/89-10, dated 20.09.2017.

| S | Minimum standards on fire | Requirements/ Existing | Provided at site | Remarks | | | | |
|-----|--|------------------------|------------------|-------------------|--|--|--|--|
| Vo. | prevention and fire safety U/R 33 | Fire Protection System | | MR/NMR | | | | |
| | Access of building | | | | | | | |
| | Road width | 9 M | 20M | MR | | | | |
| | Gate width | 5 M | 5M | MR | | | | |
| | Width of internal road | N.A. | N.A. | N.A. | | | | |
| 2. | Number, width, Type & Arrangements of exits | | | | | | | |
| | | | | | | | | |
| | a. Number of staircases | | | | | | | |
| | Upper floors | 02nos. | 02nos. | MR | | | | |
| | Basements | N.A. | N.A. | N.A. | | | | |
| | b. Width of staircases | | | | | | | |
| | Upper floors | Required | 1.20m & 70cm | MR(old case) | | | | |
| | Basements | N.A. | N.A. | N.A. | | | | |
| | c. Protection of exits | | | | | | | |
| | Fire check door | Required | Provided | MR | | | | |
| | Pressurization | N.A. | N.A. | N.A. | | | | |
| | d. No of continuous staircase | 02nos. | 02nos. | MR | | | | |
| | to terrace | | | | | | | |
| | e. Width Of Corridor | N.A. | N.A. | N.A. | | | | |
| | f. Door Size | Required | 2nos.(1m & 90cm) | MR(old case | | | | |
| 8. | Compartmentation | | | | | | | |
| | • Fire check door | Required | Provided | MR | | | | |
| | | Required | Provided | MR | | | | |
| | Sealing of electrical shafts Fig. Period of cheft door. | * | N.A. | N.A. | | | | |
| | • Fire Rating of shaft door | N.A. | N.A. | N.A. | | | | |
| | Water Curtain | N.A. | N.A. | N.A. | | | | |
| | • Fire Dampers | N.A. | IV.A. | N.A. | | | | |
| ŧ. | Smoke managements System | -/ | | | | | | |
| | Basements | N.A. | N.A. | N.A. | | | | |
| | • Upper floors | Required | Exhaust Fans | MR | | | | |
| | | | Provided | About the Control | | | | |
| 5. | Fire Extinguishers | | | | | | | |
| | | 0.0 | 10 | NAD | | | | |
| | Total numbers | 08nos. | 10 nos. | MR | | | | |

Water Con Con

MR

| | floor | 433 | Machine 1 N | | restaurant | | | |
|--|---|---|---------------------------|------------------------|--|-----------|------|--|
| 175 | Length of hose reel hose | 30m | A RECORD ROSE AND A STORY | | 30m | I | ИR | |
| | Nozzle diameter | 6mr | n | | 6mm | L | ИR | |
| 7. | Automatic fire detection and alarming system | | | | | | | |
| | Type of detectors | Hea | at, Smoke | | Heat, Smoke | | MR | |
| | Location of Main Panel | Ground floor | | | Ground floor | | MR | |
| | Location of Repeater Panel | FCC | | | FCC | | MR | |
| | Alternate source of power | Required | | UPS/Generator/Bat | terie | MR | | |
| | Hooters' Location | | | S | | | | |
| | | Required | | All Corridor, Exit gat | e | MR | | |
| 8. | MOEFA | Requ | Required Provided | | Provided | | MR | |
| | | | | | | | | |
| 9. | Public Address System | Required Provided | | | | MR | | |
| | | | | | | | | |
| 10. | Automatic Sprinkler System | | | | | | | |
| | | | | | | | | |
| | Basements | 1 | N.A. | | N.A. | N.A | | |
| | • Upper Floor | | Required N.A. | | Provided N.A. | MR N.A | | |
| 1.1 | • Sprinkler above false ceiling | C - 1 - 1 | | | | | | |
| 11. | | righti | | | for entire building) | - | | |
| | Size of riser Number of budgets are flower | | 100 mm 02nos. | | .00 mm 11no. Near | MR | | |
| | Number of hydrants per floor Hass Pay | | OZHOS. | A | estaurant | MR | | |
| | Hose Box | | 02nos. | | olno. Near | MR | | |
| | | | 021103. | | estaurant | IVID | | |
| 12. | Yard Hydrants (Fire fighting sy | stem | is common for en | | the contract of the contract o | | 3. | |
| 1 | Total number of hydrants | Stelli | 02nos. | | O2nos. | MR | | |
| | Hose Box | | 06nos | | 06nos. | MR | | |
| 13. | | mping Arrangements (Fire fighting system is common for entire building) | | | | | | |
| 1 | Ground Level | 115 57 | | | ntire banding) | + | | |
| | Discharge of main pump | | 2280 LPM | 2 | 280LPM | | MR | |
| | Head of main pump | | 70meters. | | 70 Meter | | MR | |
| | Number of main pumps | | 01no. | | lno. | | MR | |
| | Jockey pump out put | | 280LPM | | 80LPM | MR | | |
| | Jockey pump head | | 70m(Each) | | 'Om | - | MR | |
| | | | | | | | | |
| 8 | Standby Pump out put | | 2280LPM | 2 | 280LPM | | MR | |
| | > Standby Pump Head | | 70 | 7 | '0m | MR | | |
| | Auto Staring/Manual stoppin | g | Required | | rovided | MR | | |
| | Pump House Access | | Required | | Provided | MR | | |
| | Terrace levelDischarge of pump | | N.A. | - | I.A. | N.A. | | |
| | > Head of the pump | | N.A. | | I.A. | - | N.A. | |
| | Power supply | | N.A. | | I.A. | | N.A. | |
| | Auto starting of pump | | N.A. | | I.A. | | N.A. | |
| 1.4 | | - (P' | N.A. | | I.A. | 1 | N.A. | |
| 14. | Captive water Storage for fire fighting | ig(Fir | e fighting system | 1S CC | ommon for entire bu | ııldin | g) | |
| | a Undangua d tault | | 125000Liters | T. | 125000 Liters | | MR | |
| B | Underground tank capacity | | 123000Liters | | 123000 LILEIS | | IVIN | |
| | > Draw off connection | | Required | Р | rovided | | MR | |
| | Fire service inlet | | Required | | rovided | | MR | |
| | Access to tank | | Required | | rovided | - | MR | |
| | Overhead Tank capacity | | 10000Liters | | 0000Liters | | MR | |
| | | | | | | | | |
| 15 | Exit Signage | | Required | P | rovided | | MR | |
| 16. | Provision of Lifts | | | | | | | |
| | Pressurization of Lift Shaft | | N.A. | | I.A. | | N.A. | |
| | Pressurization of lift lobby | | N.A. | | I.A. | | N.A. | |
| The state of the s | Communication in lift Car | | N.A.* | N | I.A. | | N.A. | |

| | power supply | Required Required | Provided (UPS/ DG Set) | MR |
|----------------|--|---|--|---------------------|
| . 18. Refuge A | | N.A. | N.A. | N.A. |
| | ocation | ΝΔ | N.A. | N.A. |
| 19. Fire con | cocation trol room (Fire fighting system in particular | Required Required Required Required Required Required Required N.A. | Provided Provided Provided Provided Provided Provided N.A. | MR MR MR MR MR N.A. |

The fire protection systems provided in the building were test checked at random and found functional at the time of inspection. In view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules the FSC issued vide letter No.F.6/MS/DFS/EH/2013/224, dated 29.04.2013 renewal under rule 37 of the Delhi Fire Service Rule 2010 is recommended.

Accordingly reply letter in shape of DFA is put up for your kind consideration and

necessary approval please.

Signature of the Inspecting Officer

ivalile .veupai

Designation: Assistant Divisional Officer

Divisional Officer (South)

Soldier Chest this Peridene Cum

Anchology of the Compley on other win.

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2019

2