## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/GH/2017/ No2 1533

Dated : 24/10/17

## FIRE SAFETY CERTIFICATE

Certified that M/S Hazi Hotel located at 914-18, kabari Bazar, Jama Masjid, Delhi-110006. comprised of Ground floor (commercial use other properties), 1st floor (07 guest rooms + reception) & 2nd floor (02 guest rooms) Total 09 guest rooms was granted FSC by this department vide letter No.F6/DFS/MS/GH/2014/NDZ/889 dated 18/07/2014. The premise was re-inspected by the officer concerned of this department on 13/09/17 in the presence of Sh. Hazi Faiyazuddin, Owner of the guest house and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential Group A-1 for 09 guest rooms only as above with effect from -2-1/10/17------ for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued -24/10/17--at New Delhi by.

(Vipin Kental) Chief Fire Officer Delhi Fire Service

Copy to: -

- 1 The Addl. C.P.(Lic.), Police Station, Defence colony, 1<sup>st</sup> floor, New Delhi.
- 2. The Owner, Hazi Hotel, 914-18, kabari Bazar, Jama Masjid, Delhi-110006.

Conditions:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. The means of escape shall be kept unobstructed / unlocked & remain available for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8 The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to it expiry

1/34

## INSPECTION REPORT

1. Name & address of the building:- M/S Hazi Hotel, 914-18, kabari Bazar, Jama Masjid,

Delhi-110006

2. Type of occupancy:- Residential Group A-1 (Ground+ 2 upper floors),

GF- commercial use, 1<sup>st</sup> fl – reception + 07 guest rooms,

2<sup>nd</sup> fl - 02 guest rooms Total 09 guest rooms

3. Type of case:- Renewal

4. Details of previous FSC: - No. F6/DFS/MS/GH/2014/NDZ/889 dated

18/07/2014.

5. Fire safety directives No.- N/A

6. Date of inspection:- 13/09/17

7. Name of the inspecting officer:- A. D.O. Mehmood

8. Name & designation of officer

From the building side:- Sh. Hazi Faiyazuddin(owner)

9. Year of construction:- 1938

10. Applicant's letter No:- 911/Addl. C.P./Lic(H), dated - 17/05/2017

				Old case	
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement (Existing Fire Safety Measures)	Provided at site	Remarks MR/NMR	
1.	Access to Building				
	1) Road width	N/A	14 mtr.	MR	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arrangement of Exits				
	A. Number of staircases				
	1. Upper floors	01 No	02 No.	MR	
	2. Basements	N/A	N/A	N/A	
	B. Width of staircase				
	1. Upper floors	80 cms.	90 & 95 cms.	MR	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits				
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous	01 No.	01 No.	MR	
	staircase to terrace				
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	1 mtr.	1 mtr.	MR	
3.	Compartmentation				
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	1) Basements	30 ACPH	N/A	N/A	
	2) Upper floors	12 ACPH	N/A	N/A	
5.	Fire Extinguishers				
	1) Total numbers	05 Nos.	08 Nos.	MR .	



4/35

pes marking			MR		
marking	Required	Provided	MR		
Aid Hose Reel					
al number of each	01 no.	01 no. at 1 <sup>st</sup>	MR		
or		floor only			
ngth of hose reel hose	30 m.	30 m.	MR		
zzle diameter	5 mm	5 mm	MR		
Automatic Fire Detection & Alarming System					
pe of detectors	N/A	N/A	N/A		
cation of main panel	N/A	N/A	N/A		
cation of repeater panel	N/A	N/A	N/A		
ternate source of power	N/A	N/A	N/A		
ooter's Location	N/A	N/A	N/A		
CFA	N/A	N/A	N/A		
c Address System	Required	Provided	MR		
matic Sprinkler System					
sement	N/A	N/A	N/A		
oper floors	N/A	N/A	N/A		
rinkler above false	N/A	N/A	N/A		
ng	100	TI 4			
nal Hydrants					
ze of riser/down-comer	N/A	N/A	N/A		
umber of hydrants per	N/A	N/A	N/A		
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
ose box	N/A	N/A	N/A		
Yard Hydrants					
otal number of hydrants	N/A	N/A	N/A		
ose box	N/A	N/A	N/A		
ping Arrangement	NI/A	N/A	N/A		
Ground level	N/A		N/A N/A		
a) Discharge of main	N/A	N/A	N/A		
pump	N/A	N/A	N/A		
) Head of main pump		N/A	N/A		
c) Number of main	N/A	IN/A	IN/A		
pump	NI/A	N/A	N/A		
d) Jockey pump out put	N/A		N/A N/A		
e) Jockey pump head	N/A	N/A	N/A		
f) Stand by pump	N/A	N/A	IN/A		
output	NT/A	N/A	N/A ·		
g) Stand by pump head	N/A		N/A N/A		
h) Auto starting/Manual	N/A	N/A	IN/A		
stopping	01	01	MR		
			MR		
,			MR		
			MR		
,	N/A	N/A	N/A		
	b) Head of pump c) Power supply	a) Discharge of pump 225 LPM b) Head of pump 40 m. c) Power supply Required d) Auto starting of N/A	a) Discharge of pump 225 LPM 225 LPM b) Head of pump 40 m. 40 m. c) Power supply Required Provided d) Auto starting of N/A N/A		

4.	Captive Water Storage for Fire	Captive Water Storage for Fire Fighting				
	1) Under ground tank	N/A	N/A	N/A		
	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A	N/A	N/A		
	d) Over head tank	2500 Ltrs	2500 Ltrs	MR		
	capacity			1.00		
15.	Exit Signage.	Required	Provided	MR		
6.	Provision of Lifts.					
	a) Pressurization of lift shaft	N/A	N/A	N/A		
	b) Pressurization of lift lobby	N/A	N/A	N/A		
	c) Communication in lift car	N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A .		
	e) Lift signage	N/A	N/A	N/A		
17.	Stand by Power Supply	Required	Provided	MR		
18.	Refuge Area	N/A	N/A	N/A		
101	Total area location	N/A	N/A	N/A		
19.	Fire Control Room	N/A	N/A	N/A		
	a) Detector system panel	N/A	N/A	N/A		
	b) Flow switch panel	N/A	N/A	N/A		
	c) PA system panel	N/A	N/A	N/A		
	d) Battery backup	N/A	N/A	N/A		
	e) Building floor plan	N/A	N/A	N/A		
20.	Special Fire Protection Systemany:	N/A				

The fire protection system provided in the guest house were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No.F6/DFS/MS/GH/2014/NDZ/889 dated 18/07/2014, renewal under Rule 35 of the

Delhi Fire Service rules 2010, is recommended

Mehmood

Assistant Divisional Officer

D.O. (Central)

Dycro pozs

)9/9 FIK

secired on 13/10

CIED

m seell Woln.

Siepodom Alcas