## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F.6/DFS/MS/EH/2017/SZ/ 1539

Dated: 27/19/1.7

## FIRE SAFETY CERTIFICATE

Certified that the **Restaurant in the name & style of Hangout** (A Unit of MF Entertainment & Amusement P Ltd) located at **Unit No TA-02**, 3<sup>rd</sup> floor, **Select City Walk Mall**, **New Delhi**, building comprised of **3 tier basement**, **ground and seven upper floors** was inspected by the officer concerned of this department on 16/09/2017 in the presence of Mr. Sunny (Manager) of the restaurant and observed that the said building have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class-D "**Assembly**" (Eating House) as above with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued	on	at 1	Vew	Delhi	bv
100000		cee I	1 - 1 -	Y VIIII	~ 1

(Vipin Kental) Chief Fire Officer Ph. 011-23412225

Copy to: -

- 1. The Joint C.P. (Lic.), First Floor, P.S. Defence Colony, New Delhi-110049
- 2. The DHO (Central Zone), South MCD, Health Deptt, Lajpat Nagar, New Delhi-110024
- 3. Authorised Signatory, M/s Hangout (A Unit of M F Entertainment & Amusement P Ltd), Unit No. TA-02, 3<sup>rd</sup> floor, Select City Walk Mall, Saket, New Delhi-110017

## Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- 2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
- 4. The basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

	INSPECTION	ON REPORT		7		
1	Name & Address of the Building  M/s HANGOUT RESTAURANT located at Unit No. TA-					
			ect City Walk Mall, Sake			
		(A Unit of MF Entertainment & Amusement P Lt				
2	Type of Occupancy		ing "Group-D" Restaura			
3	Building Comprised of		Ground + 07 upper floo			
4	Type of Case	New		7		
5	Details of Previous NOC	Nil				
6	Fire Safety Directives Letter No	Nil		- 1		
7	Date of Inspection	16-09-2017				
8	Name of the Inspecting Officers	ADO R.N. Singl	h			
9	Name & Designation of Officers	Mr. Sunny (Man		3212		
	from the building side					
10	Year of construction	Restt loc	ated at 3rd floor of Mall bui	lding.		
11	Applicant letter No.	Nil Dt. Nil ODD	No-10737 Dt. 04.09.20	17		
S. No	Minimum standards on Fire Prevention	NBC/BBL	Provided at Site	Remarks		
	and Fire Safety U/R 33	requirement		MR/NMR		
1	Access to Building.	F.6/DFS/MS/M	all/SZ/2015/SZ/232 Dated	18/02/2015		
	Road width	Restt. within	As above	MR		
	Gate width	mall bldg.	N/A	N/A		
	Width of internal road		N/A	N/A		
2	Number, width, type & arrangement of exits.	Provided & Ma	aintained by Select City	Walk Mall		
	a. Number of Staircase					
	Upper floors	Restt within mal	1 As above	MR		
	Basement floor	N/A	As above	N/A		
	b. Width of Staircase	Provided & Maintained by Select City Walk Mall				
	Upper floors	Restt within mal		MR		
	Basement floor	N/A	As above	N/A		
	c. Protection of exits	Provided & Maintained by Select Ci		Walk Mall		
	Fire check door	N/A	As above	MR		
	Pressurization	N/A	As above	N/A		
	d. No. of continuous staircase to terrace	Required	As above	MR		
	e. Width of corridor	N/A	N/A	N/A		
	f. Door size	2 mtr	2.0m, 2.0m & 1.6m	MR		
3	Compartmentation.	Provided & Ma	intained by Select City			
	Fire check door.		As above	N/A		
	Sealing of electrical shafts.	N/A	As above	N/A		
	Fire rating of shaft door.	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
	Fire dampers.	N/A	N/A	N/A		
4.	Smoke Management system.	Provided & Maintained by Select City Walk M				
	Basement	N/A As above		N/A		
	Upper floors	Required	Exhaust fans provided	MR		
5.	Fire Extinguishers.		Ziziadot Idilo provided	1411		
	Total numbers	8 No's	10 No's	MR		
	Types	ABC/Co2	ABC-08, .Co2-02	MR		
	ISI Marking	ISI marked	Provided			
6.	First Aid Hose Reels.	Provided & Maintained by Select City Walk M		MR		
٧.	Total numbers on each floor.					
		One	As above	MR		
	<ul> <li>Length of hose-reel hose.</li> </ul>	30 m	As above	MR		
	Nozzle Diameter	5 mm	As above	MR		

7	Automatic fire detection & alarming system.	Provided & Mai	ntained by Select City	Walk Mall
	Type of detectors	Required	Smoke & Heat	MR
	Location of Main Panel	Required	As above	MR
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	Required	As above	MR
	Hooter's location	Required	As above	MR
8.	MOEFA	Required	As above	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System		intained by Select City	Walk Mall
10.	Basement	N/A	As above	N/A
	Upper floors	Required	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants.		intained by Select City	Walk Mall
11.	Size of Riser/Down-comer	N/A	As above	N/A
	NY 1 CTY 1 4 CT-	N/A	As above	N/A
		N/A	As above	N/A
10			rovided & Maintained by Select City	
12.	Yard Hydrants.	N/A	As above	N/A
	Total number of hydrants.	N/A	As above	N/A
	Hose box.	IV/A	AS above	17/21
13.	Pumping arrangements.	Drawidad & Ma	intained by Select Cit	Walk Mall
	Ground Level	2280 LPM	As above	MR
	Discharge of main pump.		As above As above	MR
	Head of main pump.	60 mtr		MR
	Number of main pumps.	One	As above As above	MR
	> Jockey Pump output.	180 LPM		MR
	> Jockey Pump head.	60 mtr	As above	MR
	> Standby Pump output.	2280 LPM	As above	MR
	Standby Pump head.	60 mtr	As above	MR
	> Auto Starting / Manual Stopping.	Required	As above	MR
	> Access to pump house	Required	As above	
	Terrace Level		intained by Select Cit	
	Discharge of pump.	450 LPM	As above	MR
	> Head of pump.	40 m	As above	MR
	> Power supply.	Required	As above	MR MR
1	> Auto starting of pump.	Required	As above	
14.	Captive water storage for Fire Fighting.		intained by Select Cit	MR
	<ul> <li>Underground tank capacity.</li> </ul>	1,00,000 ltrs	As above	N/A
	> Draw-off connection.	N/A	As above	N/A N/A
	Fire Service Inlet.	N/A	As above	N/A N/A
	Access to tank.	N/A	As above	
440	Overhead tank capacity.	5,000 Ltr	As above	MR MR
15.	Exit Signage.	Required	Provided	
16.	Provision of Lifts.	Provided & Ma		
	<ul> <li>Pressurization of lift shaft.</li> </ul>	N/A	As above	N/A
	<ul> <li>Pressurization of lift lobby.</li> </ul>	N/A	As above	N/A
	<ul> <li>Communication in lift car.</li> </ul>	N/A	As above	N/A
	• Fireman's switch.	N/A	As above	N/A
	Lift signage.	N/A	As above	N/A
17	Standby Power Supply	Required	As above	MR
18.	Refuge Area			3
10.	Total area	N/A	N/A	N/A
	1 Otal area			

19.	Fire Control Room.	Provided & Maintained by Select City Walk Mall			
	Detector System Panel.	N/A	As above	N/A	
	Flow Switch Panel.	N/A	As above	N/A	
	PA system Panel.	N/A	As above	N/A	
	Battery backup	N/A	As above	N/A	
	Building floor plan	N/A	As above	N/A	
20.	Special Fire Protection System for the Protection of special Risk, if any:	N/A	As above	N/A	

Restaurant is located at 3rd floor of mall building. Underground and over-head water storage tank, fire pumps, hose-reels, means of escape, automatic detection system, fire control room etc. are provided and maintained by mall management. The fire safety arrangements provided therein are common for entire building

The Fire protection systems provided in the building were checked / operated and found functional at the time of inspection.

Keeping in view the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name

: R.N. Singh

Designation: ADO

If the fire sujety arrangements like to reel, MACP, five primps were incheed whent Mas their Status in