GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2017/SZ

1556

Dated: 31 10 17

FIRE SAFETY CERTIFICATE

Certified that the **Pioneer Kamal Convent Sec. School,** Pioneer Road, Vikas Nagar, Hastsal, New Delhi-110059, comprised of ground floor plus three upper floors, owned/occupied by Pioneer Kamal Convent Sec. School was issued Fire Safety Certificate by this department vide letter F6/DFS/MS/School/2014/SZ/739 dated 16.06.2014. The School building was re-inspected by the officer concerned of this department on 04.10.2017 in the presence of Dr. Pramod Kumar (Admin. Officer) and found that the Pioneer Kamal Convent Sec. School have deemed complied the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class "Educational" for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on at New Delhi.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

- The Manager, Pioneer Kamal Convent Sec. School, Pioneer Road, Vikas Nagar, Hastsal, New Delhi-110059
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Comprised of ground plus three upper floors INSPECTION REPORT Name & address of the building: Pioneer Kamal Convent Sec. School, Pioneer Road, Vikas Nagar, Hastsal, New Delhi-110059. Type of Occupancy Educational 3. Type of Case Renewal 4. Details of Previous NOC F6/DFS/MS/School/2014/SZ/739 dated 16.06.2014 5. Fire Safety directives letter No: N/A 6. Date of inspection 04.10.2017 7. Name of Inspecting Officer : A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side Dr. Pramod Kumar (Admin. Officer) 9. Year of Construction 1995-1996 10. Applicant's letter No. Nil dated 10.08.2017 Minimum Standards on fire prevention and S. No. Requirement as Provided at Remarks fire safety U/R 33 per FSC dt. site MR/NMR 16.06.2014 1. Access to building Road width Accessible 05 mtrs MR, being old case Gate width 4.5 mtrs Directly accessible MR N/A Width of internal road from road N/A N/A Number, Width, Type & Arrangement of Exits 2. a. Number of staircases Upper Floors 02 No's 03 No's MR Basements N/A N/A N/A b. Width of staircases Upper Floor 150 cms/additional 150, 150 to 115 & MR staircase of 75 cms 125 to 110 cms Basements if less than 150 cms N/A N/A N/A c. Protection of exits Fire check door N/A Pressurization N/A N/A N/A N/A N/A d. No. of continuous staircases to terrace Required Two MR Width of Corridor 150 cms 200 cms MR Door Size 100 cms 110 cms MR 3. Compartmentation Fire check door N/A N/A N/A Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A Water Curtain N/A Fire Dampers N/A N/A N/A N/A N/A N/A 4. Smoke Management System Basements N/A N/A N/A Upper floors Required Natural MR ventilation 5. Fire Extinguishers Total numbers 12 no.'s Provided MR Types ABC/CO₂ type Provided MR IS marking ISI marked ISI marked MR 6. **First-Aid Hose Reels** Total numbers on each floor One Provided MR Length of hose real hose

	and the second s			
7.	Automatic fire detection and alarming system			
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel GRanding Control of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel Alternate source of power	N/A	N/A	N/A
	Alternate source of powerHooters' Location	N/A	N/A	N/A
`		N/A	N/A	N/A
3.	MOEFA	N/A	N/A	N/A
0.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System Basement	27/4	77/1	
	Ground Floor	N/A N/A	N/A	N/A
	 Sprinkler above false ceiling 	HACKS INTO	N/A	N/A
1.	Internal Hydrants	N/A	N/A	N/A
	Size of riser/down-comer	N/A	100 mm	DT/A
	Number of hydrants per floor	N/A	One	N/A N/A
	Hose Box	N/A	One	N/A
2.	Yard Hydrants	11/11	One	IN/A
6	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A N/A
3.	Pumping Arrangements	_ 1/ L X	11/11	IN/A
	Ground Level		•	
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	A Mar Phase Production	
	> Jockey Pump out put	- COLONIA DE COLONIA D	N/A	N/A
	Jockey pump headStandby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A
	S	N/A	N/A	N/A
		N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace level			*
	Discharge of pump	450 LPM	450 LPM & 180	MR
	Head of the pumpPower Supply	40 matura	LPM provided	A Company of the Comp
	> Auto Starting of pump	40 mtrs Required	Provided	MR
	7 rate Starting of pump	N/A	Provided N/A	MR
١.	Captive Water Storage for fire fighting	IN/A	IN/A	N/A
e e	Underground tank capacity	NT/A	NT/A	27//
	> Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
15.	Overhead Tank capacity	N/A	N/A	N/A
	F-4 0	10000 ltrs	Provided	MR
•	Exit Signage.	Required	Provided	MR
	Provision of Lifts.	4	- W	No Lift
	Pressurization of Lift Shaft	N/A	N/A	N/A
	 Pressurization of Lift lobby 	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A N/A	N/A N/A
	Fireman's Grounding Switch	N/A		
	Lift Signage		N/A	N/A
		N/A	N/A	N/A
	Standby power supply	Required	Provided	MR
	Defuge Avec			
	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	> Location			
100		N/A	N/A	N/A

2/16

	 Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A N/A N/A N/A	N/A N/A N/A N/A	N/A N/A N/A N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional time of inspection. Shortcomings issued vide F.6/DFS/MS/School/2017/SZ/1927 dated 31.07.2017 has been complied.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter number F6/DFS/MS/School/2014/SZ/739 dated 16.06.2014 renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

764/DOCSW) ctl.09/10/2017

D.O. (South West)

CFO (32) M. SCEN 13/10.

F.T. letter is put up for signature please.

CFOCSZ)

M.S CELL WE 30/10.