GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No. F6/MS/DFS/EH/SZ/2017/ 1609

Dated: /0/11/17

FIRE SAFETY CERTIFICATE

Certified that M/s Shree Rathnam Restaurant, HL-5, L-Block, Jail Road, Hari Nagar, New Delhi-110064 comprised of basement, ground plus two upper f. But restaurant is running at ground floor and first floor only, owned/occupied by M/s Shree Rathnam Restaurant was inspected by the officers concerned of this department on 15.09.2017 in the presence of Smt. Smritie Dass (General Manager) and found that the owner have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules,2010 and that the building/premises (Ground floor plus one upper floor only) is fit for occupancy Group-D, Assembly building with effect from......2017 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed as under.

Issued on2017 at New Delhi by.

(Vipin Kental) Chief Fire Officer, Ph: 011 - 23412225.

Copy to:

DHO(West Zone, SDMC) Public Health Department, Vishal Enclave, Rajouri Garden, New Delhi-110027. (Ref. No. D-2031/HD/WZ, dated 16.06.2016)

2. The Manager, M/s Shree Rathnam Restaurant, HL-5, L-Block, Jail Road, Hari Nagar, New Delhi-110064.

Following fire safety directives must be adhered to:-

1. The estaurant will be running at ground floor and first floor only.

- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. The means of escape arrangements shall be kept unlocked and unobstructed for speedy evacuation of occupants in case of an emergency.
- 4. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

5. The trained staff should be available round the clock.

- 6. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 7. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

8. Basement shall be used as per building bye laws.

- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 10. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

Comprised of basement, ground plus two upper floors, but restaurant is at ground plus one upper floor only

	Transfer of outside plant two upper	110013, but i estauran	it is at ground plus on	e upper moor only			
	INSPECTIO						
	1. Name & address of the building: M/s Shree	Rathnam Restaura	ant, HL-5, L-Block,	Jail Road, Hari			
	Nagar, Ne 2. Type of Occupancy : Assembly						
	2. Type of Occupancy : Assembly3. Type of Case : New	/					
	4. Details of Previous NOC : N/A						
	5. Fire Safety directives letter No : N/A						
	6. Date of inspection : 15.09.201	7		,			
			A.D.O. Sandeep D	11002			
	8. Name and designation of officers	1 3 3	Z dans	~55m			
	From the building side : Smt. Smr	ritie Dass (General	Manager)				
	9. Year of Construction : Before 2010						
		10. Applicant's letter No. : Nil dated 27.07.2017					
S. No.	Basement (vacant other property), Ground floo	or & First floor (res					
5. 110.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at	Remarks			
1.	Access to building	Requirement	site	MR/NMR			
1.	Access to bunding						
	Road width	12 mtrs	18 mtrs	M/R			
	Gate width	4.5 mtrs	Directly accessible	M/R			
	 Width of internal road 	N/A	from road	N/A			
2.	Number, Width, Type & Arrangement of Exits		N/A				
	a. Number of staircases						
	• Upper Floors	02 No's	02 No's	M/R			
	Basement	N/A	N/A	Restaurant at GF &			
	b. Width of staircases			FF			
	Upper Floor	150	150 0 150				
	Basements	150 cms	150 & 150 cms	M/R			
	c. Protection of exits	N/A	N/A	Restaurant at GF & FF			
	Fire/smoke check door			11			
	 Pressurization 	N/A	N/A	N/A			
		N/A	N/A	N/A			
		11/21	11//1	IN/A			
	d. No. of continuous staircases to	Required	One	M/D			
	e. Width of Corridor			M/R			
	e. Width of Corridor f. Door Size	150 cms	Opening in hall	N/A			
		200 cms	210 & 120 cms	M/R			
3.	Compartmentation	/					
	Fire check door	N/A	NI/A	DT/A			
	 Sealing of electrical shafts 		N/A	N/A			
	Fire Rating of shaft door	N/A	N/A	N/A			
	Water Curtain	N/A 🤜	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			
1.		N/A	N/A	N/A			
	Smoke Management System						
	Basements	N/A	N/A	N/A			
	4	14/11	11//	IN/A			
V.							
	Upper floors	Required	Natural	M/R			
	Ti Tu i		ventilation				
5.	Fire Extinguishers						
	Total numbers	08 No.'s	Drovidad	M/D			
	• Types	ABC/CO ₂ type	Provided	M/R			

6. Date of inspection 15.09.2017

D.O M.K. Chattopadhyay & A.D.O. Sandeep Duggal 7. Name of Inspecting Officer

8. Name and designation of officers

From the building side Smt. Smritie Dass (General Manager)

9. Year of Construction : Before 2010

10. Applicant's letter No. : Nil dated 27.07.2017
Basement (vacant other property), Ground floor & First floor (restaurant) & second floor (Offices)

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR		
1.	Access to building					
	Road width	12 mtrs	18 mtrs	M/R		
	Gate width	4.5 mtrs	Directly accessible	M/R		
	Width of internal road	N/A	from road N/A	N/A		
2.	Number, Width, Type & Arrangement of Exit	S	1			
	a. Number of staircases					
	Upper Floors	02 No's	02 No's	M/R		
	Basement	N/A	N/A	Restaurant at GF &		
				FF		
	b. Width of staircases		1.50 0 1.50	1.6/0		
	Upper Floor	150 cms	150 & 150 cms	M/R		
	Basements C. Protection of exits	N/A	N/A	Restaurant at GF & FF		
	Frotection of exits Fire/smoke check door					
	Pressurization	N/A	N/A	N/A		
	1 Tessurization	N/A	N/A	N/A		
		IN/A	14/71	1471		
	d. No. of continuous staircases to	D '1	One	M/R		
	terrace	Required				
	e. Width of Corridor	150 cms	Opening in hall	N/A		
	f. Door Size	200 cms	210 & 120 cms	M/R		
3.	Compartmentation					
	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4		IV/A	IVA	1071		
4.	Smoke Management System					
	Basements	N/A	N/A	N/A		
	Upper floors	Required	Natural ventilation	M/R		
5.	Fire Extinguishers					
	Total numbers	08 No.'s	Provided	M/R		
		ABC/CO ₂ type	Provided	M/R		
	TypesIS marking	4	Provided	M/R		
		ISI marked	Frovided	IVI/ IX		
6.	First-Aid Hose Reels					
-	Total numbers on each floor	01 No.	Provided	M/R		
	 Length of hose reel hose 	30 mtrs	Provided	M/R		
	Nozzle diameter	5 mm	Provided	M/R		

Comprised of basement, ground plus two upper floors, but restaurant is at ground plus one upper floor only

7.	Automatic fire detection and alarm Type of detectors	N/A	De! J 1	AT/A
	Location of Main Panel		Provided	N/A
	 Location of Walli Faller Location of Repeater Panel 	N/A	Ground floor	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	Provided	N/A
0		N/A	In Hall	N/A
8.9.	MOEFA	Required	Provided	M/R
10.	Public Address System Automatic Sprinkler System	Required	Provided	M/R
10.	Basement	N/A	N/A	t at GF & FF N/A
	Ground Floor	N/A	N/A	N/A N/A
	 Sprinkler above false ceiling 	N/A	N/A	N/A
11.	Internal Hydrants	IV/A	IN/A	IN/A
	•			
	 Size of riser/down-comer 	One	Provided	M/R
	 Number of hydrants per floor 	One	Provided	M/R
	Hose Box	One	Provided	M/R
12.	Yard Hydrants			
	• Total number of hydrants	N/A	N/A	N/A
10	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	> Head of Main pump	N/A	N/A	N/A
	> Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head		N/A	N/A
	➤ Auto Starting/Manual Sto	pping N/A	N/A	W. Walle, J. Co.
	➤ Pump House Access	N/A N/A	N/A N/A	N/A N/A
	Terrace level	14/11	IVA	IVA
	Discharge of pump	450 LPM	900 LPM	M/R
	> Head of the pump		provided	
	> Power Supply	30 mtrs	Provided	M/R
	> Auto Starting of pump	Required	Provided	M/R
	7 Auto Starting of pump	Required	Provided	M/R
14.	Captive Water Storage for fire fight			
	Underground tank capacity	N/A	N/A	N/A
	Draw-off connectionFire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
		10000 ltrs	Provided	M/R
15.	Exit Signage.	Required	Provided	M/R
	B. I.I. C. I.			
16.	Provision of Lifts.	27/4	27/4	27/4
	Pressurization of Lift labby Pressurization of Lift labby	N/A	N/A	N/A
	Pressurization of Lift lobbyCommunication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
		N/A	N/A	N/A
17.	Standby power supply	Required	Provided	M/R

1/10

Comprised of basement, ground plus two upper floors, but restaurant is at ground plus one upper floor only

19.	Fire Control Room	N/A	N/A	N/A
	Detector System Panel	N/A	N/A	N/A
	Flow Switch PanelPA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings issued vide letter no. F.6/DFS/MS/EH/2016/935 dated 13.04.2016 has been complied.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of Inspecting Officer Name:- M.K. Chattopadhyay

Designation:- Divisional Officer

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer