## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6 DFS/MS/School/2017/SZ/ 1615

Dated: 13/11/17

## FIRE SAFETY CERTIFICATE

Certified that **Basant Gram Adarsh Sanskrit Vidyalaya** located at Shri Prabhu Dutt-Brahmchari Marg, Basant Gaon, Vasant Vihar, New Delhi-110057, comprised of **Ground and One upper floor** owned/occupied by Shri Sankitan Bhawan Trust was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/2014/SZ/1245 dated 26/09/2014. The premises was re-inspected by officer concerned of this department on 16/10/2017 in the presence of Mr. Anirud Prasad Mishra (Principal) of the school and found that said school building have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education circular no. F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by Director of Education, Govt. of NCT of Delhi and that the school building is fit for occupancy class "**Educational Building**" Group-B, with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 13/11/17 at New Delhi by

(Vipin Kental) Chief Fire Officer Ph: 011-23412225

Copy to: -

- 1. The Principal, Basant Gram Adarsh Sanskrit Vidyalaya, Shri Prabhu Dutt Bramchari Marg, Basant Gaon, Vasant Vihar, New Delhi-110057
- 2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

## Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

_	INSPECT	ION REPORT				
1	Name & Address of the Building BASANT GRAM ADARSH SANSKRIT VIDYALAYA,					
*		SHRI PRABHU DUTT BRAHMCHARI MARG, BASANT				
		GAON, VASANT VIHAR, NEW DELHI-110057				
2	Type of Occupancy	Educational Building "Group-B" (School)				
-3	Building Comprised of	Ground plus one upper floor.				
4	Type of Case	Renewal				
5	Details of Previous NOC		ol/2014/SZ/1245 dated			
6	Fire Safety Directives Letter No	F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011				
7	Date of Inspection	16-10-2017				
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)				
9	me & Designation of Officers Mr. Anirud Prasad Mishra (Principal)					
	from the building side	<u> </u>				
10	Year of construction	1976				
11	Applicant letter No.	BGASV/2017/1489 Dt. 23/08/2017				
S.	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remarks		
No	and Fire Safety U/R 33	requirements		MR/NMR		
1	Access to Building.					
	Road width	Required	6 mtr	MR		
	Gate width	-N/A-	-N/A-	-N/A-		
	Width of internal road	-N/A-	-N/A-	-N/A-		
2	Number, width, type & arrangement of exits.					
	a) Number of Staircase					
	Upper floors	Required	Two	MR		
	Basement floor	-N/A-	-N/A-	-N/A-		
	b) Width of Staircase					
	> Upper floors.	1.50m / 0.75m	1.10 & 0.75m	MR (old case)		
	➢ Basement floor	-N/A-	-N/A-	-N/A-		
	c) Protection of exits					
	> Fire check door	-N/A-	-N/A-	-N/A-		
	Pressurization	-N/A-	-N/A-	-N/A-		
	d) No. of continuous staircase to terrace	Required	Two	MR		
	e) Width of corridor	-N/A-	-N/A-	-N/A-		
	f) Door size	1 mtr	Provided	MR		
3	Compartmentation.					
	Fire check door.	-N/A-	-N/A-	-N/A-		
	<ul> <li>Sealing of electrical shafts.</li> </ul>	-N/A-	-N/A-	-N/A-		
	Fire rating of shaft door.	-N/A-	-N/A-	-N/A-		
	Water curtain	-N/A-	-N/A-	-N/A-		
	Fire dampers.	-N/A-	-N/A-	-N/A-		
4.	Smoke Management system.					
	Basement	-N/A-	-N/A-	-N/A-		
	Upper floors	-N/A-	-N/A-	-N/A-		
5			~ ***			
5.	Fire Extinguishers.  • Total numbers	4 Nos	4 Nos	MR		
			ABC-4			
	Types	ABC / Co2		MR		
	ISI Marking	ISI Marked	Provided	MR		
6.	First Aid Hose Reels.					
	Total numbers on each floor.	-N/A-	-N/A-	-N/A-		
	<ul> <li>Length of hose-reel hose.</li> </ul>	-N/A-	-N/A-	-N/A-		
	Nozzle Diameter	-N/A-	-N/A-	-N/A-		
	Basant Gram Adarsh Sanskrit Vidvalava					

Basant Gram Adarsh Sanskrit Vidyalaya, Basant Gaon, Vasant Vihar, New Delhi-57

7	Automatic fire detection & alarming system.	DI/A	-N/A-	-N/A-
	Type of detectors	-N/A-	-N/A-	-N/A-
	Location of Main Panel	-N/A-	-N/A-	-N/A-
	Location of Repeater Panel	-N/A-	-N/A-	-N/A-
	Alternate source of power	-N/A-		-N/A-
`	Hooter's location	-N/A-	-N/A-	
8.	MOEFA / SIREN	-N/A-	-N/A-	-N/A-
9.	Public Address System	-N/A-	-N/A-	-N/A-
10.	Automatic Sprinkler System		77/4	NT/A
	Basement.	-N/A-	-N/A-	-N/A-
D. C.	Upper floors	-N/A-	-N/A-	-N/A-
	Sprinkler above false ceiling	-N/A-	-N/A-	-N/A-
1.	Internal Hydrants.			
	Size of Riser / Down-comer	-N/A-	-N/A-	-N/A-
	<ul> <li>Number of Hydrant per floor</li> </ul>	-N/A-	-N/A-	-N/A-
	Hose box.	-N/A-	-N/A-	-N/A-
2.	Yard Hydrants.			
. 400 0	Total number of hydrants.	-N/A-	-N/A-	-N/A-
	Hose box.	-N/A-	-N/A-	-N/A-
13.	Pumping arrangements.			
10.	Ground Level			
	Discharge of main pump.	-N/A-	-N/A-	-N/A-
	> Head of main pump.	-N/A-	-N/A-	-N/A-
	Number of main pumps.	-N/A-	-N/A-	-N/A-
	> Jockey Pump output.	-N/A-	-N/A-	-N/A-
	> Jockey Pump head.	-N/A-	-N/A-	-N/A-
	> Standby Pump output.	-N/A-	-N/A-	-N/A-
	> Standby Pump head.	-N/A-	-N/A-	-N/A-
	> Auto Starting / Manual Stopping.	-N/A-	-N/A-	-N/A-
	Pump house access.	-N/A-	-N/A-	-N/A-
	Terrace Level			
	Discharge of pump.	-N/A-	-N/A-	-N/A-
	<ul><li>Head of pump.</li></ul>	-N/A-	-N/A-	-N/A-
	> Power supply.	-N/A-	-N/A-	-N/A-
	<ul><li>Auto starting of pump.</li></ul>	-N/A-	-N/A-	-N/A-
14.	Captive water storage for firefighting.	1 1		
14.	Underground tank capacity.	-N/A-	-N/A-	-N/A-
	> Draw-off connection.	-N/A-	-N/A-	-N/A-
	> Fire Service Inlet.	-N/A-	-N/A-	-N/A-
	Access to tank.	-N/A-	-N/A-	-N/A-
	Overhead tank capacity.	-N/A-	-N/A-	-N/A-
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
10.	Pressurization of lift shaft.	-N/A-	-N/A-	-N/A-
		-N/A-	-N/A-	-N/A-
	2 ' ' ' ' ' ' '	-N/A-	-N/A-	-N/A-
		-N/A-	-N/A-	-N/A-
	The second secon	-N/A-	-N/A-	-N/A-
	Lift signage.  Company Separates	-N/A-	-N/A-	-N/A-
17	Standby Power Supply		-14/71	1 1771
18.	Refuge Area	-N/A-	-N/A-	-N/A-
	Total area	-N/A-	-N/A-	-N/A-
	Location		-IN/A-	

Basant Gram Adarsh Sanskrit Vidyalaya, Basant Gaon, Vasant Vihar, New Delhi-57

19.	Fire Control Room.			
	Detector System Panel.	-N/A-	-N/A-	-N/A-
	Flow Switch Panel.	-N/A-	-N/A-	-N/A-
	PA system Panel.	-N/A-	-N/A-	-N/A-
	Battery backup	-N/A-	-N/A-	-N/A-
	Building floor plan	-N/A-	-N/A-	-N/A-
20.	Special Fire Protection System for the Protection of special Risk, if any.	-N/A-	-N/A-	-N/A-

The Fire protection systems provided in the building were checked / operated at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the Directorate of Education circular, FSC issued vide letter No. F.6/DFS/MS/ School/2014/SZ/1245 dated 26-09-2014, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name : R.N. Singh Designation: ADO (BCP)

Başant Gram Adarsh Sanskrit Vidyalaya, Basant Gaon, Vasant Vihar, New Delhi-57

M. SGELL We 6/11

For letter is but up for eign.fal., fury.

CRO/\$ 2

miscell Welli