GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F.6/DFS/MS/School/2017/SZ/

16/9

Dated: .13/!//7

FIRE SAFETY CERTIFICATE

Certified that Real View Public School located at F-532–533, Jaitpur Extension Part-II, Kalindi Kunj Road, Badarpur, New Delhi-110044, comprised of ground plus two upper floors was granted FSC by this department vide letter No. F.6/DFS/MS/School/2014/SZ/609 dated 15/05/2014. The school premises was re-inspected by officer concerned of this department on 13.10.2017 in the presence of Smt. Geeta Chauhan (HOS) and found that said school building have deemed complied with the fire prevention and fire safety arrangements in accordance Directorate of Education circular F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by Director of Education, Govt. of NCT of Delhi and that the building/premises is fit for occupancy class "Educational Building, Group-B" as above with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

(Vipin Kental) Chief Fire Officer Ph: 011-23412225

Copy to: -

- 1. The Chairman, Real View Public School, F-532 & 533, Jaitpur Extn-II, Badarpur, ND-44
- 2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. This Certificate cannot be treated as regularization of unauthorized construction, if any.
- 5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
- 6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

		ON REPORT	TO CONTROL TO FACE	0 522		
1	Name & Address of the Building	REAL VIEW PUB	REAL VIEW PUBLIC SCHOOL, F-532 & 533,			
		Jaitpur Extn-II, Kalindi Kunj Rd, Badarpur, New Delhi				
2	Type of Occupancy	Educational Building "Group-B" (School)				
3	Building Comprised of	Ground + Two upper floors				
4	Type of Case	Renewal F.6/DFS/MS/School/2014/SZ/609 Dated 15/05/2014				
5	Details of Previous NOC					
6	Fire Safety Directives Letter No		nfety/2011/3298 to 3398 date	ed 01.03.2011		
7	Date of Inspection	13-10-2017				
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)				
9	Name & Designation of Officers	Smt. Geeta Chauhan (HOS)				
	from the building side					
10	Year of construction	2013				
11	Applicant letter No.	Nil dated 19/09/2017				
S.	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remarks		
No	and Fire Safety U/R 33	requirements		MR/NMF		
1	Access to Building.			1.00		
	Road width	Required	6 mtr	MR		
	Gate width	Required	3.80 mtr	MR		
	Width of internal road	NA	NA	NA		
2	Number, width, type & arrangement of exits.					
	a) Number of Staircase					
	> Upper floors.	2 No's	2 No's	MR		
	Basement floor.	NA	NA	NA		
	b) Width of Staircase			VI 2		
	> Upper floors	1.50m / 0.75m	1.40m & 1.30m	MR		
	> Basement floor	NA	NA	NA		
	c) Protection of exits		,			
	Fire check door	NA	NA	NA		
	Pressurization	NA	NA	NA		
	d) No. of continuous staircase to terrace	Required	One	MR		
	e) Width of corridor	NA	NA	NA		
	1) Door size	1 mtr	1 mtr	MR		
3	Compartmentation.					
3	Fire check door.	NA	NA	NA		
	Sealing of electrical shafts.	NA	NA	NA		
	• Fire rating of shaft door.	NA	NA	NA		
	Water curtain	NA	NA	NA		
		NA	NA	NA		
_	• Fire dampers.	1471		one.		
4.	Smoke Management system.	30 ACPH	NA	NA		
	Basement	12 ACPH	NA .	NA		
	Upper floors	12 ACI II	1111	1 11 1		
5.	Fire Extinguishers.	08 No's	09 No's	MR		
	Total numbers	ABC / Co2	ABC- 09	MR		
	Types		Provided	MR		
	ISI Marking	Required	riovided	IVIN		
6.	First Aid Hose Reels.		D 1 1	MD		
	 Total numbers on each floor. 	One	Provided	MR		
	 Length of hose-reel hose. 	30 mtr	Provided	MR		
	Nozzle Diameter	5 mm	Provided	MR		

Real View Public School, F-532 & 533, Jaitpur Extn.-II, Kalindi Kunj Road, Badarpur, New Delhi

7	Automatic fire detection & alarming system.			
,	Type of detectors	NA	NA	NA
	Location of Main Panel	NA	NA	NA
	Location of Repeater Panel	NA	NA	NA
	Alternate source of power	NA	NA	NA
	Hooter's location	NA	NA	NA
8.	MOEFA / SIREN	NA	NA	NA
9.	Public Address System	NA	NA	NA
10.	Automatic Sprinkler System			
10.	Basement	NA	NA	NA
	Upper floors	NA	NA	NA
	Sprinkler above false ceiling	NA	NA	NA
11.	Internal Hydrants.			
11.	Size of Riser/Down-comer	NA	NA	NA
	Number of Hydrant per floor	NA	NA	NA
		NA	NA	NA
10		1477	1471	147.1
12.	Yard Hydrants.	NA	NA	NA
	Total number of hydrants.		NA NA	NA
	Hose box.	NA	IVA	INA
13.	Pumping arrangements.			
	Ground Level	NTA I	NT A	NIA
	Discharge of main pump.	NA	NA	NA
	> Head of main pump.	NA	NA NA	NA
	Number of main pumps.	NA	NA	NA
	> Jockey Pump output.	NA	NA	NA
	> Jockey Pump head.	NA	NA	NA
	> Standby Pump output.	NA	NA	NA
	Standby Pump head.Auto Starting / Manual Stopping.	NA	NA	NA
	Auto starting / Manuar Stopping.Pump house access.	NA	NA	NA
	*	NA	NA	NA
	Terrace Level		450 1 D) 1) (D)
	Discharge of pump.	450 LPM	450 LPM	MR
	➤ Head of pump.	40 mtr	40 mtr	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for fire fighting.		271	NI A
	Underground tank capacity.	NA	NA	NA
	> Draw-off connection.	NA	NA	NA
	Fire Service Inlet.	NA	NA	NA
	Access to tank.	NA 10 000 I	NA 10 000 k	NA
	Overhead tank capacity.	10,000 ltrs	10,000 ltrs	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	NTA I	NIA	NIA
	Pressurization of lift shaft.	NA	NA	NA
	Pressurization of lift lobby.	NA	NA	NA
	 Communication in lift car. 	NA	NA	NA
	 Fireman's switch. 	NA	NA	NA
	Lift signage.	NA	NA	NA
17.	Standby Power Supply	Required _	Provided	MR
18.	Refuge Area			
	Total area	NA	NA	NA
	Location	NA	NA	NA

Real View Public School, F-532 & 533, Jaitpur Extn.-II, Kalindi Kunj Road, Badarpur, New Delhi

19.	Fire Control Room.			
	Detector system panel.	NA	NA	NA
	• Flow switch panel.	NA	NA	NA
	PA system panel. Battery backup.	NA	NA	NA
		NA	NA	NA
	Building floor plan.	NA	NA	NA
20.	Special Fire Protection System for the Protection of special Risk, if any.	Required	ABC type fire extinguisher provided near electrical panel	MR

The Fire protection systems provided in the building were checked operated and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/School/2014/SZ/609 dated 15.05.2014, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name

: R.N. Singh Designation: ADO (BCP)

Real View Public School, F-532 & 533, Jaitpur Extn.-II, Kalindi Kunj Road, Badarpur, New Delhi

For fetter is fut up for sign fol fur fur of 1)

M. SCEN VE 10/11