GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/EH/2017/SZ/ 1652

FIRE SAFETY CERTIFICATE

Certified that M/s Pind Balluchi-Grills & Platters (A unit of Classic Hospitality) running at ground floor of building comprised of Basement, Stilt, Ground + three upper floors located at A-3, Pamposh Enclave, Greater Kailash-I (TE Hotel), New Delhi-110048 was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/EH/2014/SZ/1243 dated 26/09/2014. The restaurant premises was re-inspected by the officer concerned of this department on 26/10/2017 in the presence of Mr. Mayank (Manager) and found that said restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class-D "Assembly Building" as above with effect from the date of issue of this certificate for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on 16/l1/l2 at New Delhi by

Chief Fire Officer Tel: 011-23412225

Copy to: -

- 1. The DHO (CZ), South MCD, Health Deptt, Central Zone, Lajpat Nagar, New Delhi-24
- 2. M/s Pind Balluchi- Grills & Platters at GF of A-3, Pamposh Enclave, Greater Kailash-I, New Delhi-110048

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

		ON REPORT			
1	Name & Address of the Building	M/S Pind Balluchi- Grills & Platters, A-3, Gd floor, Pamposh Enclave, Greater Kailash-I, N Delhi-48			
		(A Unit Of Classic Hospitality)			
2	Type of Occupancy	Assembly buildings 'Group-D' (Restaurant)			
3	Building comprised of	Basement, Stilt, Ground + three upper floors.			
4	Type of Case	Renewal			
5	Details of Previous NOC	F.6/DFS/MS/EH/2014/SZ/1243 Dated 26-09-2014			
6	Fire Safety Directives Letter No	Nil			
7	Date of Inspection	26-10-2017			
8	Name of the Inspecting Officers	R.N. Singh ADO (BCP)			
9	Name & Designation of Officers from the building side	Mr. Mayank (Manager)			
10	Year of construction	Restt running at ground floor of the bldg			
11	Applicant letter No.	Nil dated 01.09.2017			
S.	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remarks	
No	and Fire Safety U/R 33	requirement	de de la constant de	MR/NMF	
1	Access to Building.				
	Road width	Required	9 mtr	MR	
	Gate width	N/A	N/A	N/A	
	Width of internal road	N/A	N/A	N/A	
2	Number, width, type & arrangement of exits			V	
	a. Number of Staircase				
	Upper floors	Required	Two	MR	
	Basement floor	N/A	N/A	N/A	
	b. Width of Staircase				
	Upper floors	Required	.28m & 1.50m (Stilt to GF) MR	
	Basement floor	N/A	N/A	N/A	
	c. Protection of exits				
	Fire check door	N/A	N/A	N/A	
	Pressurization	N/A	N/A	N/A	
	d. No. of continuous staircase to terrace	Required	One	MR	
	e. Width of corridor	N/A	N/A	N/A	
	f. Door size	Required	2.0m & 1.5m	MR	
3	Compartmentation.	Required	2.011 & 1.511	IVIIC	
0	Fire check door.	N/A	N/A	N/A	
	Sealing of electrical shafts.	N/A	N/A	N/A	
	Fire rating of shaft door.	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
	and annual transfer to the	N/A	N/A	N/A	
4	• Fire dampers.	14/11	14/11	14/11	
4.	Smoke Management system. Basement	N/A	N/A	N/A	
		N/A	N/A	N/A	
_	• Upper floors	IN/A	IV/A	IN/A	
5.	Fire Extinguishers.	06 N. 1	0/ N. ?-	MD	
	Total numbers	06 No's	06 No's	MR	
	• Types	ABC / Co2	ABC-04, Co-2- 02	MR	
	ISI Marking	ISI marked	Provided	MR	
6.	First Aid Hose Reels.	-		2.40	
	Total numbers on each floor.	One	One	MR	
	Length of hose-reel hose.Nozzle Diameter	30 m 5 mm	30 m 5 mm	MR	
	Nozzle Diameter	1 * *******	\$ 122.122	MR	

M/s Pind Balluchi- Grills & Platters, A-3, GF, Pamposh Enclave, GK-I, New Delhi

				1 2
7	Automatic fire detection & alarming system.	77/4	27/4	1 37/4
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System	77/4	NUA	NT/A
	Basement	N/A	N/A	N/A
	Upper floors	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants.		100) (D
	Size of Riser/Down-comer	Required	100 mm	MR
	 Number of Hydrant per floor 	Required	One	MR
	Hose box.	Required	One	MR
12.	Yard Hydrants.		227	1
	 Total number of hydrants. 	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13.	Pumping arrangements.			
	Ground Level	27/4	NIA	DI/A
	Discharge of main pump.	N/A	N/A	N/A
	> Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A N/A
	> Jockey Pump head.	N/A	N/A	N/A N/A
	Standby Pump output.Standby Pump head.	N/A	N/A N/A	N/A
	Standby Fump head.Auto Starting / Manual Stopping.	N/A N/A	N/A	N/A
		IN/A	IN/A	IN/A
	Terrace Level Discharge of summ	450 LPM	450 LPM	MR
	Discharge of pump.Head of pump.	40m	40m	MR
	Power supply.	Required	Required	MR
	Auto starting of pump.	Required	Required	MR
14.	Captive water storage for Fire Fighting.	Roquitou	Roquirou	IVIIC
A fe	Underground tank capacity.	N/A	N/A	N/A
	Draw-off connection.	N/A	N/A	N/A
	> Fire Service Inlet.	N/A	N/A	N/A
	> Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	10,000 ltrs	10,000 ltrs	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	Pressurization of lift shaft.	N/A	N/A	N/A
	 Pressurization of lift lobby. 	N/A	N/A	N/A
	 Communication in lift car. 	N/A	N/A	N/A
	Fireman's switch.	N/A	N/A	N/A
	Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18.	Refuge Area		-	
	Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A

M/s Pind Balluchi- Grills & Platters, A-3, GF, Pamposh Enclave, GK-I, New Delhi

19.	Fire Control Room.			
17.	 Detector System Panel. Flow Switch Panel. PA system Panel. Battery backup Building floor plan 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection System for the	N/A	N/A	N/A
	Protection of special Risk, if any:			1.0

The Fire protection systems provided in the building were checked /operated at random and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH2014/SZ/1243 dated 26.09.2014, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: R.N. Singh Designation: ADO (BCP)

M/s Pind Balluchi- Grills & Platters, A-3, GF, Pamposh Enclave, GK-I, New Delhi

Ox CACS2)

Whor Fire Oils CAO (S M)

My

FT 61.

Musque

FT 61.

For letter is for signple. huy

CAO (S M)

CAO (S M)

My

CAO (S M)

CAO (S M)

My

CAO (S M)

My

CAO (S M)

CAO (