

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001**

Fax No. 011-23412593, Ph. 011-23412225

No. F.6/DFS/MS/EH/2017/SZ/ 1711

Dated: 30/11/17

FIRE SAFETY CERTIFICATE

Certified that the **Restaurant** located at **Essex Farms Pvt. Ltd., 4, Aurobindo Marg, New Delhi**, running at ground floor of the building comprised of **Ground floor only** was granted FSC by this department vide letter No. F.6/DFS/MS/EH/2014/SZ/1049 dated 21/08/2014. The restaurant premise was re-inspected by the officer concerned of this department on 21-11-2017 in presence of Mr. R.N. Mathur of the restaurant and observed that the said restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class-D "**Assembly Building**" (Restaurant) as above with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 30/11/17 at New Delhi by


(Vipin Kental)
Chief Fire Officer

Copy to: -

1. The DHO, S.D.M.C, Public Health Deptt., South Zone, Green Park, New Delhi-110016
2. The Director, M/s Essex Farms Pvt. Ltd., 4, Aurobindo Marg, New Delhi-110016


Conditions for the validity of Fire Safety Certificate

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of firefighting system.
4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT				
1	Name & Address of the Building	RESTAURANT AT ESSEX FARMS PVT. LTD, No-4, AUROBINDO MARG, NEW DELHI-110016		
2	Type of Occupancy	Assembly buildings 'Group-D'		
3	Building comprised of	Ground floor only		
4	Type of Case	Renewal		
5	Details of Previous NOC	F.6/DFS/MS/EH/2014/SZ/1049 Dated 21-08-2014		
6	Fire Safety Directives Letter No	F.6/DFS/MS/EH/2005/718 dated 04/04/2005		
7	Date of Inspection	21-11-2017		
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. R.N. Mathur (Manager)		
10	Year of construction	Restt running at ground floor of the bldg		
11	Applicant letter No.	Nil dated 12-10-2017		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC requirement	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	• Road width	Required	6 mtr	MR
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2	Number, width, type & arrangement of exits			
	a. Number of Staircase			
	• Upper floors	N/A	N/A	N/A
	• Basement floor	N/A	N/A	N/A
	b. Width of Staircase			
	• Upper floors	N/A	N/A	N/A
	• Basement floor	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d. No. of continuous staircase to terrace	N/A	N/A	N/A
	e. Width of corridor	N/A	N/A	N/A
	f. Door size	1.55 & 1.05m	Provided	MR
3	Compartmentation.			
	• Fire check door.	N/A	N/A	N/A
	• Sealing of electrical shafts.	N/A	N/A	N/A
	• Fire rating of shaft door.	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire dampers.	N/A	N/A	N/A
4.	Smoke Management system.			
	• Basement	N/A	N/A	N/A
	• Upper floors / Ground floor	Required	Exhaust fans Provided	MR
5.	Fire Extinguishers.			
	• Total numbers	07 No's	07 No's	MR
	• Types	ABC / Co2	ABC-05, Co2-02	MR
	• ISI Marking	ISI marked	Provided	MR
6.	First Aid Hose Reels.			
	• Total numbers on each floor.	One	One	MR
	• Length of hose-reel hose.	30 m	30 m	MR
	• Nozzle Diameter	5 mm	5 mm	MR

Restaurant at Essex Farms Pvt Ltd, No.4, Aurobindo Marg, New Delhi

7	Automatic fire detection & alarming system.		N/A	N/A	N/A
		• Type of detectors	N/A	N/A	N/A
		• Location of Main Panel	N/A	N/A	N/A
		• Location of Repeater Panel	N/A	N/A	N/A
		• Alternate source of power	N/A	N/A	N/A
	• Hooter's location	N/A	N/A	N/A	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	N/A	N/A	N/A	
10.	Automatic Sprinkler System				
	• Basement	N/A	N/A	N/A	
	• Upper floors	N/A	N/A	N/A	
	• Sprinkler above false ceiling	N/A	N/A	N/A	
11.	Internal Hydrants.				
	• Size of Riser/Down-comer	N/A	N/A	N/A	
	• Number of Hydrant per floor	N/A	N/A	N/A	
	• Hose box.	N/A	N/A	N/A	
12.	Yard Hydrants.				
	• Total number of hydrants.	N/A	N/A	N/A	
	• Hose box.	N/A	N/A	N/A	
13.	Pumping arrangements.				
	• Ground Level				
	➤ Discharge of main pump.	225 LPM	900 LPM	MR	
	➤ Head of main pump.	28 mtr	28 mtr	MR	
	➤ Number of main pumps.	One	One	MR	
	➤ Jockey Pump output.	N/A	180 LPM	N/A	
	➤ Jockey Pump head.	N/A	28 mtr	N/A	
	➤ Standby Pump output.	N/A	N/A	N/A	
	➤ Standby Pump head.	N/A	N/A	N/A	
	➤ Auto Starting / Manual Stopping.	N/A	N/A	N/A	
	• Terrace Level				
	➤ Discharge of pump.	N/A	N/A	N/A	
	➤ Head of pump.	N/A	N/A	N/A	
	➤ Power supply.	N/A	N/A	N/A	
	➤ Auto starting of pump.	N/A	N/A	N/A	
14.	Captive water storage for Fire Fighting.				
	• Underground tank capacity.	N/A	N/A	N/A	
	➤ Draw-off connection.	N/A	N/A	N/A	
	➤ Fire Service Inlet.	N/A	N/A	N/A	
	➤ Access to tank.	N/A	N/A	N/A	
	• Overhead tank capacity.	2,500 ltrs	10,000 ltrs	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.				
	• Pressurization of lift shaft.	N/A	N/A	N/A	
	• Pressurization of lift lobby.	N/A	N/A	N/A	
	• Communication in lift car.	N/A	N/A	N/A	
	• Fireman's switch.	N/A	N/A	N/A	
	• Lift signage.	N/A	N/A	N/A	
17	Standby Power Supply	Required	Provided	MR	
18.	Refuge Area				
	• Total area	N/A	N/A	N/A	
	• Location	N/A	N/A	N/A	

19.	Fire Control Room.	N/A	N/A	N/A
	• Detector System Panel.	N/A	N/A	N/A
	• Flow Switch Panel.	N/A	N/A	N/A
	• PA system Panel.	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any :	N/A	N/A	N/A
<p>The Fire protection systems provided in the building were checked /operated and found functional at the time of inspection. Shortcomings communicated earlier vide letter dated 20.09.2017 have been complied.</p> <p>Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/DFS/MS/EH2014/SZ/1049 dated 21.08.2014, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.</p> <p>Accordingly, DFA is put up for approval and signature please.</p> <div style="text-align: right;">  Signature of the Inspecting Officer Name : R.N. Singh Designation: ADO (BCP) </div>				

Restaurant at Essex Farms Pvt Ltd, No. 4, Aurobindo Marg, New Delhi

DO (SD)

[Signature]
23/11/17

1403/cfo 82

27/11, 30/11

[Signature]
CFO (S2)



CFO (S2)

[Signature]
23/11

M. S. Pell *[Signature]*
24/11

FT to Her is put up for sign-ple.
[Signature]
27/11

M. S. Pell *[Signature]*
29/11