GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No.F6/DFS/MS/School/2017/NDZ/ | 7 6

Dated: 8 /12/17

FIRE SAFETY CERTIFICATE

Certified that the S.R. DAV Public School (Nursery Wing only) Dayanand Vihar, Delhi, owned/occupied by S.R.DAV Public School, Comprised of ground plus two upper floors was granted FSC vide letter F6/DFS/MS/School/2011/488 dated-15/03/11. The school building was inspected by the officer concerned of this department on 15/11/17 in the presence of Mrs. Dhenu Narang (Incharge) of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the NBC Part-IV and ground plus two floors (Nursery Wing only) of building is fit for occupancy class B "Educational Building" with effect from 8/12/17 for a period of three years, subject to conditions printed overleaf.

Issued on 8 1217 at New Delhi by

(Vipin Kental)
Chief Fire Officer
Delhi Fire Service

Copy to:-

- 1 The Director of Education, Old secretariat ,Delhi-54.
- 2. The Incharge, S.R. DAV Public School (Nursery Wing only) Dayanand Vihar, Delhi.

- Conditions -

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in good working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction if any.
- 6. "The owner /occupier shall apply for renewal of this Fire Safety certificate to the Director inform'J'[sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

1.Name & address of the building :S.R.DAV Public School Dayanand Vihar, Delhi.
 2. Building is comprised of : Ground +2 upper floor

3. Type of Occupancy : Educational

4. Type of Case : Renewal

5. Details of Previous FSC : F6/DFS/MS/School/2011/488 dated-15/03/11

6. Fire Safety direction letter No : NBC Part IV

7. Date of Inspection : 15/11/17

8. Name of the Inspecting Officers: : ADO R.K. Yadav

9. Name of the designation of Officer

from the building side : Mrs. Dhenu Narang (Incharge)

10. Year of Construction :

11. /	Applicant's letter No.	: SRDAV/PS/E	0V/874 dated 30/10/	17		
S. N o	Minimum Standards on fire safety requirements as per	Requirement	Provided at Site	Remarks MR/NMR		
1.	Access to building					
	Road width	6 m	6 m	MR		
1	Gate width	N.A	N.A	N.A		
	Width of internal road	N.A	N.A	N.A		
	Number, Width, Type and Arrangement of Exits					
	a. Number of Staircases					
	Upper Floor	2 no.	2 no.	MR		
	Basement	N.A	N.A	N.A		
	b. Width of Staircases					
	Upper FloorBasement	1.5 m	1.50 m each	MR		
	c. Protection of exits	N.A	N.A	N.A		
,	Fire check door	N.A	N.A	N.A		
	Pressurization	N.A	N.A	, N.A		
	d. No. of continuous staircases to terrace	1 no.	1 no.	MR		
1	e. Width of Corridor	1.5 m	1.5 m	MR		
	f. Door Size	1 m	1 m .	MR		
	Compartmentation.	2				
	Fire check door	N.A	N.A	N.A		
1	Sealing of electrical shafts	N.A	N.A	N.A		
	Fire rating of shaft door	N.A	N.A	N.A		
	Water curtain Fire Dampers	N.A	N.A	N.A		
	·	N.A	N.A	N.A		
	Smoke Management System.					
- 1	Basement	N.A	N.A	N.A		
	Jpper floor	N.A	N.A	N.A		
	Fire Extinguisher	J				
- 1	Total numbers	8 no.	Provided	MR		
1	Г <mark>уреѕ</mark>	CO ₂ & ABC	Provided	MŔ		
13	SI marking	ISI marked	Provided	MR		

C	First aid Harr Dark	l s		75.			
6	First-aid-Hose Reels.						
	Total numbers of each floor	01 no.	Provided	MR			
	Length of hose reel hose Nozzle diameter	30 m	Provided	MR			
	I SANDANIA MARINA MARIN	5 mm	Provided	MR			
7	Automatic fire detection and alarming system.						
	Type of detectors	N.A	N.A	N.A			
	Location of main panel	N.A	N.A	N.A			
	Location of repeater panel	N.A	N.A	N.A			
	Alternate source of power	N.A	N.A	N.A			
	Hooters	N.A	Provided	MR			
8	MOEFA	N.A	N.A.	N.A.			
9	Public address System.	Required	Provided	MR			
10	Automatic Sprinkler System.	rtequired	TTOVIGEG	IVIIX			
	Basement	N.A	N.A	N.A			
	upper floor	N.A	N.A	N.A			
	sprinkler above false ceiling						
11		N.A	N.A	N.A			
11	Internal Hydrants	NI A					
	size of riser/down-comer	N.A	N.A	N.A			
	Number of hydrants per floor Hose Box	N.A	N.A	N.A			
10		N.A	N.A	N.A			
12	Yard Hydrants.						
	Total number of hydrants	N.A	N.A	N.A			
	Hose Box	N.A	N.A	N.A			
13	Pumping Arrangements.						
	Ground Level	N.A	N.A	N.A			
	Discharge of main Pump	N.A	N.A	N.A			
	Head of Main Pump	N.A	N.A	N.A			
	Number of main pumps	N.A	N.A	N.A			
	Jockey pump out put	N.A	N.A	N.A			
	> Jockey pump head	N.A	N.A	N.A			
	Standby pump out put	N.A	N.A	N.A			
	> Standby pump Head	N.A	N.A	N.A			
	Auto Starting /Manual stopping	N.A	N.A	N.A			
	Pump House Access	N.A	N.A	N.A			
	Terrace Level						
	Discharge of pump	450 LPM	Provided	MR			
	Head of the Pump	40 m	Provided	MR			
	Power supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for Fire Fighting.						
	Underground tank capacity	N.A	N.A	N.A			
	Draw-off connection	N.A	N.A	N.A			
	Fire service inlet	N.A	N.A	N.A			
	Access to tank	N.A	N.A	N.A			
	Overhead Tank capacity			MR			
15	Exit Signage			MR			
15	Exit Signage.	10,000 liters Required	Provided Provided				

16	Provision of Lifts.			
	Pressurization of Lift Shaft	N.A	N.A	N.A
	Pressurization of Lift lobby Communication in lift car Firemen's grounding switch Lift Signage	N.A	N.A	N.A
		N.A	N.A	N.A
		N.A	N.A	N.A
		N.A	N.A	N.A
17	Standby power supply	N.A	N.A	N.A
18	Refuge Area.			
	Total area Location	N.A	N.A	N.A
		N.Ä	N.A	N.A
19	Fire Control Room			\ ,
	Detector system panel	N.A	N.A	N.A
	Flow switch panel PA system panel Batter backup Building Floor Plans	N.A	N.A	N.A
		N.A	N.A	N.A
		N.A	N.A	N.A
		N.A	N.A	N.A
20	Special Fire Protection systems for protection of special Risks, if any:	N.A	N.A	N.A

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules. The FSC issued vide letter no. F6/DFS/MS/School/2011/488 dated-15/03/11 renewal under the NBC Part-IV is recommended to grant Fire Safety Certificate.

Signature of the Inspecting Office 1 202

Name :- R. K. Yadav Designation: - ADO (LN)

submitted for approval pleau.

DYCFOLMOY M. 21/1×1'

Shy IT helter as fut up. for sign plans