GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2017/SZ

Dated: 08 12 2017

FIRE SAFETY CERTIFICATE

Certified that the **B.V.M World School,** Aggarwal Dharamshala Road, Opp. Police Station, Prem Nagar, Najafgarh, New Delhi-110043 comprised of basement, ground plus two upper floors, but school is running at ground plus one upper floor only owned/occupied by B.V.M World School was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/2014/SZ/1027 dated 13.08.2014. The school building was reinspected by the officer concerned of this department on 16.11.2017 in the presence of Sh. Ajay Sharma (Manager) and found that the B.V.M World School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on 08 12 2017 at New Delhi.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

- The Managing Director,
 B.V.M World School, Aggarwal Dharamshala Road,
 Opp. Police Station, Prem Nagar, Najafgarh, New Delhi-110043
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. Basement shall not be used for any purpose & kept vacant

Building is Comprised of basement, ground plus two upper floors but school is running at Ground plus one upper floor. INSPECTION REPORT 1. Name & address of the building: B.V.M World School, Aggarwal Dharamshala Road, Opp. Police Station, Prem Nagar, Najafgarh, New Delhi-110043 Type of Occupancy Educational 3. Type of Case Renewal 4. Details of Previous NOC F.6/DFS/MS/School/2014/SZ/1027 dated 13.08.2014 5. Fire Safety directives letter No Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection 16.11.2017 7. Name of Inspecting Officer A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side Sh. Ajay Sharma (Manager) 9. Year of Construction 2013 10. Applicant's letter No. BVMWS/083 dated 04.09.2017 Minimum Standards on fire prevention and S. No. Requirement Provided at Remarks fire safety U/R 33 as per FSC dt. site MR/NMR 13.08.2014 1. Access to building Road width Accessible 06 mtrs 6.4 mtrs MR 4.5 mtrs Gate width Directly accessible M/R N/A from road Width of internal road N/A N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 01 no. 02 no.'s MR Basements N/A N/A N/A, school is running at GF & FF only b. Width of staircases Upper Floor 150 cms 150 & 120 cms MR Basements N/A N/A, school is running at GF N/A & FF only c. Protection of exits Fire check door Required Provided MR Pressurization N/A N/A N/A d. No. of continuous staircases to N/A One N/A terrace 150 cms 205 cms MR Width of Corridor f. Door Size 100 cms MR, students less 110 cms than 45 in each class 3. Compartmentation Fire check door N/A N/A N/A, school is running at GF & FF only Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain Fire Dampers N/A N/A N/A N/A N/A N/A 4. Smoke Management System Basements Required Exhaust fans MR are provided Upper floors Required Natural Ventilation MR provided 5. Fire Extinguishers Total numbers 08 No's Provided MR **Types** ABC/CO₂ type Provided MR ISI marked IS marking ISI marked MR **First-Aid Hose Reels** 6. Total numbers on each floor N/A N/A N/A I anoth of home most he

7.	Automatic fire detection and alarming system	the unique stay as	9.20 OSHQUAN 1.8 d	
	Type of detectors	N/A	N/A	N/A
Part F. Iv	Location of Main Panel	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
-	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
				27/4
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System	LI TETE		
	Basement	N/A	Provided	N/A, school is running at GF & FF only
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	Size of riser/down-comer	N/A	N/A	N/A
	 Number of hydrants per floor 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	Ground Level	The state of the s		<u> </u>
122	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pumpNumber of main pumps	N/A	N/A	N/A
	Number of main pumpsJockey Pump out put	N/A	N/A	N/A
* 1	> Jockey pump head	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A N/A	N/A N/A	N/A N/A
	Pump House Access	IVA	IVA	17/11
	Terrace level	27/4	450 LPM provide	d NI/A
	Discharge of pump	N/A	40 mtrs provided	d N/A N/A
	Head of the pumpPower Supply	N/A N/A	Provided Provided	N/A N/A
	> Auto Starting of pump	N/A N/A	Provided	N/A
	Tuto Starting of partip	IVA	Tiovided	14/71
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
-	> Draw-off connection	N/A	N/A	N/A
	> Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	5000 ltrs prov	ided N/A
15.	Exit Signage.	N/A	N/A	N/A
16.	Provision of Lifts.			(Lift not in use)
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A N/A	N/A N/A	N/A
	Fireman's Grounding Switch			
	Lift Signage	N/A	N/A	N/A
		N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.		global osali in A.	
1947	> Total Area	N/A	N/A	N/A
449	> Location	DT/A	DI/A	NT/A

2)8

is running at Gloui

19.	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	 Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number <u>F.6/DFS/MS/School/2014/SZ/1027</u> dated <u>13.08.2014</u> renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

795/20/80

Divisional Officer (South West)

Alar (south west)

DCFO(SZ)

M

carl 21/4

r-scell FT to

28/11

F.T. letter is put up for signature please.

1447/cf 52