GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2017/SZ 1772

FIRE SAFETY CERTIFICATE

Dated: 08 12 2017

Certified that Sarvodaya Kanya Vidyalaya, D-Block, Janakpuri, New Delhi-110058 comprised of ground plus one upper floor owned/occupied by Govt. of NCT of Delhi having Admn. Wing, Sr. Wing plus SPS Wing was issued FSC by this department vide letter No F.6/DFS/MS/School/2014/SZ/1588 dated 15.12.2014. The school has added one more block comprised of ground floor plus one upper floor of SSA (Sarv Shiksha Abhiyan). The premise was inspected by the officer concerned of this department on 11.10.2017 in the presence of Smt. Sneh Sabarwal (H.O.S) and found to have deem complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on 08.12.2017 at New Delhi.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- The Principal,
 Sarvodaya Kanya Vidyalaya,
 D-Block, Janakpuri, New Delhi-110058
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

having ground plus one upper floor.

INSPECTION REPORT

1. Name & address of the building: Sarvodaya Kanya Vidyalaya, D-Block, Janakpuri, New Delhi-110058.

2. Type of Occupancy : Educational3. Type of Case : Renewal/New

4. Details of Previous NOC : F.6/DFS/MS/School/2014/SZ/1588 dated 15.12.2014. (for AW, SW & SPS)
5. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

6. Date of inspection : 11.10.2017

7. Name of Inspecting Officer : A.D.O. Sandeep Duggal

8. Name and designation of officers

From the building side : Smt. Sneh Sabarwal (H.O.S)

9. Year of Construction : Admn. & Sr. Wing (Before 2006), SPS Wing (Before 2011) & SSA (2017)

10. Applicant's letter No. : 1870 dated 04.9.2017

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as p FSC dt. 15.12.201 circular dt. 01.03.	4/ at site	Remarks MR/NMR			
1.	Access to building	circular ut. 01.03	2011				
	 Road width Gate width Width of internal road 	Accessible (06 mt 4.5 mtrs N/A	09 mtrs 5.8 & 3.5mtrs N/A	MR MR N/A			
2.	Number, Width, Type & Arrangement of E	xits		11, 1 215			
	a. Number of staircasesUpper FloorsBasements	AW-01 no., SW- no.'s, SPS-03 no & 01 no. in SS.	.'s	MR			
		N/A	N/A	N/A			
	b. Width of staircasesUpper FloorBasements	150 cms/addition staircase of 75 c if less than 150 c	ms 137 cms in SW & 140, 142 cms in SP 170 cms in SSA	180, S &			
		N/A	N/A	N/A			
	c. Protection of exitsFire check doorPressurization	N/A N/A	N/A N/A	N/A N/A			
	d. No. of continuous staircases to terrace	N/A	Three	N/A			
	e. Width of Corridor	150 cms	180 to 170 cms	MR			
	f. Door Size	100 cms	95 to 105 cms. (double door) few class rooms ha single door & 119 & 8 cms (double door in SS	ave case			
3.	Compartmentation	A. J.					
	Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	N/A	N/A			
	Fire Rating of shaft door	N/A	N/A	N/A			
	Water Curtain	N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System						
	Basements	N/A	N/A	N/A			
	Upper floors	Required	Natural Ventilation	MR			
5.	Fire Extinguishers						
	Total numbers	30 No's	Provided	MR			
	• Types	ABC/CO ₂ typ	e Provided	MR			
	IS marking	ISI marked	ISI marked	MR			
6.	First-Aid Hose Reels						
1141	Total numbers on each floor	N/A	N/A	N/A			
	• Length of hose reel hose	N/A	N/A	N/A			

	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
		N/A	N/A	N/A
# E = 1	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System			
	Basement	N/A	N/A	N/A
4		Location of Main Panel	N/A	
44		N/A	N/A	N/A
11.		DI/A	DT/A	27/4
				N/A
12.	Yard Hydrants	11/11	14/71	14/11
		N/A	N/A	N/A
			The state of the s	N/A
13.	Pumping Arrangements	1 6 6 6 6		
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
		N/A	N/A	N/A
-		N/A	N/A	N/A
		N/A	N/A	N/A
1	> Standby Pump out put	N/A	N/A	N/A
		The second secon	The same of the sa	N/A
	Auto Starting/Manual Stopping			N/A
				N/A
	Dumm II			N/A
			/ / / / / / / / / / / / / / / / / / /	
	The second secon	N/A	N/A	N/A
				N/A
	> Power Supply			N/A
	Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting			
		N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
1		N/A	N/A	N/A
				N/A
	Overneau Tank capacity	N/A	N/A	N/A
15.	Exit Signage.	N/A	N/A	N/A
16.	Provision of Lifts.	4		(No Lift)
	A CONTRACTOR OF THE CONTRACTOR	N/A	N/A	N/A
		N/A	N/A	N/A
				N/A
		N/A	N/A	N/A
	Lift Signage			N/A
17.	Standby nawar supply			
17.	Standby power supply	N/A	IN/A	IV/A
18.	Refuge Area.			
	> Total Area	N/A	N/A	N/A
A STATE OF	Location	N/A	N/A	N/A

19.	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2014/SZ/1588 dated 15.12.2014 for Admn. Wing, Sr. Wing & SPS Wing renewal/new in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note:- As per the letter submitted by the H.O.S (placed at C-24) four rooms constructed under SSA Block are not being used as class rooms.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

Sander

Divisional Officer (South West)

CFO CPH + How many students are there is one class som doors in new class room.