GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

No. F.6/DFS/MS/EH/2017/SZ/ 1753

Dated: 1.2./1.7./1.7

FIRE SAFETY CERTIFICATE

Certified that the Restaurant in the name of M/s Theobroma Foods Private Limited, located at 1st floor, Select City Walk, District Centre, Saket, New Delhi, building comprised of 3 tier basement, Ground plus seven upper floors was inspected by the officer concerned of this department on 07/11/2017 in the presence of Mr. Balwinder (Manager) of the restaurant and observed that the said restaurant premise have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class-D "Assembly" as above with effect from the date of issue of this certificate for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issûed on 12/12/12 at New Delhi by

(Vipin Kental)

Chief Fire Officer

Copy to: -

- 1. The DHO (SZ), South MCD, Public Health Deptt, Green Park, New Delhi-110016
- 2. Authorized Signatory, M/s Theobroma Foods Pvt. Ltd., 1st Floor, Select City Walk, District Centre, Saket, New Delhi-110017

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."
- 7. This FSC will become null & void, if the FSC of the main premise is not renewed under Rule 37 or cancelled under Rule 40 of DFS Rules-2010

- Total	INSPECTION REPORT					
1	Name & Address of the Building	CARLOW THE REAL PROPERTY OF THE PARTY OF THE	Foods Private Limited, F	-62, First		
	Traine de Francisco de anomalia	floor, Select City Walk, Distt. Centre, Saket, N Delhi				
2	Type of Occupancy	Assembly Building "Group-D" Restaurant				
3	Building Comprised of	3 Tier Basement, Ground + 07 upper floors				
4	Type of Case	New				
5	Details of Previous NOC	Nil				
6	Fire Safety Directives Letter No	Nil				
7	Date of Inspection	07-11-2017				
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)				
9	Name & Designation of Officers	Mr. Balwinder (
	from the building side					
10	Year of construction		ated at 1st floor of Mall buil			
11	Applicant letter No.	Nil Dt. 09/10/2017, ODD No. 12775 Dt. 17.10.2017				
S. No.	Minimum standards on Fire Prevention	NBC/BBL	Provided at Site	Remarks		
	and Fire Safety U/R 33	requirement		MR/NMR		
1	Access to Building.		all/SZ/2015/SZ/232 Dated			
	Road width	Restt. within	As above	MR		
	Gate width	mall bldg.	N/A	N/A		
	Width of internal road		N/A	N/A		
2	Number, width, type & arrangement of exits.	Provided & Maintained by Select City Walk Mall				
	a. Number of Staircase	75 44 241 1	3 3	MD		
Table 1	Upper floors	Restt within mal		MR		
	Basement floor	N/A	As above	N/A		
	b. Width of Staircase	Provided & Maintained by Select City Walk Mall				
	Upper floors	Restt within mal		MR		
	Basement floor	N/A	As above	N/A		
	c. Protection of exits	Provided & Maintained by Select City Walk Mall				
	Fire check door	N/A	As above	MR		
	Pressurization	N/A	As above	N/A		
	d. No. of continuous staircase to terrace	Required	As above	MR		
	e. Width of corridor	N/A	N/A	N/A		
-	f. Door size	Required	Open space	MR		
3	Compartmentation.	The state of the s	intained by Select City			
NIS-BARRET	Fire check door.	N/A	As above	N/A		
TARREST OF THE PARTY OF THE PAR	Sealing of electrical shafts.	N/A	As above	N/A		
Special Page 1	• Fire rating of shaft door.	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
4	• Fire dampers.	N/A	N/A	N/A		
4.	Smoke Management system.		intained by Select City	The same of the sa		
	Basement	N/A	As above	N/A		
	Upper floors	Required	Exhaust fans provided	MR		
5.	Fire Extinguishers.	421.3	ANTA	MD		
	Total numbers	4 No's	4 No's	MR		
On the special services	Types	ABC / Co2	ABC-02, .Co2-02	MR		
	ISI Marking	ISI marked	Provided	MR		
6.	First Aid Hose Reels.	Provided & Maintained by Select City Walk Mall				
	Total numbers on each floor.	One	Provided near Restt.	MR		
	 Length of hose-reel hose. 	30 m 💌	30 m	MR		
		5 mm	5 mm	MR		

7	Automatic fire detection & alarming system.	Provided & Ma	aintained by Select City	Walk Mal	
	Type of detectors	Required	Smoke & Heat	MR	
	 Location of Main Panel 	Required	As above	MR	
	 Location of Repeater Panel 	N/A	N/A	N/A	
	 Alternate source of power 	Required	As above	MR	
	 Hooter's location 	Required	As above	MR	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	N/A	N/A	N/A	
10.	Automatic Sprinkler System	Provided & Maintained by Select City Walk Mal			
	Basement	N/A	As above	N/A	
	Upper floors	Required	Provided	MR	
	 Sprinkler above false ceiling 	N/A	N/A	N/A	
11.	Internal Hydrants.	Provided & Ma	intained by Select City	Walk Ma	
	Size of Riser/Down-comer	N/A	As above	N/A	
	 Number of Hydrant per floor 	N/A	As above	N/A	
W	 Hose box. 	N/A	As above	N/A	
12.	Yard Hydrants.	Provided & Maintained by Select City Walk Mal			
	 Total number of hydrants. 	N/A	As above	N/A	
	Hose box.	N/A	As above	N/A	
13.	Pumping arrangements.			1 17/11	
	Ground Level	Provided & Maintained by Select City Walk Mall			
	Discharge of main pump.	N/A	2280 LPM	N/A	
	➤ Head of main pump.	N/A	60 mtr	N/A	
	Number of main pumps.	N/A	One	N/A	
	Jockey Pump output.	N/A	180 LPM	N/A	
	Jockey Pump head.	N/A	60 mtr	N/A	
	Standby Pump output.	N/A	2280 LPM	N/A	
	Standby Pump head.	N/A	60 mtr	N/A	
	Auto Starting / Manual Stopping.	N/A	Provided	N/A	
	Access to pump house	N/A	Provided	N/A	
	Terrace Level	Provided & Mai	intained by Select City		
	Discharge of pump.	450 LPM	As above	MR	
	Head of pump.	40 m	As above	MR	
	Power supply.	Required	As above	MR	
and described the state of the	Auto starting of pump.	Required	As above	MR	
14.	Captive water storage for Fire Fighting.	Provided & Maintained by Select City Walk Mall			
	 Underground tank capacity. 	N/A	1,00,000 ltrs	N/A	
	Draw-off connection.	N/A	As above	N/A	
	Fire Service Inlet.	N/A	As above	N/A	
	Access to tank.	N/A	As above	N/A	
	Overhead tank capacity.	5,000 Ltr	As above	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.	Provided & Maintained by Select City Walk Mal			
	 Pressurization of lift shaft. 	N/A	As above	N/A	
	 Pressurization of lift lobby. 	N/A	As above	N/A	
9	 Communication in lift car. 	N/A	As above	N/A	
	Fireman's switch.	N/A	As above	N/A	
	Lift signage.	N/A	As above	N/A	
17	Standby Power Supply	Required	As above	MR	
18.	Refuge Area		110 40010	TATIK	
	Total area	N/A	N/A	N/A	

19.	Detector System Panel. Flow Switch Panel.	Provided & Maintained by Select City Walk Mal		
		N/A	As above	N/A
The state of the s		N/A	As above	N/A
		N/A	As above	N/A
	PA system Panel.	N/A	As above	N/A
1	Battery backup	N/A	As above	N/A
	Building floor plan Special Fire Protection System for the	N/A	As above	N/A
20.	Protection of special Risk, if any:		1 aver hard water stor	age tank f

Restaurant is located at 1st floor of mall building. Underground, over-head water storage tank, fire pumps, hose-reels, means of escape, automatic detection system, fire control room etc. are provided and maintained by mall management. The fire safety arrangements provided therein are common for entire building

The Fire protection systems provided in the building were checked / operated and found functional at the time of inspection.

Keeping in view the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

: R.N. Singh Name Designation: ADO (BCP)

fut apoith Mall FSC. DO (SD) Sprepen PSC és placed et e/5.

Mala

1. What's the approved use of First proc.
in the mall.
2. If the restamant is an open area