GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

No. F.6/DFS/MS/School/2017/SZ/ 1814

Dated: .1.5.../1.2./.17

FIRE SAFETY CERTIFICATE

Certified that **Bantam Elementary School** located at **Village Rangpuri**, **New Delhi-110037**, comprised of **Ground + two upper floors**, but school is running at ground and 1st floor & two servant quarters at 2nd floor was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/2014/SZ/498 dated 22/04/2014. The school premises was re-inspected by officer concerned of this department on 29/11/2017 in presence of Sh. Kamal Kishor (Manager) and found that said school building have deemed complied with the fire prevention and fire safety arrangements in accordance with Directorate of Education circular No. 262–362 dated 17-01-2005 issued by Director of Education, Govt. of NCT of Delhi and that the building/premises is fit for occupancy class **"Educational Building, Group-B"** as above with effect from the date of issue of this certificate for a period of **Three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

(Vipin Kental)
Chief Fire Officer

Copy to: -

1. The Manager, Bantam Elementary School, Village Rangpuri, New Delhi- 110037

2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	INSPECTION REPORT				
1	Name & Address of the Building	BANTAM ELEMENTRY SCHOOL, VILLAGE			
		RANGPURI, NEW DELHI- 110037			
2	Type of Occupancy	Educational Building, Group-B			
3	Building Comprised of	Ground + two upper floors			
4	Type of Case	Renewal			
5	Details of Previous NOC	F.6/DFS/MS/School/2014/SZ/498 Dated 22/04/2014			
6	Fire Safety Directives Letter No	DOE circular No	262-362 dated 17/01/20	005	
7	Date of Inspection	29-11-2017			
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)			
9	Name & Designation of Officers from the building side	Sh. Kamal Kishor (Manager)			
10	Year of construction	2007 School is running at ground & 1 st floor only			
11	Applicant letter No.	BES/9/17-18 dated 10/11/2017			
S.	Minimum standards on Fire Prevention	Old NOC Provided at Site Remarks			
No	and Fire Safety U/R 33	requirements		MR/NMR	
1	Access to Building.				
	Road width	Required	6 mtr	MR	
	Gate width	-NA-	-NA-	-NA-	
	Width of internal road	-NA-	-NA-	-NA-	
2	Number, width, type & arrangement of exits.				
	a) Number of Staircase				
	> Upper floors.	Required	2 No's	MR	
	➤ Basement floor.	-NA-	-NA-	-NA-	
	b) Width of Staircase	1771	-1471-	-14/1-	
	> Upper floors	Doguinad	1.20m each	MR	
	Basement floor	Required			
		-NA-	-NA-	-NA-	
	c) Protection of exits				
	Fire check door	-NA-	-NA-	-NA-	
	> Pressurization	-NA-	-NA-	-NA-	
	d) No. of continuous staircase to terrace	Required	One	MR	
	e) Width of corridor	-NA-	-NA-	-NA-	
	f) Door size	1 mtr	Provided	MR	
3	Compartmentation.				
	Fire check door.	-NA-	-NA-	-NA-	
	 Sealing of electrical shafts. 	-NA-	-NA-	-NA-	
	 Fire rating of shaft door. 	-NA-	-NA-	-NA-	
	Water curtain	-NA-	-NA-	-NA-	
	Fire dampers.	-NA-	-NA-	-NA-	
4.	Smoke Management system.				
	Basement	-NA-	-NA-	-NA-	
	Upper floors	-NA-	Open corridor	-NA-	
5.	Fire Extinguishers.				
	Total numbers	Required	10 No's	MR	
	Types	ABC / Co2	ABC- 08, Co2- 02	MR	
	ISI Marking	Required	Provided	MR	
6.	First Aid Hose Reels.			I TYAIL	
0.	Total numbers on each floor.	-NA-	One	-NA-	
	Length of hose-reel hose.	-NA-	30 mtr	-NA-	
	Nozzle Diameter Bantam Flementary School	-NA-	5 mm	-NA-	

Bantam Elementary School at Village Rangpuri, New Delhi

	-NA-	-NA-	-NA-
- 1			-NA-
			-NA-
			-NA-
-			-NA-
			-NA-
			-NA-
	-NA-	-INA-	-INA-
	NIA	NA	-NA-
			-NA-
* *			-NA-
	-NA-	-INA-	-14/4-
	NIA	NIA	-NA-
			-NA-
	-NA-	-NA-	-NA-
	37.4	3.7.4	NTA.
			-NA-
Hose box.	-NA-	-NA-	-NA-
Pumping arrangements.			
Ground Level			
Discharge of main pump.	-NA-		-NA-
Head of main pump.			-NA-
	-NA-		-NA-
	-NA-		-NA-
	-NA-		-NA-
			-NA-
			-NA-
			-NA-
±	-NA-	-NA-	-NA-
Terrace Level	T		
Discharge of pump.			-NA-
Head of pump.			-NA-
			-NA-
	-NA-	Provided	-NA-
Captive water storage for fire fighting.	1		
 Underground tank capacity. 			-NA-
Draw-off connection.			-NA-
CONTRACTOR OF THE PROPERTY OF			-NA-
and the second s			-NA-
			-NA-
Exit Signage.	Required	Provided	MR
	N. C.	* * *	7.74
			-NA-
Pressurization of lift lobby.			-NA-
Communication in lift car.			-NA-
Fireman's switch.	-NA-	-NA-	-NA-
	-NA-	-NA-	-NA-
Lift signage.			
Lift signage. Standby Power Supply	-NA-	-NA-	-NA-
	-NA-		
Standby Power Supply	-NA-	-NA-	-NA-
	 Number of Hydrant per floor Hose box. Total number of hydrants. Hose box. Pumping arrangements. Ground Level Discharge of main pump. Head of main pumps. Jockey Pump output. Jockey Pump head. Standby Pump output. Standby Pump head. Auto Starting / Manual Stopping. Pump house access. Terrace Level Discharge of pump. Head of pump. Power supply. Auto starting of pump. Captive water storage for fire fighting. Underground tank capacity. Draw-off connection. Fire Service Inlet. Access to tank. Overhead tank capacity. Exit Signage. Provision of Lifts. Pressurization of lift shaft. Pressurization in lift car. 	 Type of detectors Location of Main Panel NA- Location of Repeater Panel Alternate source of power Hooter's location MOEFA / SIREN Public Address System Basement Upper floors Sprinkler Bystem Size of Riser/Down-comer Number of Hydrant per floor Hose box. Posicarge of main pump. Head of main pump. Jockey Pump head. Standby Pump head. Auto Starting / Manual Stopping. Pump house access. Terrace Level Dorw-off connection. Power service Inlet. NA- NA- NA- NA- Captive water storage for fire fighting. Underground tank capacity. Pressurization of lift shaft. Pressurization of lift car. 	 Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooter's location Hose System Basement Uper floors Sprinkler above false ceiling NA- Sprinkler above false ceiling NA- <

Bantam Elementary School at Village Rangpuri, New Delhi

Fire Control Room.			
Detector system panel.	-NA-	-NA-	-NA-
	-NA-	-NA-	-NA-
	-NA-	-NA-	-NA-
	-NA-	-NA-	-NA-
Building floor plan.	-NA-	-NA-	-NA-
Special Fire Protection System for the	-NA-	-NA-	-NA-
	 Detector system panel. Flow switch panel. PA system panel. Battery backup. Building floor plan. 	 Detector system panel. Flow switch panel. PA system panel. Battery backup. Building floor plan. Special Fire Protection System for the NA- NA- 	 Detector system panel. Flow switch panel. PA system panel. Battery backup. Building floor plan. Special Fire Protection System for the NA- -NA- -NA- -NA- -NA- -NA- -NA- -NA-

The Fire protection systems provided in the building were checked /operated at random and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/School/2014/SZ/498 dated 22.04.2014, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

: R.N. Singh Name Designation: ADO (BCP)

Bantam Elementary School at Village Rangpuri, New Delhi

FIT letter is furt up for sign fole fure reform

CROSS

M.SCELL WIJIZ