## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

Fax No. 011-23412593, Ph. 011-23412225

No. F.6 DFS/MS/School/2017/SZ/ 1820

Dated: (.5.1.) 2.1.7

## FIRE SAFETY CERTIFICATE

Certified that Govt. Co-Ed. Secondary School, Maidan Garhi, New Delhi-110068, comprised of Ground plus one upper floor owned/occupied by Directorate of Education was issued FSC by this department vide letter No. F.6/MS/DFS/School/2014/SZ/1289 dated 17/10/2014. The school premises was re-inspected by officer concerned of this department on 01/12/2017 in presence of Ms. Asha Gupta (HOS) and found that said school building have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education circular F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by Director of Education, Govt. of NCT of Delhi and that the school building is fit for occupancy class "Educational Building" Group-B, with effect from the date of issue of this certificate for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 15/12/12 at New Delhi by

(Vipin Kental)
Chief Fire Officer

alc

Copy to: -

1. The HOS, Govt. Co-Ed Secondary School, Maidan Garhi, New Delhi-110068

2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

## Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	INSPECTION REPORT					
1	Name & Address of the Building		CONDARY SCHOOL	MAIDAN		
1	Name & Address of the Building	GAPHI NEW DELHI 110068 (ID 1023033)				
2	Type of Occupancy	GARHI, NEW DELHI-110068 (ID-1923033)  Educational Building "Group-B"				
3	Building Comprised of					
4	Type of Case	Ground plus one upper floor Renewal				
5	Details of Previous NOC		ol/2014/SZ/1289 dated	17/10/2014		
6	Fire Safety Directives Letter No		afety/2011/3298 to 3398 date			
7	Date of Inspection	01-12-2017	11cty/2011/32/0 to 33/0 date	04.05.2011		
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)				
9	Name & Designation of Officers	Ms. Asha Gupta (HOS)				
	from the building side	1415. Fisha Gupta (1105)				
10	Year of construction	2008				
11	Applicant letter No.	595 Dated 17/10/2017, ODD No. 14461 Dt. 06/11/17				
S. No	Minimum standards on Fire Prevention	Old NOC Provided at Site Remarks				
5.110	and Fire Safety U/R 33	requirements		MR/NMF		
1	Access to Building.					
	Road width	Required	6 mtr	MR		
	Gate width	-N/A-	-N/A-	-N/A-		
	Width of internal road	-N/A-	-N/A-	-N/A-		
2	Number, width, type & arrangement of	1771	1 1/1 1	1 1772		
Lost	exits.					
all participation of the control of	a) Number of Staircase					
and the second	Upper floors	2 Nos	3 Nos	MR		
O dispersion of	Basement floor	-N/A-	-N/A-	-N/A-		
	b) Width of Staircase					
a-sale-sale-sale-sale-sale-sale-sale-sal	> Upper floors.	1.50m / 0.75m	1.5m & 1.25m	MR		
dame	Basement floor	-N/A-	-N/A-	-N/A-		
		-1N/A-	-IN/A-	-1N/A-		
and the second	c) Protection of exits	37/4	DT/A	DT/A		
Disam-	> Fire check door	-N/A-	-N/A-	-N/A-		
	Pressurization	-N/A-	-N/A-	-N/A-		
to construct the construction of the construct	d) No. of continuous staircase to terrace	Required	Provided one	MR		
	e) Width of corridor	1.5m	Provided	MR		
	f) Door size	1 mtr	Provided	MR		
3	Compartmentation.					
and the state of t	Fire check door.	-N/A-	-N/A-	-N/A-		
	<ul> <li>Sealing of electrical shafts.</li> </ul>	-N/A-	-N/A-	-N/A-		
-	<ul> <li>Fire rating of shaft door.</li> </ul>	-N/A-	-N/A-	-N/A-		
	Water curtain	-N/A-	-N/A-	-N/A-		
	Fire dampers.	-N/A-	-N/A-	-N/A-		
4.	Smoke Management system.					
	Basement	-N/A-	-N/A-	-N/A-		
	<ul> <li>Upper floors</li> </ul>	-N/A-	-N/A-	-N/A-		
5.	Fire Extinguishers.					
	Total numbers	Required	11 Nos	MR		
	Types	ABC / Co2	ABC-11	MR		
			Provided			
	ISI Marking	ISI Marked	rrovided	MR		
6.	First Aid Hose Reels.	**************************************	<b>NT/A</b>	3.7/4		
	Total numbers on each floor.	-N/A-	-N/A-	-N/A-		
	<ul> <li>Length of hose-reel hose.</li> </ul>	-N/A-	-N/A-	-N/A-		
	<ul> <li>Nozzle Diameter</li> </ul>	-N/A-	-N/A-	-N/A-		

Govt. Co-Ed Secondary School, Maidan Garhi, New Delhi-68

A 1.	to a dia fine detection & alamin and			1
7 Au	<ul> <li>tomatic fire detection &amp; alarming system.</li> <li>Type of detectors</li> </ul>	-N/A-	-N/A-	-N/A-
	Location of Main Panel	-N/A-	-N/A-	-N/A-
		-N/A-	-N/A-	-N/A-
- Control of the Cont		-N/A-	-N/A-	-N/A-
	<ul><li>Alternate source of power</li><li>Hooter's location</li></ul>	-N/A-	-N/A-	-N/A-
0 34		-N/A-	-N/A-	-N/A-
	OEFA	-N/A-	-N/A-	-N/A-
	ablic Address System	-IN/A-	-1V/A-	-14/71-
10. A	utomatic Sprinkler System	-N/A-	-N/A-	-N/A-
	Basement.	-N/A-	-N/A-	-N/A-
Spanish and a spanish a spanish and a spanish a spanish and a spanish and a spanish a spanish and a spanish and a spanish a span	• Upper floors	-N/A-	-N/A-	-N/A-
	Sprinkler above false ceiling	-IN/A-	-1N/A-	-14/74-
11. In	ternal Hydrants.	DT/A	-N/A-	-N/A-
	Size of Riser / Down-comer	-N/A-		-N/A-
	Number of Hydrant per floor	-N/A-	-N/A-	
	Hose box.	-N/A-	-N/A-	-N/A-
12. Y:	ard Hydrants.			27/4
Constitution of the Consti	<ul> <li>Total number of hydrants.</li> </ul>	-N/A-	-N/A-	-N/A-
The second secon	<ul> <li>Hose box.</li> </ul>	-N/A-	-N/A-	-N/A-
13. Pt	umping arrangements.	-	American service de la companya del la companya de	
	Ground Level			
	Discharge of main pump.	-N/A-	-N/A-	-N/A-
	> Head of main pump.	-N/A-	-N/A-	-N/A-
	Number of main pumps.	-N/A-	-N/A-	-N/A-
	> Jockey Pump output.	-N/A-	-N/A-	-N/A-
	➤ Jockey Pump head.	-N/A-	-N/A-	-N/A-
	Standby Pump output.	-N/A-	-N/A-	-N/A-
	Standby Pump head.	-N/A-	-N/A-	-N/A-
	Auto Starting / Manual Stopping.	-N/A-	-N/A-	-N/A-
	Pump house access.	-N/A-	-N/A-	-N/A-
-	Terrace Level	×		
	Discharge of pump.	-N/A-	-N/A-	-N/A-
	Head of pump.	-N/A-	-N/A-	-N/A-
-	Power supply.	-N/A-	-N/A-	-N/A-
- Special Control of the Control of	> Auto starting of pump.	-N/A-	-N/A-	-N/A-
14. C	aptive water storage for firefighting.			
	Underground tank capacity.	-N/A-	-N/A-	-N/A-
	> Draw-off connection.	-N/A-	-N/A-	-N/A-
	Fire Service Inlet.	-N/A-	-N/A-	-N/A-
O. Constitution	Access to tank.	-N/A-	-N/A-	-N/A-
Riveronality	<ul> <li>Overhead tank capacity.</li> </ul>	-N/A-	-N/A-	-N/A-
15. E	xit Signage.	-N/A-	-N/A-	-N/A-
	rovision of Lifts.	and the second s		
	Pressurization of lift shaft.	-N/A-	-N/A-	-N/A-
PERMITTER	Pressurization of lift lobby.	-N/A-	-N/A-	-N/A-
ROSSITION AND ADDRESS OF THE PERSON ADDRES	Communication in lift car.	-N/A-	-N/A-	-N/A-
	• Fireman's switch.	-N/A-	-N/A-	-N/A-
-	• Lift signage.	-N/A-	-N/A-	-N/A-
17 S	tandby Power Supply	-N/A-	-N/A-	-N/A-
	efuge Area	1 4/ X	1.11.1	- 1/4 4
10. K	Total area	-N/A-	-N/A-	-N/A-
	• Location	-N/A-	-N/A-	-N/A-
	Govt. Co-Ed Secondary School			-14/17-

Govt. Co-Ed Secondary School, Maidan Garhi, New Delhi-68

19.	Fire Control Room.			
	Detector System Panel.	-N/A-	-N/A-	-N/A-
	Flow Switch Panel.	-N/A-	-N/A-	-N/A-
	PA system Panel.	-N/A-	-N/A-	-N/A-
	Battery backup	-N/A-	-N/A-	-N/A-
	Building floor plan	-N/A-	-N/A-	-N/A-
20.	Special Fire Protection System for the	-N/A-	-N/A-	-N/A-
	Protection of special Risk, if any.			

The Fire protection systems provided in the building were checked / operated at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the DOE circular, FSC issued vide letter No. F.6/MS/DFS/School/2014/SZ/1289 dated 17-10-2014, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name : R.N. Singh Designation: ADO (BCP)

Govt. Co-Ed Secondary School, Maidan Garhi, New Delhi-68

DO(SD) Jah

on Leave to

CPOCSY

m-scell

FTM.

11/12

erost

Miscell 14/12

1464 CF 82