## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/EH/2017/SZ/

Dated: 02.01.18

## FIRE SAFETY CERTIFICATE

Certified that M/s **Odd Even Restaurant** (A Unit of KMS Hotels & Restaurants Pvt. Ltd) located at **Shop No. 24–25**, **Hnd Floor**, **MGF Metropolitan Mall**, **Saket**, **New Delhi-110017**, building comprised of basement, ground + 02 upper floors (Restt. running at 2<sup>nd</sup> floor of the bldg) was issued FSC in the name M/s **Chaper–25** (formerly Café Ludus) by this department vide letter No. F.6/DFS/MS/EH/2014/SZ/1506 dated 02/12/2014. The MGF Mall, Saket has been issued FSC by this department vide letter dated 17/12/2015. The said restaurant was re-inspected by the officer concerned of this department on 07/12/2017 in the presence of Mr. Deepak (Manager) and observed that the restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the said building/premises is fit for occupancy class-D "Assembly Building" (Eating House) as above with effect from the date of issue of this certificate for a period of **Three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 02.01.18 at New Delhi by

(Vipin Kental)
Chief Fire Officer

Copy to: -

- 1. The DHO (South Zone), South MCD, Health Deptt, Green Park, New Delhi-110016
- 2. The Director, M/s Odd Even Restt. (A Unit of KMS Hotels & Restaurants Pvt. Ltd.), Shop No. 24–25, IInd Floor, MGF Mall, Saket, New Delhi-110017

## Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	INSPECTION REPORT					
Penne	Name & Address of the Building	M/s Odd Ever (	Formerly Chapter 25 Res	tt) Shon No		
		M/s Odd Ever (Formerly Chapter 25 Restt) Shop No. 24–25, 2 <sup>nd</sup> floor, MGF Mall, Saket, New Delhi-17				
		(A Unit of KMS	S Hotels & Restaurants P	vt. Ltd)		
2	Type of Occupancy	Assembly Build	ling "Group-D"			
3	Building Comprised of	Basement, Ground + 2 upper floors.				
4	Type of Case	Renewal & Cha	inge of Name			
5	Details of Previous NOC		H/2013/SZ/1506 Dated 02	2/12/2014		
6	Fire Safety Directives Letter No	N/A				
7	Date of Inspection	07.12.2017				
8	Name of the Inspecting Officers	R.N. Singh ADO (BCP)				
9	Name & Designation of Officers from the building side	Mr. Deepak (Manager)				
10	Year of construction	2009-10 Restt running at second floor of the building				
11	Applicant letter No.	Nil dated 11/08/17, ODD No. 10250 dated 22.08.2017				
S.	Minimum standards on Fire Prevention	Old NOC   Provided at Site   Remarks				
No	and Fire Safety U/R 33	Requirements	a rovided at Site	MR/NMR		
1	Access to Building.			I IANEMA I A I A I A		
	<ul> <li>Road width</li> </ul>	Restt within	12 mtr	MR		
	Gate width	Mall	As above	N/A		
	Width of internal road	average of the second s	As above	N/A		
2	Number, width, type & arrangement of exits		710 400 10	14/74		
	a. Number of Staircase	Provided & Maintained by MGF Mall				
	Upper floors	Required	Two	MR		
	Basement floor	N/A	N/A			
	b. Width of Staircase			N/A		
	Upper floors	Provided & Maintained by MGF Mall Required 1.50 mtr MR				
	Basement floor	N/A	1.50 mtr N/A	MR		
	c. Protection of exits	IV/A				
	• Fire check door	Provided & Maintained by MGF Mall				
	Pressurization	Required	As above	MR		
	d. No. of continuous staircase to terrace	Required	As above	MR		
	e. Width of corridor	Required	Two	MR		
7	f. Door size	N/A	N/A	N/A		
3	Compartmentation.	Required 2m MR				
	• Fire check door.		& Maintained by MGF			
	<ul> <li>Sealing of electrical shafts.</li> </ul>	Required	As above	MR		
		Required	As above	MR		
	<ul><li>Fire rating of shaft door.</li><li>Water curtain</li></ul>	N/A	As above	N/A		
A. Contraction of the Contractio		N/A	As above	N/A		
4.	The dumpers.	N/A	As above	N/A		
7.	Smoke Management system.	Provided	Provided & Maintained by MGF Mall			
project particular	Basement	30 ACPH	N/A	N/A		
	Upper floors	12 ACPH	Exhaust fan provided	MR		
5.	Fire Extinguishers.					
and the state of t	Total numbers		10 No's	MR		
	• Types	ISI marked	ABC-06, Co2-04,	MR		
	ISI Marking		Provided Provided	MR		
6.	First Aid Hose Reels.	Provided	The state of the s			
	Total numbers on each floor.	11011000	Provided & Maintained by MGF Mall Provided near Restt. MR			
	Length of hose-reel hose.	Hose-reel		MR		
	Nozzle Diameter	11030-1001	30 m	MR		
	- INOZZIE DIAIIIEIEI	05 mm MR				

M/s Odd Even Restt at Shop No. 24–25, SF, MGF Mall, Saket

7	Automatic fire detection & alarming system	Provide	d & Maintained by MGF	Mall	
	Type of detectors	Required	Smoke & Heat	MR	
-	<ul> <li>Location of Main Panel</li> </ul>	Required	Upper basement	MR	
	<ul> <li>Location of Repeater Panel</li> </ul>	Required	Ground floor	MR	
	Alternate source of power	Required	Provided	MR	
	<ul> <li>Hooter's location</li> </ul>	Required	Provided	MR	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	Required	Provided	MR	
10.	Automatic Sprinkler System	Provided & Maintained by MGF Mall			
	Basement	N/A	N/A	N/A	
	<ul> <li>Upper floors</li> </ul>	Required	Provided	MR	
	<ul> <li>Sprinkler above false ceiling</li> </ul>	N/A	N/A	N/A	
11.	Internal Hydrants.	Provided & Maintained by MGF Mall			
	Size of Riser/Down-comer	N/A	As above	N/A	
	<ul> <li>Number of Hydrant per floor</li> </ul>	N/A	As above	N/A	
	Hose box.	N/A	As above	N/A	
12.	Yard Hydrants.	Provided & Maintained by MGF Mall			
	Total number of hydrants.	N/A	N/A	N/A	
	Hose box.	N/A	N/A	N/A	
13.	Pumping arrangements.				
	Ground Level	Provided & Maintained by MGF Mall			
	Discharge of main pump.	N/A	4500 LPM	N/A	
	Head of main pump.	N/A	88 mtr	N/A	
	Number of main pumps.	N/A	Two	N/A	
	Jockey Pump output.	N/A	240 LPM	N/A	
	Jockey Pump head.	N/A	88 mtr	N/A	
	Standby Pump output.	N/A	4500 LPM	N/A	
	Standby Pump head.	N/A	88 mtr	N/A	
	Auto Starting / Manual Stopping.	N/A	As above	N/A	
	Terrace Level	Provide	d & Maintained by MGF	Mall	
	Discharge of pump.	225 LPM	As above	MR	
	Head of pump.	N/A	N/A	N/A	
	Power supply.	N/A	N/A	N/A	
	Auto starting of pump.	N/A	N/A	N/A	
14.	Captive water storage for Fire Fighting.	Provided & Maintained by MGF Mall			
	<ul> <li>Underground tank capacity.</li> </ul>	N/A	3,00,000 ltrs	N/A	
	Draw-off connection.	N/A	As above	N/A	
	Fire Service Inlet.	N/A	As above	N/A	
-	Access to tank.	N/A	As above	N/A	
	Overhead tank capacity.	2,500 ltrs	60,000 ltrs	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.		d & Maintained by MGF		
	Pressurization of lift shaft.	N/A	As above	N/A	
	<ul> <li>Pressurization of lift lobby.</li> </ul>	N/A	As above	N/A	
	<ul> <li>Communication in lift car.</li> </ul>	N/A	As above	N/A	
Self-like special control	• Fireman's switch.	N/A	As above	N/A	
	Lift signage.	N/A	As above	N/A	
17	Standby Power Supply	Required	Provided	MR	
18.	Refuge Area	T. T. T.			
	Total area	N/A	N/A	N/A	
90	<ul> <li>Location</li> </ul>	N/A	N/A	N/A	

M/s Odd Even Restt at Shop No. 24–25, SF, MGF Mall, Saket

19.	Fire Control Room.	Provided & Maintained by MGF Mall		
	<ul> <li>Detector System Panel.</li> </ul>	Required	As above	MR
	<ul> <li>Flow Switch Panel.</li> </ul>	Required	As above	MR
	<ul> <li>PA system Panel.</li> </ul>	Required	As above	MR
	<ul> <li>Battery backup</li> </ul>	Required	As above	MR
	Building floor plan	Required	As above	MR
20.	Special Fire Protection System for the Protection of special risk, if any:	N/A	As above	N/A

Previously, the restaurant in the name of M/s Chapter-25 (A Unit of BTS Hospitality) was issued FSC by this department vide letter No. F.6/DFs/MS/EH/2014/SZ/1506 dated 02/12/2014

The Fire protection systems provided in the building were checked/ operated at random and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH2014/SZ/1506 Dated 02/12/2014, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

: R.N. Singh Designation: ADO (BCP)

M/s Odd Even Restt at Shop No. 24-25, SF, MGF Mall, Saket

Sin. necessary corrections have been made and re. submitteelple

fuz.

19/12

m-spell

Ell 22/12-Ell sign ble for si