## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2017/ 1778

Dated: 8/12/17

## **FIRE SAFETY CERTIFICATE**

Issued 8 11210 at New Delhi by.

(VIPEN KENTAL) CHIEF FIRE OFFICER

Copy to:-

1. Sh. Kamal Kishore (Owner), Guest House Apra Inn, 15A/61, W.E.A, Karol Bagh, New Delhi-110005.

2. The Addl. C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi

## Following Fire Safety Directives must be adhered to: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [ sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: M/s Apra Inn, 15A/61, W.E.A, Karol Bagh, New Delhi- 05

2. Type of Occupancy : Lodging House

3. Type of Case : Renewal

4. Details of previous NOC : F.6/DFS/MS/GH/2014/NDZ/985 dated 06.08.2014

5. Fire Safety directives letter No : N/A

6. Date of inspection : 04-12-2017

7. Name of the Inspecting Officers: M.K. Chattopadhyay, Divisional Officer (South West)

8. Name and designation of officers

from the building side : Sh. Rajender, Manager

9. Year of Construction : 2003-04

10. Applicant's letter No. : Nil dated Nil

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per letter No 06.08.2014	Provided at site	Remarks MR/NMR		
1	Access to building					
	• Road width	06 mts	Provided	MR		
	Gate width	05 mts	Directly accessible	MR		
	• Width of internal road	N/A	N/A	N/A		
2	Number, Width, Type & Arrangemen	nt of Exits				
	a. Number of staircases	-	-	_		
	• Upper Floors	01	Provided(01)	MR being old case		
	Basements	01	Provided(01)	MR being old case		
	b. Width of staircases	_	-			
	• Upper Floors	old case	1.30 mts.	MR being old cas		
	Basements	old case	1.50 mts.	MR being old cas		
	c. Protection of exits	-		-		
	• Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A	N/A		
	e. No. of continuous staircases to terrace	01	01	MR		
	g. Width of Corridor	1.25 mts	1.50 mts	MR		
	h. Door Size	Old case	Provided (0.79 mt.)	MR being old case		
3	Compartmentation.	-				
	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	Sealed			
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	• Fire Dampers	N/A	N/A	N/A		
	Smoke Management System.					
	Basements	30 a/c per hour	Exhaust fan provided	l MR		
	Upper floors	12 a/c per hour	Natural ventilation	MR		

	• Total numbers	15	Provided	MR			
	• Types	CO <sub>2</sub> , ABC type	Provided	MR			
	IS marking	ISI marked	Provided	MR			
6	First-Aid Hose Reels.						
	Total numbers on each floor	01	Provided	MR			
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided	MR			
	Nozzle diameter	5 mm	Provided	MR			
7	Automatic fire detection and alarming system.						
8	Type of detectors	N/A	N/A	N/A			
	Location of Main Panel	N/A	N/A	N/A			
	Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	Required	D.G set (85 KVA)	N/A			
7	Hooters' Location	N/A	N/A	N/A			
8	MOEFA	Required	Provided	MR			
9	Public Address System.	Required	Provided	MR			
10	Automatic Sprinkler System.	* 1 .					
	Basement	Required	Provided	MR			
	Upper Floor	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants						
	Size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12	Yard Hydrants.						
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13	Pumping Arrangements.	- 1	v —				
•	Ground Level						
	Discharge of main Pump	N/A	N/A	N/A			
	➤ Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	> Jockey Pump out put	N/A	N/A	N/A			
	> Jockey pump head	N/A	N/A	N/A			
-	Standby Pump out put	N/A	N/A	N/A			
	> Standby Pump Head	N/A	N/A	N/A			
	Auto Starting/ Manual stopping	N/A	N/A	N/A			
	> Pump House Access	N/A	N/A	N/A			
	<ul><li>Terrace level</li><li>Discharge of pump</li></ul>						
	Discharge of pullip	450 LPM	Provided	AP haing old ages			

	> Head of the pump	30 mts	Provided	MR			
€.	> Power Supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for fire fighting.						
	Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	Provided				
	> Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	5,000 lts	Provided	MR being old case			
15	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	Required	Provided	MR			
	Fireman's Grounding Switch	Required	Provided	MR			
	Lift Signage	Required	Provided	MR <sup>©</sup>			
17	Standby power supply	Required	Provided	MR			
18	Refuge Area.						
	> Total Area	N/A	N/A	N/A			
	> Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup	Required	Provided	MR			
	Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	Two ABC type fire extinguisher found provided near elect. panel	MR			

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/GH/2014/NDZ/985 dated 06.08 2014, renewal under rule 37 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Note:- Previously FSC was issued for basement (used as hall), ground plus three upper floors but the owner has rented out the basement floor to a Ayurveda Spa center.

CON

M.K. CHATTOPADHYAY
Divisional Officer (South West)