GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI-110001

No. F6/DFS/MS/EH/SZ/2017/1883

Dated: 29/12/17

FIRE SAFETY CERTIFICATE

Certified that the Restaurant in the name & style of M/s Junction (A unit of Tewari Café Pvt. Ltd.) located at Shop No. 3 to 10 Ground Floor with open area, C.S.C. Complex, Hauz Khas, New Delhi-110016, comprised of Ground & one upper Floor. The restaurant is running at Ground Floor only was inspected by the officer concerned of this department on 15/12/17 in the presence of Mr. Vikram (Manager) and found that the said premises have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Group-D Assembly "Eating House" (at 2nd floor only) Building with from ... 27:12:2017. for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .. 29.12. 2017 at New Delhi by

(Vipin Kental) Chief Fire Officer

Tel: 011-23412225

Copy to:-

- 1. Dy. Health Officer, South Zone, SDMC, Green Park, New Delhi-110016 {reference to your letter No. DHO/SZ/2017/D1276 dated 13/09/17}
- 2. M/s Junction (A unit of Tewari Café Pvt. Ltd.), Shop No. 3 to 10 Ground Floor, C.S.C. Complex, Hauz Khas, New Delhi-110016

Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in **Form 'K'** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form 'J'** [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	INSPECT	ON REPORT				
1	Name & Address of the Building M/S Junction (Unit Of Tewari Cafe Pvt. Ltd), Short					
		No. 3 to 10 at GF with open area, CSC Complex,				
		Hauz Khas, New Delhi-110016				
2	Type of Occupancy	Assembly buildings 'Group-D'				
3	Building comprised of	Ground plus one upper floor.				
4	Type of Case	New				
5	Details of Previous NOC	Nil				
6	Fire Safety Directives Letter No	Cir. No. 4/22/2004/HP-III/356 –369 Dt. 22-03-2005				
7	Date of Inspection	15-12-2017				
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)				
9	Name & Designation of Officers	Mr. Vikram (Manager)				
	from the building side					
10	Year of construction	1980-89				
11	Applicant letter No.	Nil dated 18/10	/17, ODD No. 12806 Dt. 1	8/10/2017		
S. No	Minimum standards on Fire Prevention	As per Circular Provided at Site Remark				
	and Fire Safety U/R 33	(22/03/2005)		MR/NMI		
1	Access to Building.			178840141788		
	Road width	4.5 mtr	9 mtr	MR		
	Gate width	N/A	5.5 mtr	N/A		
	Width of internal road	N/A	N/A	N/A		
2	Number, width, type & arrangement of exits			1 1/1 1		
	a. Number of Staircase					
	Upper floors	N/A	N/A	N/A		
	Basement floor	N/A	N/A	N/A		
	b. Width of Staircase	THER	1 14/7	14/74		
	Upper floors	A/A	N/A	N/A		
	Basement floor	N/A	N/A	N/A N/A		
	c. Protection of exits	14/74	IN/A	NATE OF THE PERSON OF THE PERS		
	Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A N/A	N/A N/A		
	d. No. of continuous staircase to terrace	N/A				
	e. Width of corridor	N/A	N/A	N/A		
DOD NAME	f. Door size	Two exits	N/A 1.9m, 1.95m & 1.1m	N/A		
3	Compartmentation.	1 WO CXILS	1.9m, 1.95m & 1.1m	MR		
	Fire check door.	N/A	N/A	DI/A		
alian and a second	Sealing of electrical shafts.	N/A	N/A N/A	N/A		
	• Fire rating of shaft door.	N/A	The same of the sa	N/A		
4.	Water curtain	N/A	N/A	N/A		
	Fire dampers.	N/A N/A	N/A N/A	N/A		
	2	14/17	N/A	N/A		
To	Smoke Management system. Basement	NI/A	B.T./ A	1 27/1		
O-MITTER METERS		N/A	N/A	N/A		
	Upper floors	Required	Exhaust fans provided	MR		
5.	Fire Extinguishers.					
disentation	 Total numbers 	4 No's	10 No's	MR		
Consumptions.	 Types 	ABC / Co2	ABC-60, Co2-04	MR		
	ISI Marking	ISI marked	Provided	MR		
6.	First Aid Hose Reels.		1 I VIII L	1411/		
		One	- O) (D		
de la company	Total numbers on each floor.	30 m	One	MR		
		411 222	30 m	MR		
OBSERBICIONALANA	Length of hose-reel hose.Nozzle Diameter	5 mm	5 mm	IAII		

M/s Junction, Shop No. 3 to 10 GF, CSC Complex, Hauz Khas, New Delhi

	A A 4° 5° 3° 4 4° 6° 1. ° 4.			
7	Automatic fire detection & alarming system.	N/A	N/A	N/A
W) parents	Type of detectors Leasting of Main Panel	N/A N/A	N/A N/A	N/A
The department of the	Location of Main Panel Location of Reporter Panel	N/A	N/A	N/A
The second	Location of Repeater Panel Alternate source of powers	N/A	N/A	N/A
Company of the Control of the Contro	Alternate source of power	N/A N/A	N/A	N/A
_	Hooter's location		Provided	MR
	MOEFA / MCP'S	Required N/A	N/A	N/A
	Public Address System	N/A	IV/A	IVA
10.	Automatic Sprinkler System	N/A	N/A	N/A
	Basement	IN/A	Provided	N/A
and the same of th	Upper floors	N/A	N/A	N/A
	Sprinkler above false ceiling	IV/A	IV/PA	1 11/12
11.	Internal Hydrants.	DT/A	100	N/A
The Control of the Co	Size of Riser/Down-comer	N/A	100 mm	N/A N/A
Villedinassanderen	Number of Hydrant per floor	N/A	One	
	Hose box.	N/A	One	N/A
12.	Yard Hydrants.	* T / *	A. I. / T) NT/A
	 Total number of hydrants. 	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13.	Pumping arrangements.			
-	Ground Level	37/4	AT/A	DT/A
	Discharge of main pump.	N/A	N/A	N/A
	Head of main pump.	N/A	N/A	N/A
No.	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A N/A
and a second	> Jockey Pump head.	N/A	N/A	N/A N/A
	> Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.Auto Starting / Manual Stopping.	N/A	N/A N/A	N/A
		N/A	N/A	IN/A
-	Terrace Level	225 LPM	450 LPM	MR
	Discharge of pump.	40 mtr	40 mtr	MR
e constant	Head of pump.Power supply.	Required	Provided	MR
OF THE PERSON NAMED IN COLUMN	Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for Fire Fighting.	Redanca	I I V I U C U	IVIII
A Tre	 Underground tank capacity. 	N/A	N/A	N/A
(C)	> Draw-off connection.	N/A	N/A	N/A
questiones	Fire Service Inlet.	N/A	N/A	N/A
equintered.	Access to tank.	N/A	N/A	N/A
The state of the s	Overhead tank capacity.	2,500 ltrs	10,000 ltrs	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	Andrew Control of the	ang ann an an air an ann an air an faoi agus badh a an an ag a ba agus thair an tarban ag an an an an an ag an	
	Pressurization of lift shaft.	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
***************************************	Communication in lift car.	N/A	N/A	N/A
activated litera	Fireman's switch.	N/A	N/A	N/A
	 Lift signage. 	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18.	Refuge Area			
131	Total area	N/A	N/A	N/A

M/s Junction, Shop No. 3 to 10 Ground floor, CSC Complex, Hauz Khas, New Delhi

19.	Fire Control Room.			
	Detector System Panel.	N/A	N/A	N/A
	 Flow Switch Panel. 	N/A	N/A	N/A
	PA system Panel.	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the	N/A	N/A	N/A
	Protection of special Risk, if any:			

The Fire protection systems provided in the building were checked / operated at random and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Office

: R.N. Singh Name Designation: ADO (BCP)

M/s Junction, Shop No. 3 to 10 Ground floor, CSC Complex, Hauz Khas, New Delhi

frende the in staircase details in inspection

Sir. The regress for Restaunt at 9. floor only So trust we have not mon tian to wite of

Strin case in the inspection report pla

- ! The letter from med has asked for FSC for both G.F. F.F. B&R them to clarify. 2. The exit doesn't meet required watth