GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F.6/DFS/MS/Hospital/2018/WZ 6 2

FIRE SAFETY CERTIFICATE

Certified that the Satyawadi Raja Harish Chander Hospital (200 Bedded) located at Narela Delhi-110040 comprised of Basement, Ground, 1st Floor, 2nd Floor, 3rd Floor & 4th Floors only owned / occupied by Delhi Govt. has already been issued Fire Safety Certificate Vide letter No. F6/DFS/MS/Hospital/2013/241 dated 03/05/2013. The premises was re-inspected by the officer concerned of Fire Service on 29.12.2017 in the presence of Sh. B.L. Meena (J.E. Elec.) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the fire prevention and Fire Safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and premises is fit for occupancy Institutional C-1(iv) with effect from 6 / 0 / 0 / 2018 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rules, 2010.

Issued on 05/01/18 at New Delhi by.

CHIEF FIRE OFFICE

Dated: 09/01/2018

Copy to :-

1. Executive Eng. (E), Health Maintenance Elect. Division (North), PWD, GNCTD, Dr. BSA Hospital, Rohini, Sec.-6, Delhi-110085.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. The Basement shall be used strictly as per the provision of building bye laws.
- 6. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 7. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
- 8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on WWW.dfs.Delhigovt.nic.in

INSPECTION REPORT

T NS3

Basement +

upper floors

Ground + Four

To see the compliance of office letter No.F6/DFS/MS/Hospital/2017/2503 Dated 26/09/2017.

1. Name & address of the building: Satyawadi Raja Harish Chander Hospital, (200 Bedded), Narela Delhi-110040.

2. Type of Occupancy : Institutional C-1(iv)

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/Hospital/2013/241 dated 03/05/2013

5. Fire Safety directives Letter No.: NBC (Part-IV)

6. Date of inspection : 29/12/2017

7. Name of the Inspecting Officer: A.K. Jaiswal (A.D.O. JWP)

8. Name and designation of Officer

from the building side : Sh. B.L. Meena (J.E. Elec.)

9. Year of Construction : 2003

S No	Applicant's letter No.: 23(7)/XEN Minimum standards on fire prevention and fire safety U/R 33	BBL / NBC Requirements		Provided at site	Remarks MR/NMR		
1.	Access of building						
	Road width	9 mtr		9 mtr	MR		
	Gate width	6 mtr		6 mtr	MR		
	Width of internal road	6 mtr		6 mtr	MR		
2.	Number, width, Type & Arrangements of exits						
	a. Number of staircases	-					
	Upper floors	9		8	MR (Old case)		
	Basements	9		8	MR (Old case)		
	b. Width of staircases						
	Upper floors	2 mtr	2.00 mtr x 4 & 1.00 mtr x 4		MR		
	• Basements	2 mtr 2.00 mtr x 4 & 1.00 mtr x 4		MR			
	c. Protection of exits						
	Fire check door	Required Provided		MR			
	Pressurization	NR		NR	NR		
	d. No of continuous	4		4	MR		
	staircase to terrace						
	e. Width Of Corridor	NA		NA	NA		
2	f. Door Size	NA	1.	52 mtr & 1.73 mtr	NA		
3.	Compartmentation						
	Fire check door	Required		Provided	MR		
	 Sealing of electrical shafts 	Required		Provided	MR		
	Fire Rating of shaft door	NA		NA	NA		
	Water Curtain	NA		NA	NA		
	• Fire Dampers	NA		NA	NA		
4.	Smoke managements System				3.000 -40		
	Basements	Required		Exhaust fan Provided	MR		
	 Upper floors 	Required		Provided	MR .		
5.	Fire Extinguishers						
	 Total numbers 	1 @ 300 m ²		187	MR		
	• Types	ISI marked ABC/CO ₂		Provided	MR		
	IS marking	Required		Provided	MR		
			BARRE	1			

11/39 6. First – Aid Hose Reels Total numbers on 7 7 MR each floor Length of hose reel 30Mtr. 30Mtr. MR Nozzle diameter 5mm. 5mm. MR 7. Automatic fire detection and alarming system Type of detector Smoke Smoke MR Location of Main GF GF MR Panel Location of Repeater NA NA NA Panel Alternate source of Required Provided MR power Hooters' Location Required Provided MR 8. **MOEFA** Required Provided MR Public Address System 9. Required Provided MR 10. Automatic Sprinkler System Basements Required Provided MR Upper Floor Required Provided MR Sprinkler above false NA NA NA ceiling 11. Internal Hydrants Size of riser/down-150 mm 150 mm MR comer Number of hydrants 11 11 MR per floor Hose Box Required Provided MR 12. Yard Hydrants Total number of 11 11 MR hydrants Hose Box Required Provided MR 13. Pumping Arrangements Ground Level • Discharge of main pump 2850 LPM 2850 LPM MR ► Head of main pump 70MH 70MH MR Number of main pumps 2 2 MR Jockey pump out put 180 LPM 450 LPM MR Jockey pump head 70MH 70MH MR Standby Pump out put 2850 LPM 2850 LPM MR Standby Pump Head 70MH **70MH** MR Auto Staring/Manual Required Provided MR stopping Pump House Access Required Provided MR Terrace level • Discharge of pump NR NR NR Head of the pump NR NR NR Power supply NR NR NR Auto starting of pump NR NR NR 14. Captive water Storage for fire fighting Underground tank 2,40,000 ltr 2,40,000 ltr MR capacity Draw of connection Required Provided MR Fire service inlet Required Provided MR Access to tonl

	NUSS					
15	Exit Signage	Required	Provided	MR		
16.	Provision of Lifts					
	Pressurization of Lift Shaft	Required	Provided	MR		
	Pressurization of lift lobby	NA	NA	NA		
	Car Communication in lift	Required	Provided	MR		
	Fireman's Grounding Switch	Required	Provided	MR		
	➤ Lift Signage	Required	Provided	MR		
17.	Standby power supply	Required	2 x 750 KVA	MR		
18.	Refuge Area	ŇR	NR			

NR

NR

NA

NA

NR

Required

Required

Required

NR

NR

NA

NA

NR

Provided

Provided

Provided

NR

NR

MR

NA

MR

MR

NA

NR

special Risks, if any; The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. MCB and Conduit Metal Wiring has also been provided.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No. F6/DFS/MS/Hospital/2013/241 dated 03/05/2013 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

> Signature of the Inspecting Officer Name : A.K. Jaiswal

Designation: A.D.O. (JWP)

Total area

Detector system panel

Flow Switch Panel

Building Floor Plans

PA System Panel

Battery backup

Location

Special Fire Protection

Systems for Protection of

Fire control room

19.

20.

F.T. letter is prit up post sejnatuufst.