GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE

NEW DELHI- 110 001

No.F.6/DFS/MS/School/2017/NDZ/

Dated: 09/01/18

FIRE SAFETY CERTIFICATE

Certified that the M/s Govt. Girls Sr. Sec. School located at New Seelampur, Delhi-110053, comprised of Ground plus three upper floors & Ground plus one upper floor (two separate blocks) owned / occupied by Govt. Girls Sr. Sec. School was issued FSC vide letter No. F.6/DFS/MS/School/2013/NDZ/1003 Dated 30/09/13. The school building was re-inspected by the officer concerned of this department on 12/12/17 in presence of Mrs. Veena Gupta, Estate Manager of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010 and observed that the school building is fit for occupancy class "B" conditions printed overleaf.

(Vipin Kental) Chief Fire Officer Delhi Fire Service

Olc for

To,

The Principal Govt. Girls Sr. Sec. School, New Seelampur, Delhi- 110053.

Copy to:-

The Dy. Director of Education B- Block, Yamuna Vihar. Delhi- 110053.

- Conditions -

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in good working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. "The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form'J'[sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"

1. Name & address of the building : Govt. Girls Sr. Sec. School, New Seelampur,

Delhi- 110053.

2. Building is comprised of : G+3 & G+1 (in two separate block

3. Type of Occupancy : Educational 4. Type of Case : Renewal

5. Details of Previous FSC letter : F.6/DFS/MS/School/2013/NDZ/1003 Dated 30/09/13

6. Fire Safety circular No : NBC Part IV 7. Date of Inspection : 12/12/2017

8. Name of the Inspecting officers : ADO R.K. YADAV 9. Name and designation of Officer

from the building side

: Mrs Veena Gupta (Estate Manager)

: 1984

10. Year of Construction 11. Applicant's letter No : GGSSS/No.2/NSP/2017/215 Dated - 28/11/2017

NO.	Minimum Standards on fire prevention and fire safety U/R33	Requirement	Provided at Site	Remark MR/NMR			
1	Access to building						
	 Road width 	06 Mtr	06 Mtr	MR			
	Gate width	4.50 mtr	4.50 mtr	MR			
	 Width of internal road 	N/A	N/A	N/A			
2	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases						
	 Upper Floor (G+3) 	02 nos.	02 nos	• MR			
	 Upper Floor (G+1) 	01 nos.	01 nos	MR			
	 Basement 	N/A	N/A	N/A			
	b. Width of Staircases						
	 Upper Floor 	1.5 mtr	1.5 mtr each	MR			
	Basement	N/A	N/A	N/A			
	c. Protection of exits	27					
	 Fire check door 	N/A	N/A	N/A			
	 Pressurization 	N/A	N/A	N/A			
	d. No. of continuous staircases						
	to terrace						
	e. Width of Corridor	1.5 mtr	02 mtr	MR			
	f. Door Size	01 mtr	1.0 mtr	MR			
3	Compartmentation.						
	 Fire check door 	N/A	N/A	N/A			
	 Sealing of electrical shafts 	N/A	N/A	N/A			
	 Fire rating of shaft door 	N/A	N/A	N/A			
	Water curtain	N/A	N/A	N/A			
	 Fire Dampers 	N/A	N/A	N/A			
4	Smoke Management System.						
	Basement	N/A	N/A	N/A			
	Upper floor	N/A	N/A	N/A			
5.	Fire Extinguishers						
	Total numbers	12 nos.	12 nos.	MR			
	types	ABC & Co2	ABC & Co2	MR			
	ISI marking	ISI marked	ISI marked	MR			

6	First-aid-Hose Reels.						
	Total numbers of each floor	01 no	01 no	MR			
	 Length of hose reel hose 	30 mtr	30 mtr	MR			
	Nozzle diameter	05 mm	05 mm	MR			
7	Automatic fire detection and alarming system.						
	Type of detectors	N/A	N/A	N/A			
	Location of main panel	N/A	N/A	N/A			
	Location of repeater panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter's location	N/A	N/A	N/A			
8	MOEFA	N/A	N/A	N/A			
9	Public address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.						
	Basement	N/A	N/A	N/A			
	upper floor	N/A	N/A	N/A			
	 sprinkler above false ceiling 	N/A	N/A	N/A			
11	Internal Hydrants						
	 size of riser/down-comer 	N/A	N/A	N/A			
	 Number of hydrants per floor 	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12	Yard Hydrants.						
	 Total number of hydrants 	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	Ground Level	N/A	N/A	N/A			
	Discharge of main Pump	N/A	N/A	N/A			
	Head of Main Pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby pump out put	N/A	N/A	N/A			
	Standby pump Head	N/A	N/A	N/A			
	Auto Starting /Manual stopping	N/A	N/A	N/A			
	> Pump House Access	N/A	N/A	N/A			
	Terrace Level						
	➤ Discharge of pump	450 lpm	450 lpm	MR			
	➤ Head of the Pump	40 mtr	40 mtr	MR			
	> Power supply	Required	Provided	MR			
	> Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for Fire Fighting						
	Underground tank capacity	N/A	N/A	N/A			
	> Draw-off connection	N/A	N/A	N/A			
	➢ Fire service inlet	N/A	N/A	N/A			
	> Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	10,000 ltr	10,000 ltr	MR			
15	Exit Signage.	Required	Provided	MR			

16	Provision of Lifts.	N/A	N/A	N/A
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby		N/A	N/A
	Communication in lift car	N/A	N/A	N/A
	Firemen's grounding	N/A	IN/A	14// (
	switch • Lift Signage	N/A	N/A	N/A
17	Lift Signage Standby power supply	N/A	N/A	N/A
18	Refuge Area.			2.10
10	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room			21/0
19	Detector system panel	N/A	N/A	N/A
	Elitab papal	N/A	N/A	N/A
	PA system panel	N/A	N/A	N/A
		N/A	N/A	N/A
	Battery backup Battery backup Battery backup	N/A	N/A	N/A
20	Building Floor Plans Special Fire Protection systems for protection of special Risks, if	N/A	N/A	N/A
	any:		2	

The fire protection systems provided in the building were tested / checked and found functional, at the time of inspection. The shortcomings issue vide letter No. F6/DFS/MS/School/2017/617 dated 08/03/17 has been rectified now.

Keeping in view, of the deemed compliance, of the minimum standards on fire prevention and fire safety measures as required under NBC Part IV, it is recommended to issue Fire Safety Certificate.

Signature of the Inspecting Officer

Name
Designation
R.K. YADAV

DO (East) Jun J

rc FO . m-scell

F.T/0.

F.t. leller is Prepare and put up for signalis felm.

CFO/HIS/ MISCELL LESTIFIE