GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI-110001

No. F6/DFS/MS/EH/SZ/2018/90

Dated: (5.01.18

FIRE SAFETY CERTIFICATE

(Vipin Kental) Chief Fire Officer Tel: 011-23412225

010 A

Copy to:-

- 1. Sh. Tushar Gulati M/s The Studio By Gurdas Maan (A Unit of Gmnow Hospitality Pvt. Ltd.), M4, Second Floor, South Extension Part-2, New Delhi.
- 2. Dy. Health Officer, Central Zone, SDMC, Jal Vihar, Lajpat Nagar, New Delhi {reference to your letter No. DHO/CNZ/2017/1139 dated 04/12/2017}

Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/occupier shall submit a declaration **every year** in **Form 'K'** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	the Studio By Gurdas Maan (A Onli of Gmnow Hospitality Pvt. L		Extension Part-2, New	Delhi				
	INSPECTIO	N REPORT						
1.	Name & address of the building: Restaurant wi	th name & style The S	tudio By Gurdas N	Maan (A Unit				
	Gmnow Hospitality Pvt. Ltd.), M4, Second Floor, South Extension Part-2, New Delhi							
2.	Type of Occupancy : Assembly Building, Group-D, Restaurant							
3.		pe of Case : New case [Restaurant at 2 nd Floor Only]						
4. 5.	Details of Previous NOC : Nil	3.7.10						
6.	Fire Safety directives letter No: FPW directive Date of inspection: 10/01/2018	es at N/2						
	Date of inspection : 10/01/2018 Name of Inspecting Officer : A. K. Malik							
	Name and designation of							
0.	officers from the building side: Mr. Tushar Gu	ılati						
9	**		C 41 D	and was				
		sement, Stilt & 1 st Floor as 39 dated 04/12/2017 outdoor of	lie of others Property	y) + 2 ^m Floor				
S. No.	Minimum Standards on fire prevention	Directives at N/2	Provided at	Remarks				
	and fire safety U/R 33	& 2005 circular	site	MR/NMR				
	and me salety of R 55		Site	WIR/INIVIR				
		Requirement	le e totale e					
1.	Access to building							
	Road width	4.5m	6m	MR				
	• Gate width	-NA-	-NA-	-NA-				
	Width of internal road	-NA-	-NA-	-NA-				
2.	Number, Width, Type & Arrangement of E	xits						
	a. Number of staircases							
	• Upper Floors	2 =	2	MR				
	Basements	-NA-	-NA-	-NA-				
	b. Width of staircases							
	Upper Floor	1.725m & 1.45m	1.8m & 1.4m	MR				
	Basements	-NA-	-NA-	-NA-				
	c. Protection of exits							
	Fire check door	-NA-	-NA-	-NA-				
	 Pressurization 	-NA-	-NA-	-NA-				
	d. No. of continuous staircases to terrace e.	One	Two	MR				
	Width of Corridor	-NA-	-NA-	-NA-				
	f. Door Size	Two Exit	Three Nos of	MR				
		I WO LAIL	1.8m, 0.7m &	IVIK				
			0.9m					
3.	Compartmentation							
	Fire check door	-NA-	-NA-	-NA-				
	Sealing of electrical shafts	-NA-	-NA-					
	• Fire Rating of shaft door	-NA-		-NA-				
	• Water Curtain	-NA-	-NA-	-NA-				
	• Fire Dampers	-NA-	-NA-	-NA-				
4.	Smoke Management System	1111	-1177-	-11/2-				
	Basements	20 A CDII	NIA	27.4				
	Upper floors	30 ACPH 12 ACPH	-NA- Exhaust Fan	-NA- MR				
_	^ ^	12110111	Danaust Fall	IVIIC				
5.	Fire Extinguishers	-						
	Total numbers	6 No's	6-No's	MR				
	• Types	ISI	ABC-3 No's	MR				
	IS marking	Marked	CO ₂ -3 No's					
6.	First-Aid Hose Reels		Yes	MR				
0.								
	 Total numbers on each floor 	One	One	MR				

	Type of detectors	-NA-	Provided	-NA-			
	Location of Main Panel	-NA-	Provided	-NA-			
	 Location of Repeater Panel 	-NA-	Provided	-NA-			
	 Alternate source of power 	-NA-	Provided	-NA-			
	 Hooters' Location 	-NA-	Provided	-NA-			
8.	MOEFA	Required	Provided	MR			
9.	Public Address System	-NA-	-NA-	-NA-			
10.	Automatic Sprinkler System	L					
	Basement	-NA-	-NA-	-NA-			
	• Ground & Upper Floors	Required	Provided	MR			
	 Sprinkler above false ceiling 	-NA-	-NA-	-NA-			
11.	Internal Hydrants						
	Size of riser/down-comer	100mm	100mm	MR			
	 Number of hydrants per floor 	One	One	MR			
	Hose Box	One	One	MR			
12.	Yard Hydrants						
	 Total number of hydrants 	-NA-	-NA-	-NA-			
	Hose Box	-NA-	-NA-	-NA-			
13.	Pumping Arrangements						
	• Ground Level						
	Discharge of main Pump	-NA-	-NA-	-NA-			
	Head of Main pump	-NA-	-NA-	-NA-			
	Number of main pumps	-NA-	-NA-	-NA-			
	Jockey Pump out put	-NA-	-NA-	-NA-			
	Jockey pump head	-NA-	-NA-	-NA-			
	Standby Pump out put	-NA-	-NA-	-NA-			
	> Standby Pump Head	-NA-	-NA-	-NA-			
	Auto Starting/Manual Stopping	-NA-	-NA-	-NA-			
	Terrace level						
	Discharge of pump	450 LPM	1620 & 180	MR			
			LPM				
	Head of the pump	40m	40m	MR			
	Power Supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
14.	Captive Water Storage for fire fighting						
	 Underground tank capacity 	-NA-	-NA-	-NA-			
	Draw-off connection	-NA-	-NA-	-NA-			
	Fire service inlet	-NA-	-NA-	-NA-			
	Access to tank	-NA-	-NA-	-NA-			
	Overhead Tank capacity	5,000 Lts.	40,000 Lts.	MR			
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.			1			
	Pressurization of Lift Shaft	-NA-	-NA-	-NA-			
	 Pressurization of Lift lobby 	-NA-	-NA-	-NA-			
	Communication In lift Car	-NA-	-NA-	-NA-			
	Fireman's Grounding Switch	-NA-	-NA-	-NA-			
-	Lift Signage	-NA-	-NA-	-NA-			
17.	Standby power supply	Required	Provided	MR			
18.	Refuge Area.	required	TIOVIDED	IVIK			
		27.4		27.4			
10.	Total Area	N A	N I A				
10.	Total AreaLocation	-NA-	-NA-	-NA-			

-N16-

The Studio By Gurdas Maan (A Unit of Gmnow Hospitality Pvt. Ltd.), M4, Second Floor, South Extension Part-2, New Delhi

The Studio By Gurdas Maan (A Unit of Ginnow Prospecting 1 -NA-			
Detector System Panel Switch Panel	-NA-	-NA-	-NA-
Flow Switch PanelPA System Panel	-NA-	-NA-	-NA-
Battery backup	-NA-	-NA-	-NA-
Building Floor Plans	-NA-	-NA-	-NA-
Special Fire Protection System for Protection	of special Risks, if any:		-NA-
Special Fire Protection System for Frotection	or special -	t to I abooked as	nd found

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Accordingly DFA of form "H" is put up for approval and signature.

Signature of Inspecting Officer

Name: A. K. Malik Designation: DO (SD)

Dy. CFO (SZ)

slaph (2)

Cto CST

FT n.scell

12/1

Sity F.T. is putup for Sir plean

Ch(52)

MSCELL WEJI