GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001.

No. F.6/DFS/MS/EH/2018/SZ / & 6

Dated: /2/01/8

FIRE SAFETY CERTIFICATE

Certified that the **Mc Donald's Family Restaurant**, R-1, Janak Place, District Centre, Janak Puri, New Delhi 110058, is running at ground floor only. The above restaurant was issued FSC vide Letter No. F6/DFS/MS/EH/2014/SZ/1577 dated 15.12.2014 owned/ occupied by M/s Connaught Plaza Restaurant Pvt. Ltd. The Restaurant building was re-inspected by the officers concerned of this department on 27.12.2017 in the presence of Mrs. Megha (Manager) and found that the M/s Connaught Plaza Restaurant Pvt. Ltd. have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant building (at ground floor only) is fit for occupancy class Group D assembly building w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on 12/01/18 at New Delhi.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

The Manager, Mc Donald's Family Restaurant, R-1, ground floor only, Janak Place, District Centre, Janak Puri, New Delhi 110058. Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Restaurant at ground floor only

INSPECTION REPORT

1. Name & address of the building: Mc Donald's Family Restaurant, R-1, ground floor only, Janak

Place, Janakpuri District Centre, New Delhi 110058.

2. Type of Occupancy : Group D (Assembly)

3. Type of Case : Renewal

4. Details of Previous NOC : F6/DFS/MS/EH/2014/SZ/1577 dated 15.12.2014.

5. Fire Safety directives letter No: Nil.

6. Date of inspection : 27.12.2017

7. Name of Inspecting Officer : D.O. M.K. Chattopadhyay and A.D.O. Sandeep Duggal

8. Name and designation of officers

IS marking

From the building side : Mrs. Megha (Manager)

9. Year of Construction : Before 2007

S.		m Standards on fire prevention and fire	NBC/ BBL	Provided at	Remarks	
No.	safety I		Requirement	site	MR/NMR	
1.		to building		T		
	•	Road width	Accessible	12 mtrs Directly accessible	M/R	
	•	Gate width	4.5 mtrs N/A	from road	M/R	
	•	Width of internal road	IN/A	N/A	N/A	
2.	Number, Width, Type & Arrangement of Exits					
	a. Num	ber of staircases	1			
		Upper Floors	N/A	N/A	(Restaurant at Groun Floor only)	
	•	Basements	N/A	N/A	(Restaurant at Ground Floor only)	
	b. Wid	th of staircases	- x			
	•	Upper Floor	N/A	N/A	(Restaurant at Ground Floor only)	
	c Prote	Basements ection of exits	N/A	N/A	(Restaurant at Ground Floor only)	
		Fire check door	N/A	N/A	(Restaurant at Ground	
	•		N/A	N/A	(Restaurant at Ground	
	•	Pressurization			Floor only)	
	d. No.	of continuous staircases to	N/A	N/A	(Restaurant at Ground Floor only)	
	e. Wid	lth of Corridor	150 cms	Opening in	M/R, Being old	
	f. Do	or Size	100 01115	hall	case	
			Two Exits	207 cms (02 no.'s)	M/R	
	Compa	rtmentation	-	(Restaurant at Ground Floor only)		
	•	Fire check door	N/A	N/A	N/A	
	•	Sealing of electrical shafts	N/A	N/A	N/A	
		Fire Rating of shaft door Water Curtain	N/A 🦏	N/A	N/A	
	•	Fire Dampers	N/A	N/A	N/A	
		<u> </u>	N/A	N/A	N/A	
٠.	Smoke Management System					
	Baseme	ents	N/A	Exhaust Fans Provided	(Restaurant at Ground Floor only)	
	Upper f	loors	N/A	N/A	(Restaurant at Ground Floor only)	
	Fire Ext	tinguishers		(Restaurant a	at Ground Floor only)	
	Total n	ımbers	Six no's/floor	Provided	M/R	
	1 Ottal lit					

ha =	7. Na		K. Chattopadhyay a	nd A.D.O. Sandeep	Duggal
		me and designation of officers	1 (1)		
			egha (Manager)		
		al of construction	d 09.10.2017		
S.		m Standards on fire prevention and fire	NBC/ BBL	Provided at	Remarks
S. No.	safety U		Requirement	site	MR/NMR
1.		to building			
1.	_	Road width	Accessible	12 mtrs	M/R
		Gate width	4.5 mtrs	Directly accessible	M/R
		Width of internal road	N/A	from road	N/A
				N/A	
2.		r, Width, Type & Arrangement of Exits			
	a. Num	ber of staircases	N/A	N/A	(Restaurant at Ground
		Linnar Floors	IN/A	IN/A	Floor only)
		Upper Floors Basements	N/A	N/A	(Restaurant at Ground
		Basements	<u> </u>		Floor only)
	b Widt	th of staircases		27/4	(Restaurant at Ground
	U. Wild	Upper Floor	N/A	N/A	Floor only)
	1	opper rises	N/A	N/A	(Restaurant at Ground
	•	Basements	11/11	1,17	Floor only)
	c. Prote	ection of exits			
			N/A	N/A	(Restaurant at Ground Floor only)
	•	Fire check door	N/A	N/A	(Restaurant at Ground
			N/A	IN/A	Floor only)
	•	Pressurization			
	1 N.	of continuous staircases to	N/A	N/A	(Restaurant at Ground
		1			Floor only)
	terr	ace Ith of Corridor	150 cms	Opening in	M/R, Being old
		and the second s	150 cms	hall	case
	f. Do	or Size	Two Exits	207 cms	M/R
			I WO LAILS	(02 no.'s)	
2	Compo	rtmentation			Ground Floor only)
3.	Compa		N/A	N/A	N/A
	•	Fire check door			
	•	Sealing of electrical shafts	N/A	N/A	N/A
	•	Fire Rating of shaft door	N/A	N/A	N/A
	•	Water Curtain	N/A	N/A	N/A
	•	Fire Dampers	N/A	N/A	N/A
4.	Smoke	Management System			
4.			N/A	Exhaust Fans	(Restaurant at
	Basem	ents	14/71	Provided	Ground Floor only)
N	Upper	floors	N/A	N/A	(Restaurant at
	Opper	110013			Ground Floor only)
	D' D	· · · · · · · · · · · · · · · · · · ·		(Restaurant	at Ground Floor only)
5.	Fire Ex	ktinguishers		(Itobiani mir	,
	Total	numbers	Six no's/floor	Provided	M/R
	Types	initioots	ABC/CO ₂	Provided	M/R
	IS mar	king	TOY 1	ISI marked	M/R
			ISI marked		
6.	First-A	Aid Hose Reels		(Kestaurant at	Ground Floor only)
		1.0	One	Provided	M/R
		numbers on ground floor	One	Provided	M/R
		of hose reel hose	30 mtrs 5 mm		
	Nozzle	e diameter	J IIIII	Provided	M/R

1				
Restaurant	at	ground	floor	only

7.	Automatic fire detection and alarming system			Ground Floor only)		
	Type of detectors	Smoke & Heat	Provided	M/R		
	Location of Main Panel (Common with Janak Place)	Required	G. Floor	M/R		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	Required -	Provided	M/R		
	Hooters' Location	Required	Near exits	M/R		
8.	MOEFA	Required	Provided	M/R		
9.	Public Address System	Required	Provided	M/R		
10.	Automatic Sprinkler System	× .				
	Basement	N/A	N/A	(Restaurant at Ground Floor only)		
	Ground Floor	Required	Provided	M/R		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11.	Internal Hydrants (Restaurant at Ground Floor only)					
	Size of riser/down-comer	N/A	Provided	M/R		
	Number of hydrants	N/A	Provided	M/R		
	Hose Box	N/A	Provided	M/R		
12.	Yard Hydrants					
	Total number of hydrants	N/A	one	M/R		
	Hose Box	N/A	one	M/R		
13.	Pumping Arrangements (common with Janak Place)					
	Ground Level		i			
	Discharge of main Pump	2400 LPM	Provided	M/R		
	Head of Main pump	88 mtrs	Provided	M/R		
	Number of main pumps	01	Provided	M/R		
	Jockey Pump out put Jockey pump head	240 LPM	Provided	M/R		
	society pump near	88 mtrs	Provided	M/R		
	Standby Pump out put	2400 LPM	Provided	M/R		
	Standby Pump Head	88 mtrs	Provided	M/R		
	Auto Starting/Manual Stopping			M/R		
		Both	Provided Provided	M/R M/R		
	Pump House Access	Required	Provided	IVI/ K		
	Terrace level	N/A	N/A	N/A		
	Discharge of pump	N/A	N/A	N/A		
	Head of the pump	Required	Provided	M/R		
	Power Supply Auto Starting of pump	N/A	N/A	N/A		
14.	Captive Water Storage for fire fighting (common with Janak Place)					
	Underground tank capacity	Required	200000 Ltrs	M/R		
	Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	Access to tank	Required	Provided	M/R		
	Overhead Tank capacity	N/A	N/A	N/A		
15.	Exit Signage.	N/A Required	Provided	M/R		
16.	Provision of Lifts.	(Re	staurant at Groun	Floor only)		
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift Shart Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		

	Hooters Location	_ I	Near exits	M/K		
	MOEFA	Required	Provided	M/R		
	Public Address System	Required	Provided	M/R		
0.	Automatic Sprinkler System					
	Basement	N/A	N/A	(Restaurant at Ground Floor only)		
	G 1 FI	Required	Provided	M/R		
	Ground Floor Sprinkler above false ceiling	N/A	N/A	N/A		
1.	Internal Hydrants (Restaurant at Ground Floor only					
		N/A	Provided	M/R		
	Size of riser/down-comer	N/A	Provided	M/R		
	Number of hydrants Hose Box	N/A	Provided	M/R		
2.	Yard Hydrants			7		
	Total number of hydrants	N/A	one	M/R		
	Hose Box	N/A	one	M/R		
3.	Pumping Arrangements		(common with J	anak Place)		
	Ground Level		D 11.1	M/D		
	Discharge of main Pump	2400 LPM	Provided	M/R		
	Head of Main pump	88 mtrs	Provided	M/R		
	Number of main pumps	01	Provided	M/R		
	Jockey Pump out put Jockey pump head	240 LPM	Provided	M/R		
	Jockey pump nead	88 mtrs	Provided	M/R		
	Standby Pump out put	2400 LPM	Provided	M/R		
	Standby Pump Head	88 mtrs	Provided	M/R		
	Auto Starting/Manual Stopping	Both	Provided	M/R		
		Required	Provided	M/R		
	Pump House Access	1				
	Terrace level	N/A	N/A	N/A		
	Discharge of pump	N/A	N/A	N/A		
	Head of the pump	Required	Provided	M/R		
	Power Supply Auto Starting of pump	N/A	N/A	N/A		
			(common y	with Janak Place)		
14.	Captive Water Storage for fire fighting	D 11	200000 Ltrs	M/R		
	Underground tank capacity	Required	N/A	N/A		
	Draw-off connection	N/A		N/A		
	Fire service inlet Access to tank	N/A	N/A	M/R		
	Overhead Tank capacity	Required	Provided			
	Overhead Tank capacity	N/A	N/A	N/A M/R		
15.	Exit Signage.	Required	Provided	IVI/ K		
16.	Provision of Lifts.	Provision of Lifts. (Restaurant at Ground Floor only)				
10.	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
		Required	Provided	M/R		
17.	Standby power supply	Roquitou		And the second s		
18.	Refuge Area.		>T/A	NI/A		
18.	Total Area	N/A	N/A	N/A		
	Total Area					

2)15

Restaurant at ground floor only

19.	Fire Control Room	27/4	Decement	NI/A
Detect	Detector System Panel	N/A	Basement	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel Battery backup	N/A	N/A	N/A
	Building Floor Plans	Required	Provided	M/R
		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter number F6/DFS/MS/EH/2014/SZ/1577 dated 15.12.2014 renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Note :-Restaurant is having common fire fighting system with the Janak Place Building and restaurant manager has submitted the letter regarding the same.

Signature of Inspecting Officer Name: - M.K. Chattopadhyay

Designation:- Divisional Officer

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer