GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No.F6/DFS/MS/SCHOOL/2018

101

Dated: 17 01/8

FIRE SAFETY CERTIFICATE

> (Vipin Kental) Chief Fire Officer Delhi Fire Service

Copy to:

- 1. The Director Shadhra Angels Educational Society Plot no. B-12 & B-20, Vasundhara Enclave, Delhi- 32.
- 2. Director of Education GNCT of Delhi, Old Secretariat Delhi- 54.

- Conditions -

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in good working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. "The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form'J'[sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"

NIZ

1. Name & address of the building : Shahdara Angels Educational Society (Regd.)

Plot No. B-12 & B-20, Vasundhara Enclave, Delhi.

2. Building is comprised of : Basement, Ground plus four upper floor. H=18M

Type of Occupancy : Educational

4. Type of Case : Renewal (addition/alteration)

5. Details of Previous FSC letter : F.-6/DFS/School/2014/NDZ/821 dated 02/07/14

6. Fire Safety circular No : F.6/DFS/MS/BP/2013/351 Dated: 27.11.2013

7. Date of Inspection : 04/01/20188. Name of the Inspecting officers : DO F.Brown

9. from the building side : Sh. Sushant Raghav (Administration Head)

10. Year of Construction : (G+2) 2005, & (III & IV floor) ,2017

11. Applicant's letter No : SAES/110/2017 dated 15.12.2017.

S.No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement	Provided at Site	Remark		
1	Access to building		Site	MR/NMR		
	Road width	06 Mtrs	40 104			
	Gate width		18 Mtrs	M/R		
	Width of internal road	4.5 Mtrs	4.5 Mtrs	M/R		
0		6 M	6 M	M/R		
2	Number, Width, Type and Arrangement of Exits					
	a. Number of Staircases					
	Upper Floor	03 no.	03 no.	M/R		
	Basement	03 no.	04 no. + 2 ramp	M/R		
	B. Width of Staircases			101/12		
	 Upper Floor 	1.5 m	1.5 m	M/R		
	Basement	1.5 m	1.5 m	M/R		
	c. Protection of exits		1.0 111	101/13		
	Fire check door	Required	Provided	M/R		
	Pressurization	N/A	N/A	N/A		
	e. No. of continuous staircases to terrace	01 no.	03 no.	M/R		
	g. Width of Corridor	1.5 m	2.0 m	M/R		
	h. Door Size	1.0 m	1.0 m	M/R		
3	Compartmentation.		1.0 111	IVI/IX		
	 Fire check door 	Required	Provided	M/R		
	 Sealing of electrical shafts 	Required	Provided	M/R		
	 Fire rating of shaft door 	Required	Provided	M/R		
	 Water curtain 	N/A	N/A	N/A		
	 Fire Dampers 	N/A	N/A	N/A		
	Smoke Management System.		14// (IN/A		
	Basement	Required	Provided	MID		
	 Upper floor 	N/A	N/A	M/R		
	Fire Extinguishers	1471	IN/A	N/A		
	 Total numbers 	20 Nos.	30 Nos.	M/R		
	• types	ABC & Co2	ABC & Co2	M/R		
	ISI marking	ISI marked	ISI marked	M/R		

6	First-aid-Hose Reels.						
	Total numbers of each floor	02no					
	 Length of hose reel hose 		02no	M/			
	Nozzle diameter	30M	30M	M/			
7		5 mm	5 mm	M/			
	Automatic fire detection and alarming system.						
	 Type of detectors 	N/A	N/A	N/			
	 Location of main panel 	N/A	N/A	N/			
	 Location of repeater panel 	N/A	N/A	N/			
	Alternate source of power	N/A	N/A	N/			
_	Hooter's location	Staircase	Provided	*			
8	MOEFA	Required	Provided	M/			
9	Public address System.	Required	Provided	M/			
10	Automatic Sprinkler System.		TTOVIded	M/I			
	 Basement 	Required	Provided	M/F			
	 upper floor 	N/A	N/A				
	sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants	1477	IN/A	N/A			
	 size of riser/down-comer 	150mm	150mm	B.A.C			
	 Number of hydrants per floor 	02 no.	02 no.	M/F			
	 Hose Box 	02 no.	02 no.	M/F			
2	Yard Hydrants.	52 110.	02 110.	M/F			
	 Total number of hydrants 	02	02	B # / F			
	Hose Box	02	02	M/R			
3	Pumping Arrangements.	02	02	M/R			
	Ground Level	N/A	Provided	NI/A			
	Discharge of main Pump	N/A	900 LPM	N/A			
	Head of Main Pump	N/A	40 M	N/A			
_	Number of main pumps	N/A	01 No.	N/A			
	Jockey pump out put	N/A	450 LPM	N/A			
-	Jockey pump head	N/A	40 M	N/A			
-	Standby pump out put	N/A	N/A	N/A N/A			
+	Standby pump Head	N/A	N/A	N/A			
	> Auto Starting /Manual	Required	Provided	M/R			
+	stopping > Pump House Access			IVI/IX			
+	Timp House Access	N/A	Provided	M/R			
+	TOTAGE LEVEL						
+	Discharge of pump	900LPM	900LPM	M/R			
+	➢ Head of the Pump ➢ Power supply	40M	40M	M/R			
	Power supply	Required	provided	M/R			
	Auto Starting of pump	Required	provided	M/R			
(Captive Water Storage for Fire Fighting.						
	Underground tank capacity	N/A	50,000 Ltrs.	A1/A			
	Draw-off connection	N/A		N/A			
	Fire service inlet	N/A	provided	N/A			
+	Access to tank	N/A	provided	N/A			
	Overhead Tank capacity xit Signage.	25,000 Litrs	provided 25,000 Litrs	N/A M/R			
-							

10	Description of Life			
16	Provision of Lifts.	<u>'</u>		
	 Pressurization of Lift Shaft 	N/A	N/A	N/A
	 Pressurization of Lift lobby 	N/A	N/A	N/A
BELLEVINE	 Communication in lift car 	N/A	N/A	N/A
	 Firemen's grounding switch 	N/A	N/A	N/A
OLAN-	 Lift Signage 	N/A	N/A	N/A
17	Standby power supply	Required	provided	M/R
18	Refuge Area.	N/A	N/A	N/A
	Total area	N/A	N/A	N/A
	 Location 	N/A	N/A	N/A
19	Fire Control Room	Required	provided	M/R
	 Detector system panel 	Required	provided	M/R
	 Flow switch panel 	Required	provided	M/R
	 PA system panel 	Required	provided	M/R
	 Battery backup 	Required	provided	M/R
2	 Building Floor Plans 	Required	provided	M/R
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The Fire protection systems provided in the building were tested / checked and found functional, at the time of inspection.

Keeping in view, of the deemed compliance, of the minimum standards on Fire prevention and Life safety measures as required under the rules. The Fire safety Certificate issued for Basement, ground plus two upper floor vide letter no.F.6/MS/School/2014/NDZ/821 dated 02/07/2014 and renewal for basement ground and four upper floor under the direction letter no F.6/DFS/MS/BP/2013/351 dated 27.11.2013, is recommended to renewal Fire Safety Certificate, under rule 37 of the Delhi Fire Service Rule 2010.

Submitted for approved plean.

Signature of the Inspecting Officer Name: Francis Brown

Designation: DO (East)

Spoken, And CF.O. FTM. 4571 m.sey

Ft lella is Propus and put up for BIS natur plan. 0001116