GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

Fax No. 011-23412593, Ph. 011-23412225

No. F.6 DFS/MS/School/2018/SZ/ 153

Dated: 23/11/8

FIRE SAFETY CERTIFICATE

Certified that **Tinu Public School** located at **B-5/1189**, **Sangam Vihar**, **New Delhi-110080** comprised of four building blocks each **Ground plus three upper floors** was issued Fire Safety Certificate by this department vide letter No. F.6/MS/DFS/School/2014/SZ/1447 Dated 25/11/2014. The school premises was re-inspected by officer concerned of this department on 11/01/2018 in presence of Mr. D.P. Siwas (Manager) of the school and found that the said School building have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education Circular No. F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by Director of Education, Govt. of NCT of Delhi and that the building/premises is fit for occupancy class "**Educational Building**" Group-B, with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 23/1/16 at New Delhi by

(Vipin Kental) Chief Fire Officer

Copy to: -

- 1. The Manager, Tinu Public School, B-5/1189, Sangam Vihar, New Delhi-110080
- 2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

1	Name & Address of the Building	TINU PUBLIC	SCHOOL R-5/1189		
1	Name & Address of the Building	TINU PUBLIC SCHOOL, B-5/1189, SANGAM VIHAR, NEW DELHI-110080 Educational Building "Group-B"			
2	Type of Occupancy				
3	Building Comprised of	Ground plus three upper floors. (Four Blocks)			
4	Type of Case	Renewal			
5	Details of Previous NOC		chool/2014/SZ/1447 Dt. 2	5/11/2014	
6	Fire Safety Directives Letter No		No 262-362 dated 17/01/2		
7	Date of Inspection	11-01-2018		Z X X	
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)			
9	Name & Designation of	Mr. D.P. Siwas (Manager)			
	Officers from the building side				
10	Year of construction	2009		<	
11	Applicant letter No.	TPS/FSC/01/2017 dated 04-12-2017			
S. No	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remark	
	and Fire Safety U/R 33	requirement		MR/NMI	
1	Access to Building.				
	Road width	Required	6 mtr	MR	
	Gate width	Required	4.5 mtr	MR	
	Width of internal road	N/A	N/A	N/A	
2	Number, width, type & arrangement of exits				
	a) Number of Staircase				
	> Upper floors	Two each block	Provided	MR	
	Basement floor	N/A	N/A	N/A	
	b) Width of Staircase				
	> Upper floors	1.5m / 0.75m	Bk 1 (1.25, 1.0m), Block 2&3	(1.4, MR	
			1.5m each), Bk 4- 1.15, 1.06n		
	> Basement floor	N/A	N/A	N/A	
	c) Protection of exits				
	Fire check door	N/A	N/A	N/A	
	Pressurization	N/A	N/A	N/A	
	d) No. of continuous staircase to terrace	Required	One in each block	MR	
	e) Width of corridor	N/A	N/A	N/A	
	f) Door size	1m	Provided	MR	
3	Compartmentation.				
	Fire check door.	N/A	N/A	N/A	
	 Sealing of electrical shafts. 	N/A	N/A	N/A	
	 Fire rating of shaft door. 	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
	Fire dampers.	N/A	N/A	N/A	
4.	Smoke Management system.			,	
	Basement	30 ACPH	N/A	N/A	
	Upper floors	12 ACPH	N/A	N/A	
				1	
5.	Fire Extinguishers.		30 Nos	MR	
5	Fire Extinguishers. • Total numbers	Required	30 1103	1411/	
5.	Total numbers	Required ABC / Co2			
5.	Total numbersTypes	ABC / Co2	ABC type	MR	
3	Total numbersTypesISI Marking				
5.	 Total numbers Types ISI Marking First Aid Hose Reels. 	ABC / Co2	ABC type Provided	MR MR	
8)	Total numbersTypesISI Marking	ABC / Co2 ISI marked	ABC type Provided 04 Nos	MR MR MR	
31	 Total numbers Types ISI Marking First Aid Hose Reels. 	ABC / Co2	ABC type Provided	MR MR	

Tinu Public School, B-5/1189, Sangam Vihar, New Delhi-110080

7	Automatic fire detection & alarming system		· ·	
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			14/11
	Basement	Required	Provided	MR
	Upper floors	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants.			
	Size of Riser/Down-comer	N/A	100 mm	MR
	 Number of Hydrant per floor 	N/A	04 Nos	MR
	Hose box.	N/A	04 Nos	MR
12.	Yard Hydrants.	27/22	1 011103	14117
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	
13.	Pumping arrangements.	14/74	IN/A	N/A
13.	Ground Level			
	> Discharge of main pump.	NI/A	NI/A	21/4
	Head of main pump.	N/A N/A	N/A	N/A
	Number of main pumps.		N/A	N/A
	Jockey Pump output.	N/A N/A	N/A	N/A
	Jockey Pump head.	N/A N/A	N/A	N/A
	Standby Pump output.	N/A N/A	N/A	N/A
	Standby pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
	Terrace Level	IV/A	N/A	N/A
	Discharge of pump.	450 LPM	450 LPM x 2 provided	MR
	Head of pump.	40m	40m each	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for Fire Fighting.	1	- 1011000	1111
•	Underground tank capacity.	N/A	N/A	N/A
	Draw-off connection.	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
and the state of t	Access to tank.	N/A	N/A	N/A
	 Overhead tank capacity. 	10,000 Ltr	25,000 Ltr	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provisions of Lifts.	•		
	 Pressurization of lift shaft. 	N/A	N/A	N/A
	 Pressurization of lift lobby. 	N/A	N/A	N/A
	 Communication in lift car. 	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	N/A	N/A	N/A
8.	Refuge Area		1	4 11 4 1
	Total area	N/A	N/A	N/A
	• Location	N/A	N/A	
	Tinu Public School, B-5/1189, Sa			N/A

Tinu Public School, B-5/1189, Sangam Vihar, New Delhi-110080

19.	Fire Control Room.	The state of the s		
	Detector System Panel.	N/A	N/A	N/A
	 Flow Switch Panel. 	N/A	N/A	N/A
	PA system Panel.	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection. Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under Directorate of Education circular, Fire Safety Certificate issued vide letter No. F.6/DFS/MS/School/2014/SZ/1447 dated 25/11/2014, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: R.N. Singh Designation: ADO (BCP)

Tinu Public School, B-5/1189, Sangam Vihar, New Delhi-110080

DO (SD)

STA Mischell FTM.

18/1

FT lefter is put up for significal huming 19/1

Mischell We 19/1