GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/Hospital/2018/SZ / 142

Dated: 23/1/18

FIRE SAFETY CERTIFICATE

Certified that the Rosewood Hospital (A unit of J.L.K.D. Healthcare Pvt. Ltd.), Plot No.-5, J-L Block, Roshan Garden, New Delhi-110043 comprised of lower ground, ground floor plus two upper floors owned/occupied by Rosewood Hospital (A unit of J.L.K.D. Healthcare Pvt. Ltd.). The Hospital building was inspected by the officers concerned of this department on 12.01.2018 in the presence of Sh. Naveen Dabas (Director) and found that Rosewood Hospital (A unit of J.L.K.D. Healthcare Pvt. Ltd.) have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class Group-C "Institutional Building" Sub. Div. C-1 w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

(VIPIN KENTAL) CHIEF FIRE OFFICER

9c da 22/1/2016

Copy to:-

Sh. Naveen Dabas (Director), Rosewood Hospital (A unit of J.L.K.D. Healthcare Pvt. Ltd.), Plot No.-5, J-L Block, Roshan Garden, New Delhi-110043

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT 1. Name & address of the building: Rosewood Hospital (A unit of J.L.K.D. Healthcare Pvt. Ltd.), Plot No.-5, J-L Block, Roshan Garden, New Delhi-110043. Institutional Type of Occupancy 3. Type of Case New 4. Details of Previous NOC N/A F.6/DFS/MS/BP/2016/898 dated 08.4.2016 5. Fire Safety directives letter No 6. Date of inspection 12.01.2018 D.O M.K. Chattopadhyay & A.D.O. Sandeep Duggal 7. Name of Inspecting Officers Name and designation of officers From the building side Sh. Naveen Dabas (Director) 9. Year of Construction 2014 Nil dated Nil 10. Applicant's letter No. Minimum Standards on fire prevention and NBC/BBL Provided at Remarks S. No. MR/NMR fire safety U/R 33 Requirement site

	The salety O/R 33	1tequil ement	Site	TITLE TO THE TENE		
1.	Access to building					
	Road width	09 mtrs	Provided	M/R		
	• Gate width	05 mtrs.	Provided\	M/R		
	Width of internal road	N/A	N/A	N/A		
2.	Number, Width, Type & Arrangement of Ex	its				
	a. Number of staircases					
	Upper Floors	02 No's	02 No's	M/R		
	Basements	N/A	N/A	N/A		
	b. Width of staircases		200 (02 1)	16/20		
	Upper Floor	200 cms	200 cms (02 no.'s)	M/R		
	Basements	N/A	N/A	N/A		
	c. Protection of exits					
	Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A	N/A		
	d. No. of continuous staircases to	Domino d	Two	M/R		
	terrace	Required				
	e. Width of Corridor	240 cms	270 cms	M/R		
	f. Door Size of ward	200 cms & 125 cms	200 cms & 125 cms	M/R		
3.	Compartmentation					
	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
	Fire Rating of shaft door	N/A	N/A	N/A		
	• Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System		98 40 50 50			
	Basements	N/A	N/A	N/A		
	• Upper floors	Required	Natural ventilation	M/R		
5.	Fire Extinguishers					
	Total numbers	20 no's	Provided	M/R		
	Types	ABC/CO ₂ type	Provided	M/R		
	IS marking		ISI marked	M/R		
		ISI marked	151 marked	1VI/ IX		
6.	First-Aid Hose Reels					
	Total numbers on each floor	One	Provided	M/R		
	Length of hose reel hose	30 mtrs	Provided	M/R		
	Nozzle diameter	5 mm	Provided	M/R		

Building is comprised of Lower Ground, Ground plus two upper floors and terrace. Automatic fire detection and alarming system 7. M/R Required Provided Type of detectors (Smoke/Heat) Location of Main Panel N/A N/A N/A Location of Repeater Panel N/A N/A N/A Alternate source of power Required Provided M/R Hooters' Location Required Provided M/R Provided M/R Required **MOEFA** 8. N/A N/A N/A 9. **Public Address System** 10. **Automatic Sprinkler System** N/A N/A N/A Basement Provided in LG M/R Required Lower Ground/Upper Floor N/A Sprinkler above false ceiling N/A N/A **Internal Hydrants** 11. M/R Required 100 mm Size of riser/down-comer Provided M/R One Number of hydrants per floor One Provided M/R Hose Box **Yard Hydrants** 12. N/A N/A N/A Total number of hydrants N/A N/A N/A Hose Box **Pumping Arrangements** 13. Ground Level M/R Discharge of main Pump 1620 LPM Provided Head of Main pump > M/R Provided 50 mtrs Number of main pumps M/R One Provided Jockey Pump out put Provided M/R 180 LPM Jockey pump head Standby Pump out put M/R 50 mtrs Provided Standby Pump Head M/R 1620 LPM Provided > Auto Starting/Manual Stopping 50 mtrs Provided M/R Required Provided M/R M/R Required Provided Pump House Access Terrace level N/A N/A N/A Discharge of pump N/A N/A N/A > Head of the pump N/A Power Supply N/A N/A ➤ Auto Starting of pump N/A N/A N/A Captive Water Storage for fire fighting 14. M/R 50,000 ltrs Provided Underground tank capacity Draw-off connection Provided M/R Required Fire service inlet Required Provided M/R Access to tank Required Provided M/R Overhead Tank capacity 5,000 ltrs Provided M/R M/R Required Provided 15. Exit Signage. Provision of Lifts. 6. N/A N/A N/A Pressurization of Lift Shaft Pressurization of Lift lobby N/A N/A N/A Communication In lift Car Required Provided M/R Fireman's Grounding Switch M/R Provided Required Lift Signage Provided M/R Required M/R Required Provided 17. Standby power supply 18. Refuge Area. > Total Area N/A N/A N/A

Building is comprised of Lower Ground, Ground plus two upper floors and terrace.

9.	Fire Control Room Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Name: - M.K. Chattopadhyay

Designation: - Divisional Officer (SW)

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer (JKP)

Dy. C.F.O. (South Zone)

Goods of misfell we 18/1

F.T. letter is put up for Sign. pleme

22/1/2018

CFO (Souta) M. SCELL Le