## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/Bnqt/2018/ 12-3

Dated: 22/01/18

## **FIRE SAFETY CERTIFICATE**

Certified that the J B Jashn The Banquet running on first floor of the building comprised of three basement, ground plus four upper floors at 813/1, Vikas Cine Mall, G. T. Road, Shahdara, Delhi -110032 owned/occupied by M/s J B Jashn The Banquet was issued FSC vide letter No. F6/DFS/MS/Banquet/2014/NDZ/1513 dated 03/12/14. The premises was re-inspected by officer concerned of this department on 05/01/2018 in the presence of Mr. Ajay Garg, partner of the Banquet Hall and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and found that the first floor of Banquet Hall building is fit for occupancy Group "D" Assembly Building with effect from ... 222 e.l.) ... for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, subject to conditions printed overleaf.

Issued on. 22/51/19 at New Delhi by

(Vipin Kental) Chief Fire Officer

To,

Mr. Ajay Garg (Partner), M/s J B Jashn The Banquet (A unit of ARS Enterprises) 813/1, Vikas Cine Mall, G. T. Road, Shahdara, Delhi -110032

Copy:-

The Dy. Health Officer, East Delhi Municipal Corporation, Health Department, Karkardooma, North Zone, Shahdara, Delhi. ole of

## **CONDITIONS**

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry

ADO 18

813/1, Vikas Cine Mall, G T Road, Shahdara,

Delhi-110032

2. Building is comprised of

: Three Basements and Ground plus four upper floors

3. Type of Occupancy

: Assembly Building (Banquet Hall) at first floor 💸

4. Type of Case

: Renewal

5. Details of Previous NOC letter

: F6/DFS/MS/Banquet/2014/NDZ/1513 dt 03/12/14

6. Fire Safety directives letter No

: F.6/DFS/BP/2013/1790 dated 12/07/2013

7. Date of Inspection

: 05/01/2018

8. Name of the Inspecting officers

: ADO Vijay Bahadur

9. Name and designation of Officer

from the building side

: Mr. Ajay Garg (Partner)

10. Year of Construction

: 2012

11. Applicant's letter No

: Letter No.-Nil, Dated- 15/12/17

Sr.	Minimum Standards on Fire	Directives	Provided at Site	Remarks			
No.	Prevention and Fire Safety U/R33	Requirement		MR/NMR			
01	Access to Building.						
0.00	<ul> <li>Road width</li> </ul>	12 mtr.	39 mtr.	MR			
	<ul> <li>Gate width</li> </ul>	4.50 mtrs	4.50 mtrs	MR			
	<ul> <li>Width of internal road</li> </ul>	06 mtrs	06 mtrs	MR			
02	Number, Width, Type and Arrangement of Exits.						
	a. Number of Staircases						
	Upper floor	05 nos.	05 nos.	MR			
	Basement	05 nos.	05 nos. + 01 ramp	MR			
	b. Width of Staircases						
	Upper floor	1.50 mtr & 02 mtrs	1.50 mtr & 02 mtrs	MR			
	Basement	1.50 mtr	1.50 mtr & 02 mtrs	MR			
	c. Protection of Exits			. 8			
	Fire check door	Required	Provided	MR			
	<ul> <li>Pressurization</li> </ul>	Required	Provided	MR			
	d. No. of Continuous Staircases to Terrace	02 nos.	02 nos.	MR			
	e. Width of Corridor	1.50 mtr & 02 mtrs	1.50 mtr & 02 mtrs	MR			
	f. Door Size	01 mtr & 02 mtr.	(2 down) (2 downs)	MR			
03	Compartmentation.						
	Fire check door	Required	Provided	MR			
	Sealing of electrical shafts	Required	Provided	MR			
	Fire rating of shaft door	1 & 2 hrs	Provided	MR			
	Water curtain	N/A	N/A	N/A			
	Fire dampers	Required	Provided	MR			
04	Smoke Management System.						
	Basement	Required	Provided	MR			
	Upper floor	Required	Provided	MR			
05.	Fire Extinguishers.						
	Total numbers	06 nos.	10 nos.	MR			
-	• types	ABC /CO <sub>2</sub>	Not Provided	MR			
	ISI marking	ISI marked	Not Provided	MR			

\*\* This Boughet Hall is on first floor of cinewall building. Fee for cinewall Bldg. has bean issued a valid ripto mue 2019.

06	First-Aid-Hose Reels.			
	Total numbers on each floor	03 No.	03 No.	MR
	Length of hose reel hose	30 mtr.	30 mtr.	MR
	Nozzle diameter	05 mm	05 mm	MR
07	Automatic Fire Detection and Alarming Sys	stem.		
	Type of detectors	Heat &	Provided	MR
	• Type of detectors	Smoke		
,	Location of main panel	Basement	Provided	MR
	Location of repeater panel	Security	Provided	MR
		room		
	<ul> <li>Alternate source of power</li> </ul>	Battery &	Provided	MR
		DG Set	D 11-1	MD
	Hooter's location	Staircase	Provided Provided	MR MR
08	MOEFA	Required	Provided	MR
09	Public Address System.	Required	Provided	IVIIX
10	Automatic Sprinkler System.			
	Basement	Required	Provided	MR
42	• upper floor	Required	Provided	MR
	sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants			
	size of riser/down-comer	150 mm	150 mm	MR
	Number of hydrants per floor	03 No.	03 No.	MR
	Hose box per,floor	03 No.	03 No.	MR
12	Yard Hydrants.		(1.00 to 1.00	
12		04 nos	07 nos	MR
	Total number of hydrants	04 nos	07 nos	MR
	Hose box	04 1103		
13	Pumping Arrangements.			
	Ground Level			
	Discharge of main pump	2850 Lpm.	2850 Lpm.	MR
-	Head of Main pump	70 M	70 M	MR
	Number of main pumps	02 No.	02 No. 180 Lpm.	* MR
	<ul> <li>Jockey pump out put</li> </ul>	180 Lpm.	70 M	MR
	Jockey pump head	70 M 2850 Lpm.	2850 Lpm.	MR
	Standby pump out put	70 M	70 M	MR
	Standby pump head	Required	Provided	MR
	Auto starting /manual stopping	Required	Provided	MR
	<ul><li>Pump house access</li><li>Terrace Level</li></ul>			
		N/A	N/A	N/A
	Discharge of pump	N/A	N/A	N/A
	Head of the Pump	N/A	N/A	N/A
	Power supply     Auto Starting of pump	N/A	N/A	N/A
4.4	<ul> <li>Auto Starting of pump</li> <li>Captive Water Storage for Fire Fighting.</li> </ul>	:		
14		2,00,000 ltr.	2,00,000 ltr	MR
	Underground tank capacity	Required	Provided	MR
	Draw-off connection  Fire parties inlet	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	<ul><li>Access to tank</li><li>Overhead Tank capacity</li></ul>	20,000 ltr.	25,000 ltr.	MR
15	Exit Signage.	Required	Provided	MR
15 16	Provision of Lifts.	L. L. L.		
10		Required	Provided	MR
	<ul><li>Pressurization of Lift Shaft</li><li>Pressurization of Lift lobby</li></ul>	Required	Provided	MR
	oindian in lift car	Required	Provided	MR
	E:	Required	Provided	MR
	Lift Signage	Required	Provided	MR
	Lift Olymago		The state of the state of	1

17	Standby Power Supply	Required	Provided	MR
18	Refuge Area.	1 -1		
	Total area	N/A	N/A	N/A
19	Location  Fire Control Room	N/A	N/A	N/A
	<ul><li>Detector system panel</li><li>Flow switch panel</li></ul>	Required	Provided	MR
		Required	Provided	MR
	PA system panel	Required	Provided	MR
	Battery backup	Required	Provided	MR
		Required	Provided	MR
20	Danding 1 1001 1 1alls	Required	Provided	MR
20	Special Fire Protection Systems for Protection of Special Risks, if any:	Required	Provided	MR

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection. Fire Safety Certificate for the main building was issued in 2016.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to issue Fire Safety Certificate. The Cinemall Building has been issued for while Letter NO F6/DFSIMS/2016/1027 duted 13/6/16.

Signature of the Inspecting Officer

Name

:- Vijay Bahadur

Designation :- A.D.O

Six, FT letter io put up for signature placerse

miscell le