

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

No. F.6/DFS/MS/EH/2018/SZ/ 105

Dated: 18/11/18

FIRE SAFETY CERTIFICATE

Certified that the Restaurant in the name & style of **M/s Domino's Pizza** located at FC-2, DLF Place Mall, Plot No-3, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070, comprised of **Two tier Basement, Lower ground, Upper ground, First floor & Projection room** was inspected by the officer concerned of this department on 28/12/2017 in the presence of Mr. Nitin (Manager) of the restaurant and observed that the said restaurant premise have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class-D "**Assembly**" as above with effect from the date of issue of this certificate for a period of **Three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on 18/11/18 at New Delhi by


(Vipin Kental)
Chief Fire Officer

Copy to: -

1. The DHO (SZ), South MCD, Public Health Deptt, Green Park, New Delhi-110016
2. M/s Domino's Pizza at FC-2, DLF Place Mall, Plot No-3, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070

Conditions for the validity of Fire Safety Certificate


1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of firefighting system.
4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

| INSPECTION REPORT | | | |
|-------------------|---|--|--|
| 1 | Name & Address of the Building | M/S Domino's Pizza, at FC-2, DLF Place Plot No-3, Nelson Mandela Marg, Vasant Kunj, New Delhi. | |
| 2 | Type of Occupancy | Assembly buildings 'Group-D' | |
| 3 | Building comprised of | 02 basements, LGF, UGF, 1 st floor+ projection room. | |
| 4 | Type of Case | New | |
| 5 | Details of Previous NOC | Nil | |
| 6 | Fire Safety Directives Letter No | Cir. No. 4/22/2004/HP-III/356 -369 Dt. 22-03-2005 | |
| 7 | Date of Inspection | 04-01-2018 | |
| 8 | Name of the Inspecting Officers | R.N. Singh, ADO (BCP) | |
| 9 | Name & Designation of Officers from the building side | Mr. Nitin (Manager) | |
| 10 | Year of construction | 2005 Restt running at 1 st floor of mall building | |
| 11 | Applicant letter No. | 2527/Addl. C.P/Lic./EH (DA-III) Dt. 03/11/2017 | |
| S. No | Minimum standards on Fire Prevention and Fire Safety U/R 33 | As per Circular (22/03/2005) | Remarks MR/NMR |
| 1 | Access to Building. | F.6/DFS/MS/Mall/SZ/2017/857 dated 15/06/2017 | |
| | <ul style="list-style-type: none"> Road width Gate width Width of internal road | Restt within DLF Place Mall | 9 mtr N/A N/A MR N/A N/A |
| 2 | Number, width, type & arrangement of exits | | |
| | a. Number of Staircase | Provided & Maintained by Mall Mgmt | |
| | <ul style="list-style-type: none"> Upper floors Basement floor | Required | Two provided near restt N/A MR N/A |
| | b. Width of Staircase | Provided & Maintained by Mall Mgmt | |
| | <ul style="list-style-type: none"> Upper floors Basement floor | 1.5m N/A | As above As above MR N/A |
| | c. Protection of exits | Provided & Maintained by Mall Mgmt | |
| | <ul style="list-style-type: none"> Fire check door Pressurization | N/A N/A | As above As above N/A N/A |
| | d. No. of continuous staircase to terrace | N/A N/A N/A | |
| | e. Width of corridor | N/A N/A N/A | |
| | f. Door size | N/A one exit + open space N/A | |
| 3 | Compartmentation. | Provided & Maintained by Mall Mgmt | |
| | <ul style="list-style-type: none"> Fire check door. Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. | N/A N/A N/A N/A N/A | N/A N/A N/A N/A N/A |
| 4. | Smoke Management system. | Provided & Maintained by Mall Mgmt | |
| | <ul style="list-style-type: none"> Basement Upper floors | 30 ACPH 12 ACPH | N/A Exhaust fan provided N/A MR |
| 5. | Fire Extinguishers. | | |
| | <ul style="list-style-type: none"> Total numbers Types ISI Marking | 2 No's for ABC / Co2 ISI marked | 2 No's for ABC-01, Co2-01 Provided MR MR MR |
| 6. | First Aid Hose Reels. | Provided & Maintained by Mall Mgmt | |
| | <ul style="list-style-type: none"> Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter | One 30 m 5 mm | As above As above As above MR MR MR |

M/S Domino's Pizza at FC-2, DLF Place Plot No-3, Nelson Mandela Marg, Vasant Kunj, New Delhi.

| | | | | |
|-----|--|------------------------------------|-------------|-----|
| 7 | Automatic fire detection & alarming system. | Provided & Maintained by Mall Mgmt | | |
| | • Type of detectors | N/A | As above | N/A |
| | • Location of Main Panel | N/A | As above | N/A |
| | • Location of Repeater Panel | N/A | N/A | N/A |
| | • Alternate source of power | N/A | As above | N/A |
| | • Hooter's location | N/A | As above | N/A |
| 8. | MOEFA | Required | Provided | MR |
| 9. | Public Address System | N/A | N/A | N/A |
| 10. | Automatic Sprinkler System | Provided & Maintained by Mall Mgmt | | |
| | • Basement | N/A | As above | N/A |
| | • Upper floors | Required | As above | MR |
| | • Sprinkler above false ceiling | N/A | N/A | N/A |
| 11. | Internal Hydrants. | Provided & Maintained by Mall Mgmt | | |
| | • Size of Riser/Down-comer | Required | As above | MR |
| | • Number of Hydrant per floor | Required | As above | MR |
| | • Hose box. | Required | As above | MR |
| 12. | Yard Hydrants. | Provided & Maintained by Mall Mgmt | | |
| | • Total number of hydrants. | N/A | As above | N/A |
| | • Hose box. | N/A | As above | N/A |
| 13. | Pumping arrangements. | Provided & Maintained by Mall Mgmt | | |
| | • Ground Level | Provided & Maintained by Mall Mgmt | | |
| | ➤ Discharge of main pump. | N/A | As above | N/A |
| | ➤ Head of main pump. | N/A | As above | N/A |
| | ➤ Number of main pumps. | N/A | As above | N/A |
| | ➤ Jockey Pump output. | N/A | As above | N/A |
| | ➤ Jockey Pump head. | N/A | As above | N/A |
| | ➤ Standby Pump output. | N/A | As above | N/A |
| | ➤ Standby Pump head. | N/A | As above | N/A |
| | ➤ Auto Starting / Manual Stopping. | N/A | As above | N/A |
| | • Terrace Level | Provided & Maintained by Mall Mgmt | | |
| | ➤ Discharge of pump. | 450 & 180 LPM | As above | MR |
| | ➤ Head of pump. | 40 mtr | As above | MR |
| | ➤ Power supply. | Required | As above | MR |
| | ➤ Auto starting of pump. | Required | As above | MR |
| 14. | Captive water storage for Fire Fighting. | Provided & Maintained by Mall Mgmt | | |
| | • Underground tank capacity. | N/A | As above | N/A |
| | ➤ Draw-off connection. | N/A | As above | N/A |
| | ➤ Fire Service Inlet. | Required | Provided | MR |
| | ➤ Access to tank. | N/A | As above | N/A |
| | • Overhead tank capacity. | 5,000 ltrs | 30,000 ltrs | MR |
| 15. | Exit Signage. | Required | Provided | MR |
| 16. | Provision of Lifts. | Provided & Maintained by Mall Mgmt | | |
| | • Pressurization of lift shaft. | N/A | As above | N/A |
| | • Pressurization of lift lobby. | N/A | As above | N/A |
| | • Communication in lift car. | N/A | As above | N/A |
| | • Fireman's switch. | N/A | As above | N/A |
| | • Lift signage. | N/A | As above | N/A |
| 17 | Standby Power Supply | Required | As above | MR |
| 18. | Refuge Area | Provided & Maintained by Mall Mgmt | | |
| | • Total area | N/A | N/A | N/A |
| | • Location | N/A | N/A | N/A |

M/S Domino's Pizza at FC-2, DLF Place Plot No-3, Nelson Mandela Marg, Vasant Kunj, New Delhi.

| 19. | Fire Control Room. | Provided & Maintained by Mall Mgmt | | |
|--|--|------------------------------------|----------|-----|
| | • Detector System Panel. | N/A | As above | N/A |
| | • Flow Switch Panel. | N/A | As above | N/A |
| | • PA system Panel. | N/A | As above | N/A |
| | • Battery backup | N/A | As above | N/A |
| | • Building floor plan | N/A | As above | N/A |
| 20. | Special Fire Protection System for the Protection of special Risk, if any : | N/A | As above | N/A |
| <p>The Fire protection systems provided in the building were checked / operated at random and found functional at the time of inspection.</p> <p>Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.</p> <p>Accordingly, DFA is put up for approval and signature please.</p> <div style="text-align: right;">  Signature of the Inspecting Officer Name : R.N. Singh Designation: ADO (BCP) </div> | | | | |

M/S Domino's Pizza at FC-2, DLF Place Plot No-3, Nelson Mandela Marg, Vasant Kunj, New Delhi.

~~DO (SD)~~

Anilak
8/11/18

dy. adst

[Signature]
8/11/18

Cfo S1

0.11 water storage capacity of 5000lt should be in addition to 30100lt already provided for mall. convey shortcomings.

Cfo S2

[Signature]
9/11/18



[Signature]
10/11/18

Cfo (S2)

M. Skill *[Signature]*
11/11/18

1534/Cfo S2
12/11/16/11

FT letter is put up for sign-off *[Signature]*